

1.  $\vec{H}$ ,  $\vec{I}$ ,  $\vec{B}_{\text{net}}$ ,  $\chi$

(a)  $\vec{H}$ , Magnetizing Field

For external magnetic field  $\vec{B}_{\text{ext}}$ ,  $\vec{H}$  is defined.

$$\vec{B}_{\text{ext}} = \mu_0 \vec{H}, \text{ unit of } \vec{H} \text{ is } \text{A/m.}$$

(b)  $\vec{I}$ , Intensity of Magnetization  $(\text{A/m})$

Total magnetic moment of material per unit volume.

$$\vec{I} = \frac{\vec{M}}{V}$$

(It tells how much a material is magnetized)

(c)  $\chi$ , Magnetic Susceptibility  
Tells about the ease with which a material can be magnetized.

$$\chi = I/H$$

$$\vec{B}_{\text{ext}} = \mu_0 \vec{H}$$

$$\vec{B}_i = \mu_0 \vec{I}$$

$$\vec{B}_{\text{net}} = \vec{B}_{\text{ext}} + \vec{B}_i$$

$$\Rightarrow \mu_0 \mu_r \vec{H} = \mu_0 \vec{H} + \mu_0 \vec{I}$$

$$\Rightarrow \mu_r \vec{H} = \vec{H} + \chi \vec{H}$$

$$\mu_r = 1 + \chi$$




## 2. DIAMAGNETIC AND PARAMAGNETIC MATERIAL

DIA ↓



Each atoms dipole moment is zero

≡ N




S


$$\vec{B}_i = \mu_0 \vec{I}$$

- (i) Weakly magnetized
- (ii) Material repels  $\vec{B}_{ext}$
- (iii)  $\mu_r = 1 + \chi$   
 $\mu_r < 1$  and  $\chi$  is -ve
- (iv) Graphite, Bismuth

PARA ↓



≡ S



N


$$\vec{B}_i = \mu_0 \vec{I}$$

- (i) Weakly magnetized
- (ii) Material gets weakly attracted to  $\vec{B}_{ext}$
- (iii)  $\mu_r = 1 + \chi$   
 $\mu_r > 1$  and  $\chi$  is +ve
- (iv) Al, Li, Mg




### 3. FERROMAGNETIC MATERIAL

(Fe, Ni, Co)



=



$$\vec{B}_{\text{ext}} = \mu_0 \vec{H}$$

$$\vec{B}_{\text{net}} = \vec{B}_{\text{ext}} + \vec{B}_i$$

$$\text{Here, } B_i \gg B_{\text{ext}}$$

$$\Rightarrow I \gg H$$

$$\therefore \chi \gg 1$$

### 4. CURIE'S LAW

If  $T \uparrow$ , due to thermal agitation, the alignment of dipoles gets disturbed and overall  $I \downarrow$  for a given  $H$ .

$$\therefore I \downarrow \Rightarrow \chi \downarrow$$

(a) FOR PARAMAGNETIC MATERIAL

$$\chi = \frac{C}{T}$$

$C$ : Curie Const.  
 $T$ : Abs Temp°

(b) For Ferromagnetic material

On heating it to  $T_c$ , it changes to Paramagnetic. On further  $\uparrow T$

$$\chi = \frac{C'}{T - T_c}$$

$T_c$ : Curie Temp°



## 5. MAGNETIC HYSTERESIS

(i)  $0 \rightarrow A$ : On  $\uparrow H$ ,  $I \uparrow$  and gets saturated for  $H = H_0$ .


(ii)  $A \rightarrow B$ : On  $\downarrow H$  to zero, still  $I$  is retained.  
 $OB$  is called "RETENTIVITY".

(iii)  $B \rightarrow C$ :  $\uparrow H$  in reverse direction,  $I = 0$  at  $C$ .  
 $OC$  is called "COERCIVITY".

(iv)  $C \rightarrow D$ : Further  $\uparrow H$  and  $I$  again gets saturated at  $D$ .

and so on...

NOTE: (a) Area of loop  $A B C D E F A$  shows thermal energy or heat produced / volume in 1 cyc.



## 6. HYSTERESIS CURVE: SOFT IRON VS STEEL

(i)  $\because$  Soft Iron gets easily magnetized and loses almost all magnetism easily (LOW COERCIVITY)  
It is used for "Electromagnets".

(ii)  $\because$  Steel is difficult to demagnetize

(OD = COERCIVITY)

it is used to make "Permanent Magnets".

