
NO CREEP AT ALL [GW6A-EL, GW6AX-EL]

id050320100800

TROUBLESHOOTING ITEM	No creep at all
DESCRIPTION	• Vehicle does not move in D, M or R position when idling on flat paved road.
POSSIBLE CAUSE	1. Not within idle speed specification

Diagnostic procedure

STEP	INSPECTION	ACTION	
1	INSPECT ENGINE CONTROL SYSTEM FOR MALFUNCTION <ul style="list-style-type: none">• Perform the symptom troubleshooting “NO.14 FAST IDLE/RUNS ON”. (See NO.14 FAST IDLE/RUNS ON [SKYACTIV-D 2.2].)• Is there any malfunction?	Yes	Repair or replace any malfunctioning parts according to the inspection result.
		No	Go to the next step.
2	VERIFY IF MALFUNCTION CAUSE IS TORQUE CONVERTER <ul style="list-style-type: none">• Is the malfunction symptom at same level compared to a vehicle of the same model?	Yes	Symptom troubleshooting is completed.
		No	Replace the automatic transaxle. (See AUTOMATIC TRANSAXLE REMOVAL/INSTALLATION [GW6A-EL].) (See AUTOMATIC TRANSAXLE REMOVAL/INSTALLATION [GW6AX-EL].)