

DTC U0001:88/U0100:00/U0121:00/U0155:00

id060200814600

DTC	U0001:88	CAN system Communication error
	U0100:00	Communication error to PCM
	U0121:00	Communication error to DSC HU/CM
	U0155:00	Communication error to instrument cluster
DETECTION CONDITION	<ul style="list-style-type: none"> • U0001:88 <ul style="list-style-type: none"> — Error detected in line between CAN connection module and CAN bus communication line • U0100:00 <ul style="list-style-type: none"> — Communication error to PCM is detected in CAN communication • U0121:00 <ul style="list-style-type: none"> — Communication error to DSC CM is detected in CAN communication • U0155:00 <ul style="list-style-type: none"> — Communication error to instrument cluster is detected in CAN communication 	
FAIL-SAFE FUNCTION	<ul style="list-style-type: none"> • U0001:88 <ul style="list-style-type: none"> — Control enabled — Power steering malfunction indicator light: Illuminated • U0100:00 <ul style="list-style-type: none"> — Control is maintained by gradually changing the controlled vehicle speed and setting it to 120 km/h {74.6 mph} — Power steering malfunction indicator light: Illuminated • U0121:00, U0155:00 <ul style="list-style-type: none"> — Control enabled — Power steering malfunction indicator light: Not illuminated 	
POSSIBLE CAUSE	<ul style="list-style-type: none"> • CAN system wiring harness open or short circuit with PCM • CAN system wiring harness open or short circuit with DSC HU/CM • CAN system wiring harness open or short circuit with instrument cluster • Poor connection at connectors 	
SYSTEM WIRING DIAGRAM	—	

Diagnostic procedure

- Perform inspection according to the diagnostic procedure in MULTIPLEX COMMUNICATION SYSTEM. (See FOREWORD [SKYACTIV-G 2.0, SKYACTIV-G 2.5 (L.H.D.)].) (See FOREWORD [SKYACTIV-G 2.0, SKYACTIV-G 2.5 (R.H.D.)].) (See FOREWORD [SKYACTIV-D 2.2 (L.H.D.)].) (See FOREWORD [SKYACTIV-D 2.2 (R.H.D.)].)