
NO CREEP AT ALL [FW6A-EL, FW6AX-EL]

id050317100800

TROUBLESHOOTING ITEM	No creep at all
DESCRIPTION	• Vehicle does not move in D, M or R position when idling on flat paved road.
POSSIBLE CAUSE	1. Not within idle speed specification

Diagnostic procedure

STEP	INSPECTION		ACTION
1	INSPECT ENGINE CONTROL SYSTEM FOR MALFUNCTION <ul style="list-style-type: none">• Perform the symptom troubleshooting “NO.9 FAST IDLE/RUNS ON”. (See NO.9 FAST IDLE/RUNS ON [SKYACTIV-G 2.0, SKYACTIV-G 2.5].) <ul style="list-style-type: none">• Is there any malfunction?	Yes	Repair or replace any malfunctioning parts according to the inspection result.
		No	Go to the next step.
2	VERIFY IF MALFUNCTION CAUSE IS TORQUE CONVERTER <ul style="list-style-type: none">• Is the malfunction symptom at same level compared to a vehicle of the same model?	Yes	Symptom troubleshooting is completed.
		No	Replace the automatic transaxle. (See AUTOMATIC TRANSAXLE REMOVAL/ INSTALLATION [FW6A-EL].) (See AUTOMATIC TRANSAXLE REMOVAL/ INSTALLATION [FW6AX-EL].)