
DTC U0010:88/U0155:00 [REAR BODY CONTROL MODULE (RBCM)]

id0902p4015200

System malfunction location	U0010:88 <ul style="list-style-type: none">• Unit communication error (MS-CAN) U0155:00 <ul style="list-style-type: none">• Communication error with instrument cluster
Detection condition	<ul style="list-style-type: none">• U0010:88<ul style="list-style-type: none">— With the ignition switched ON (engine off or on), the rear body control module (RBCM) detects a CAN communication line (MS-CAN) error.• U0155:00<ul style="list-style-type: none">— The rear body control module (RBCM) cannot receive CAN signals from the instrument cluster for 5 s or more with the ignition switched ON (engine off or on).
Fail-safe	—
Possible cause	<ul style="list-style-type: none">• Malfunction in CAN bus communication line• Malfunction in CAN line between the instrument cluster and rear body control module (RBCM)
System wiring diagram	—

Diagnostic Procedure

- Perform the malfunction diagnosis according to the troubleshooting procedure for the multiplex communication system. (See FOREWORD [SKYACTIV-G 2.0, SKYACTIV-G 2.5 (L.H.D.)].) (See FOREWORD [SKYACTIV-G 2.0, SKYACTIV-G 2.5 (R.H.D.)].) (See FOREWORD [SKYACTIV-D 2.2 (L.H.D.)].) (See FOREWORD [SKYACTIV-D 2.2 (R.H.D.)].)