

DTC U0401:68 [LASER SENSOR]

id0402c4895000

DTC	U0401:68	Abnormal message from PCM
DETECTION CONDITION	• Correct data cannot be received from PCM	
FAIL-SAFE FUNCTION	• Inhibits the smart city brake support (SCBS) controls. • Illuminates the master warning light • The message "SCBS Inspection Required" is indicated in the display.	
POSSIBLE CAUSE	• PCM malfunction	
SYSTEM WIRING DIAGRAM	—	

Diagnostic procedure

STEP	INSPECTION		ACTION
1	INSPECT FOR PCM MALFUNCTION <ul style="list-style-type: none">• Switch the ignition to off.• Using the M-MDS, perform the DTC inspection for the PCM. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-G 2.0, SKYACTIV-G 2.5].) (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 2.2].)• Are any DTCs detected?	Yes	Go to applicable DTC inspection. (See DTC TABLE [SKYACTIV-G 2.0, SKYACTIV-G 2.5].) (See DTC TABLE [SKYACTIV-D 2.2].)
		No	Go to the next step.
2	VERIFY THAT THE SAME DTC IS NOT PRESENT <ul style="list-style-type: none">• Clear the DTCs from the memory. (See ON-BOARD DIAGNOSIS [LASER SENSOR].)• Are the same DTCs present?	Yes	Repeat the inspection from Step 1. If the malfunction recurs, replace the PCM, then go to the next step. (See PCM REMOVAL/INSTALLATION [SKYACTIV-G 2.0, SKYACTIV-G 2.5].) (See PCM REMOVAL/INSTALLATION [SKYACTIV-D 2.2].)
		No	Go to the next step.
3	VERIFY THAT NO OTHER DTCs ARE PRESENT <ul style="list-style-type: none">• Are any other DTCs output?	Yes	Go to the applicable DTC inspection. (See ON-BOARD DIAGNOSIS [LASER SENSOR].)
		No	DTC troubleshooting completed.