

2.985

Shield – Manufacturing ProcedureFeed rate | Rough $\rightarrow 0.008'' - 0.011''$ Finishing $\rightarrow 0.003'' - 0.005''$

WATCH THE VIDEO!

<https://youtu.be/3iNqUsG0a0M>

- 1) Cut a piece of $\varnothing 1.5''$ ID X $\varnothing 1.75''$ OD Delrin acetal plastic hollow round bar to a length of 3" on the bandsaw.

Tools used: Combination square

Turning Cut \leftarrow Z-axisFacing Cut \uparrow X-axis**Lathe Operations:**

Mount stock in a 3-jaw chuck on the lathe with 1" stick-out.

- 2) Face one side to clean. (7:34)

Tools used: 6" rule, HSS turning tool, digital readout

Flip part around and remount with 1" stick-out.

- 3) Face opposite side to clean. (8:01)

Tools used: 6" rule, HSS turning tool, digital readout

Remove part, measure length with dial caliper, remount with 1" stick-out.

- 4) Face to 2.88" overall length. (8:25) Face from 3" \rightarrow 2.88"

Tools used: 6" rule, HSS turning tool, digital readout, dial caliper

- 5) Bore inside diameter to $\varnothing .003 - .010''$ clearance fit to OD of tube component. (9:16)

Tools used: 5/8" boring bar with CCGX-3(2.5)1 (or -2) carbide insert, digital readout, dial caliper

- 6) Break inside edge .015" max. (11:57)

Tools used: HSS chamfering tool, digital readout

- 7) Cut .1" X 45° external chamfer. Cut approx. .010" deeper to account for clean-up cut on OD in final step. (12:03)

Tools used: HSS chamfering tool, digital readout

Milling Machine Operations:

Install @ 60° 1.480

Install indexing head on table and ensure it is properly aligned to the table travel. Mount part in chuck with OD in jaws and with 1" stick-out.

- 8) Using edfinder, touch both sides of part OD to find center and then touch end of part to find edge. (13:46)

Tools used: Edfinder, drill chuck, digital readout

- 9) Position spindle .375" from end of part. (15:49)

Tools used: Digital readout

- 10) Spot $\varnothing .150''$ hole. (15:58)

Tools used: #3 HSS center drill, drill chuck, digital readout

- 11) Drill $\varnothing .150''$ hole. (16:04)

Tools used: #25 HSS drill, drill chuck, digital readout

Index part 120 degrees and repeat steps 10 & 11.

Then index part another 120 degrees and repeat steps 10 & 11 one more time.

#2-4





#5

#6

#7

#10

#11

X \rightarrow 2133 RPM (\approx 1500 ish)[\rightarrow 457 RPM O \rightarrow 229 RPM

- 12) Countersink all three $\varnothing.150$ " holes – indexing 120 degrees each time. Cut approx. .010" deeper to account for clean-up cut on OD in final step. Set quill stop or Z axis digital readout for consistent depth. (16:45)

Tools used: 1/2" X 100° HSS countersink, drill chuck, digital readout

Lathe Operations:

No threaded holes → no tapping

Mount shield on tube component. Mount tube in 3-jaw chuck on the lathe with minimal stick-out. Use copper shims between tube and chuck jaws to protect machined surfaces.

- 13) Turn $\varnothing 1.75$ " stock OD MINIMUM to 100% clean surface. (19:37)

Tools used: HSS turning tool, digital readout

- 14) Break inside and outside edges .015" max. (22:06)


Tools used: HSS chamfering tool, digital readout

480 RPM

#12



#13



#14



D. 300"