

# LCS6W?

## Tube – Manufacturing Procedure

Boring cut is an inside turning cut

WATCH THE VIDEO!  
(Lathe Operations)



<https://youtu.be/T-IBWwnVPLM>

- 1) Cut a piece of  $\varnothing 1.0$ " ID X  $\varnothing 1.5$ " OD 6061-T6 aluminum alloy hollow round bar to a length of 6" on the bandsaw. (7:11)

Tools used: Combination square

Feed rate  $\rightarrow$  IPR

Lathe Operations:  
Turning Cut  $\leftarrow$  Z-axis  
Facing Cut  $\uparrow$  X-axis

Roughing  $0.008$ " -  $0.01$ "  
Finishing  $0.003$ " -  $0.005$ "

Mount stock in a 3-jaw chuck on the lathe with 4.5" stick-out.

- 2) Face one side to clean. (9:13) Steps 2-6  $\rightarrow$  533 RPM  
Tools used: 6" rule, HSS turning tool, WD-40 lubricant, digital readout
- 3) Turn  $\varnothing 1.5$ " stock OD MINIMUM to 100% clean surface. Cut at least 4" length. (9:49)

Tools used: HSS turning tool, digital readout

Flip part around and remount with 3" stick-out. From this point on, use copper shims between part and chuck jaws to protect machined surfaces.

- 4) Face opposite side to clean. (11:52)  
Tools used: 6" rule, HSS turning tool, WD-40 lubricant, digital readout

Remove part, measure length with dial caliper, remount with 3" stick-out.

- 5) Face to 5.8" overall length. (12:32)  
Tools used: 6" rule, HSS turning tool, WD-40 lubricant, digital readout, dial caliper

- 6) Turn  $\varnothing 1.38$ " to  $2.0$ " from end. (14:18)  
Tools used: HSS turning tool, WD-40 lubricant, digital readout, 1-2" micrometer

- 7) Use .002" shim to touch off chamfering tool on  $\varnothing 1.38$ " surface. Blend 45° chamfer at transition between  $\varnothing 1.38$ " and  $\varnothing 1.5$ " surfaces. (19:20)

Tools used: .002" shim, HSS chamfering tool, WD-40 lubricant

- 8) Drill  $\varnothing 1.06$ " through center of part at least 4.5" deep. (20:07)

Tools used: 1-1/16" HSS twist drill, morse taper adapter (if required), WD-40 lubricant

- 9) Bore  $\varnothing 1.125$ " X  $1.00$ " deep. (21:04)

Tools used: 5/8" boring bar with CCGX-3(2.5)1 (or -2) carbide insert, WD-40 lubricant, digital readout, 1-2" micrometer, telescoping gage (size B)

- 10) Break inside edge .015" max. (24:33)

Tools used: HSS chamfering tool, WD-40 lubricant, digital readout

- 11) Cut .03" X 45° external chamfer. (25:12)

Tools used: HSS chamfering tool, WD-40 lubricant, digital readout

Flip part around again and remount with 2" stick-out.

- 12) Bore  $\varnothing 1.13$ " X  $1.5$ " deep. (25:38)

Tools used: 5/8" boring bar with CCGX-3(2.5)1 (or -2) carbide insert, WD-40 lubricant, digital readout, 1-2" micrometer, telescoping gage (size B)

- 13) Bore  $\varnothing 1.265$ " X .588" deep. (27:35)

Tools used: 5/8" boring bar with CCGX-3(2.5)1 (or -2) carbide insert, WD-40 lubricant, digital readout, 1-2" micrometer, telescoping gage (size B)

#2

#3

#4/5

#6

#7


#8

#9

#10/11

#12

#13



[ ]  $\rightarrow$  267 RPM

J  $\rightarrow$  2832 RPM

14) Cut .05" X 45° internal chamfer. (28:40)

Tools used: HSS chamfering tool, WD-40 lubricant, digital readout

#14/15

15) Cut .03" X 45° external chamfer. (28:59)

Tools used: HSS chamfering tool, WD-40 lubricant, digital readout

16) Tap 1-5/16-16 UNS 2B threads .3" deep. (29:10)

Tools used: 1-5/16-16 UNS HSS plug tap, tap handle, spring-loaded tap guide, drill chuck, WD-40 lubricant

#16

Milling Machine Operations:

Install indexing head on table and ensure it is properly aligned to the table travel. Mount part in chuck with smaller OD in jaws and with 4" stick-out. (Use copper shims!) Lightly support end of part with screw jack on table.

17) Using edfinder, touch both sides of part OD to find center and then touch end of part to find edge. Position spindle 3.22" from end of part. Do NOT forget to add radius of edfinder when locating an edge.

Tools used: Edfinder, drill chuck, digital readout

18) Spot hole for ¼-20 UNC 2B threads. → 600-1000 RPM

Tools used: #3 HSS center drill, drill chuck, WD-40 lubricant, digital readout

19) Drill hole for ¼-20 UNC 2B threads. → 2388 RPM

Tools used: #7 HSS drill, drill chuck, WD-40 lubricant, digital readout

20) Countersink hole for ¼-20 UNC 2B threads. → 480 RPM ?

Tools used: 1/2" X 90° HSS countersink, drill chuck, WD-40 lubricant, digital readout

21) Position spindle .775" from end of part.

Tools used: Digital readout

22) Spot drill first hole for #6-32 UNC 2B thread. → 600-1000 RPM

Tools used: #3 HSS center drill, drill chuck, WD-40 lubricant, digital readout

23) Pre-drill first hole for #6-32 UNC 2B thread. → 4486 RPM (3000 Tap RPM)

Tools used: #36 HSS drill, drill chuck, WD-40 lubricant, digital readout

Loosen screw jack, index part 120 degrees, reapply screw jack and repeat steps 22 & 23. Then index part another 120 degrees and repeat steps 22 & 23 again.

24) Countersink first hole for #6-32 UNC 2B thread. → 480 RPM

Tools used: 1/2" X 90° HSS countersink, drill chuck, WD-40 lubricant, digital readout

Loosen screw jack, index part 120 degrees, reapply screw jack and repeat step 24. Then index part another 120 degrees and repeat step 24 again.

25) Tap first hole for #6-32 UNC 2B thread

Tools used: #6-32 HSS plug tap, tap wrench, spring-loaded tap guide, drill chuck, WD-40 lubricant, digital readout

Loosen screw jack, index part 120 degrees, reapply screw jack and repeat step 25. Then index part another 120 degrees and repeat step 25 again.

26) Tap hole for ¼-20 UNC 2B thread

Tools used: ¼-20 HSS plug tap, tap wrench, spring-loaded tap guide, drill chuck, WD-40 lubricant, digital readout

For spotting, same speed and tool  
for drilling, single → #7 HSS drill, triple → #36 HSS  
φ0.201" φ0.107"

