

Operator's Reference Manual

Model 3241-C

Asphalt Content

Gauge



Troxler Electronic Laboratories, Inc.

3008 Cornwallis Rd. • P.O. Box 12057

Research Triangle Park, NC 27709

Phone: 1.877.TROXLER

Outside the USA: +1.919.549.8661

Fax: +1.919.549.0761

www.troxlerlabs.com

Troxler Gauges are protected by U.S. and foreign patents.

Copyright © 1989-2007

Troxler Electronic Laboratories, Inc.

All Rights Reserved

Any unauthorized reproduction is prohibited.

No part of this manual may be reproduced or transmitted in any form or by any means, electronic or mechanical, including photocopying, recording, or information storage and retrieval systems, for any purpose without the express written permission of Troxler Electronic Laboratories, Inc.

IBM is a registered trademark of International Business Machines, Inc.

Microsoft, *Windows*, and *HyperTerminal* are registered trademarks of Microsoft Corporation.

WEIGH-TRONIX is a registered trademark of Weigh-Tronix, Inc.

PN 104575

November 2007

Edition 12.0

TROXLER SERVICE CENTERS

Troxler Corporate Headquarters

3008 Cornwallis Road

P.O. Box 12057

Research Triangle Park, NC 27709

Phone: 1.877.TROXLER (1.877.876.9537)

Outside the U.S.A.: +1.919.549.8661

Fax: +1.919.549.0761

Web: www.troxlerlabs.com

Technical Support

Phone: 1.877.TROXLER (1.877.876.9537)

E-mail: TroxTechSupport@troxlerlabs.com

Midwestern Branch Office

1430 Brook Drive

Downers Grove, IL 60515

Fax: 630.261.9341

Florida Service Center

2376 Forsyth Road

Orlando, FL 32807

Fax: 407.681.3188

Western Regional Branch Office

11300 Sanders Drive, Suite 7

Rancho Cordova, CA 95742

Fax: 916.631.0541

Troxler European Subsidiary

Troxler Electronics GmbH

Gilchinger Strasse 33

D.82239 Alling nr. Munich, Germany

Phone: ++49.8141.71063

Fax: ++49.8141.80731

E-mail: troxler@t-online.de

Southwestern Branch Office

2016 East Randol Mill Road

Suite 406

Arlington, TX 76011

Fax: 817.275.8562

NOTES

How to Use The Operator's Reference Manual

Congratulations on the purchase of the **Troxler Model 3241-C Asphalt Content Gauge**.

The **Model 3241-C Operator's Reference Manual** contains information on setting up and operating the gauge. Basic parameter set up, sample preparation, reading storage and advanced operation are included. Basic maintenance and troubleshooting are also included to keep the gauge in the best condition possible.

This manual is organized into five chapters that describe all the operations of the gauge and eight appendices that include information on the theory of operation, radiation safety, transportation, troubleshooting and gauge specifications.

The **Model 3241-C Maintenance and Service** manual is available (PN 105125) for those users who will perform service and calibration functions.

GUIDE TO SYMBOLS

The symbols used throughout this manual and their purpose are as follows:

- ◆ Diamonds indicate a list of things needed (such as equipment) or things to know.
- Triangles appear when more than one option is available. Each option is marked by a triangle. Carefully select the option that best applies.
- ✓ Check marks indicate the performance of an action. With lists of check marks, follow the instructions in the order of the check marks.
- ◁▷ Angle brackets indicate a key or character (number or letter) to press on the control unit keypad. For example, "Press <Enter>" means to press the key on the control unit keypad labeled "Enter."

NOTE Indicates important information that must be read to ensure proper operation.

CONTENTS

GENERAL INFORMATION	1-1
Introduction	1-2
Gauge Parts and Accessories	1-4
Unpacking and Inspection	1-6
Site Selection	1-7
THEORY OF OPERATION	2-1
Theory	2-2
OPERATING THE GAUGE	3-1
Turning the Gauge "ON"	3-2
Gauge Parameter Set Up	3-4
Taking the Background Count	3-8
Sample Preparation	3-9
Taking a Measurement	3-10
PERFORMING A CALIBRATION	4-1
Equipment Needed	4-2
Preparing the Calibration Samples	4-3
Performing the Calibration	4-9
STORING PROJECT DATA	5-1
The Project Function	5-2
Storing A Measurement	5-4
Printing Measurement Data	5-5
Erasing a Project	5-6
THE SHIFT FUNCTIONS	6-1
Status	6-2
Offset	6-2
Special	6-7
Project	6-7
Auto-Store/Auto-Print	6-7
Erase	6-8
Recall	6-9
Target Precision	6-9
Calculator	6-10
Calibration Sample Prep	6-11

SPECIAL FUNCTIONS	7-1
Stat Test	7-2
Drift Test	7-5
Recover Erase	7-7
Time/Date	7-7
Calibration Transfer	7-8
Baud Rate	7-16
Customer Name	7-17
Serial Number	7-17
Pan Weight Display	7-18
 RADIOLOGICAL INFORMATION	 A-1
Radiation Theory	A-2
Radiation Safety	A-6
 3241-C AND 3241-M SPECIFICATIONS	 B-1
Measurement Specifications	B-2
Radiological Specifications	B-3
Electrical Specifications	B-4
Mechanical Specifications	B-6
 TROUBLESHOOTING AND SERVICE	 C-1
Troubleshooting	C-2
3241-C with Rechargeable Batteries	C-6
Leak Testing	C-5
Replacement Parts	C-7
Returning a Gauge for Service	C-8
Troxler Service Centers	C-9
 TRANSPORTATION AND SHIPPING	 D-1
U.S. Shipping Requirements	D-2
Canadian Shipping Requirements	D-4
 SPECIAL CALIBRATION SAMPLES	 E-1
 CALIBRATION FORMS	 F-1
Mixing Forms	F-3
Calibration Forms	F-6

List of Illustrations

<u>Figure #</u>	<u>Description</u>	<u>Page</u>
Figure 1	Gauge Parts	1-4
Figure 2	3241 Connections	3-2
Figure 3	Filling the Blank Sample Pan	4-4
Figure 4	Example Slope Offset Graph	6-4
Figure 5	Example Relative Offset Graph	6-4
Figure 6	Example Slope/Intercept Offset Graph	6-5
Figure 7	Range of Standard Deviation Ratios	7-2
Figure 8	Sample Stat Test Print Out	7-4
Figure 9	Sample Drift Test Print Out	7-6
Figure 10	Serial Device Connection	7-16
Figure 11	Diagram of an Atom	A-2
Figure 12	Variation of Radioactive Emission	A-5
Figure 13	Effect of Distance on Exposure	A-7
Figure 14	3241-C (100 mCi) Radiation Profile	A-9
Figure 15	3241-C (300 mCi) Radiation Profile	A-10

<u>Figure #</u>	<u>Description</u>	<u>Page</u>
Figure 20	Sealed Asphalt Sample	E-4
Figure 21	Mixing Forms	F-4
Figure 22	Calibration Forms	F-7

NOTES

ATTENTION GAUGE OWNER

This gauge contains functions that require an ACCESS CODE. This code must be entered before these functions may be used. For more information on using the access code refer to Chapter 5.

The ACCESS CODE for this gauge is:

4489

This page should be removed if the access code is not to be distributed to other parties or users of this gauge.

NOTES

CHAPTER I

GENERAL INFORMATION

This chapter will acquaint the user with the **Model 3241-C Asphalt Content Gauge's** many features and capabilities.

Contents:

INTRODUCTION 1-2

GAUGE PARTS AND ACCESSORIES 1-4

UNPACKING AND INSPECTION 1-6

SITE SELECTION 1-7

INTRODUCTION

The Model 3241-C can quickly and precisely determine the asphaltic cement (or bitumen) content of an asphalt-aggregate mix without the use of volatile or hazardous chemicals. Using the proven principle of neutron thermalization, the 3241-C determines asphalt content. Hydrogen in the asphalt slows neutrons emitted from an americium-241:beryllium source. A series of helium-3 detectors located in the gauge base detects the slowed neutrons and the microprocessor converts the count into a precise measurement of asphalt content.

The gauge may be calibrated to accommodate many different mixes and the calibrations may be transferred to other gauges using Troxler's patented *Calibration Transfer Program*. The sample temperature is always monitored allowing the gauge to compensate for variations which have been known to cause problems in other gauges.

The nuclear method of asphalt content testing has been approved by the American Society of Testing and Materials and the Model 3241-C meets or exceeds all the requirements of "ASTM D-4125-05, Standard Test Method for the Asphalt Content of Bituminous Mixtures by the Nuclear Method."

Some information contained in this manual is used in training courses offered by Troxler Electronic Laboratories, Inc. and to assist purchasers in obtaining a Radioactive Materials License from the U.S. Nuclear Regulatory Commission or an Agreement State. Owners of this gauge must maintain a current radioactive materials license as long as they own the gauge, even if it is in storage and not actively being used.

Owners are encouraged to require study of this manual by operator(s) before allowing any use of the instrument. While no radiation hazard exists for operator(s) during normal use, a potential hazard does exist if improperly used. The sections of the manual covering radiological safety should be required reading for all operators and potential operators. If these sections are not completely understood, users should seek assistance from Troxler, an appointed Troxler representative or others designated within the

user organization. Additional nuclear safety information is available by attending a *Troxler Nuclear Gauge Training Course*.

As changes are made to local, state and federal regulations on a continuing basis, the owner/user must maintain a current status with these regulations. *The responsibility for compliance ultimately falls upon the owner*. The owner may also wish to purchase and subscribe to Titles 10 and 49 of the *Code of Federal Regulations* in addition to applicable local/state regulations.

GAUGE PARTS AND ACCESSORIES




Figure 1
Gauge Parts

1. **The Sample Chamber** contains the radioactive source, the detectors and the high voltage electronics used for measuring the asphalt content of the sample.
2. **The Control Unit** provides the operator interface to the system. The console contains the keypad, display and the microprocessor used to process the sample data.
3. **The Control Unit-Chamber Interface Cable** connects the console to the sample chamber.
4. **Power Adapter** (Not Shown) connects the gauge to a 115/230 VAC, 50/60 Hz power source.
5. **The Sample Pans** are used to hold an exact amount of asphalt for testing. Four pans are supplied with the gauge.
6. **Optional Serial Printer** (Not Shown) connects to the control unit for printing sample data.
7. **Optional Water Resistant Transport Case** (Not Shown) is a D.O.T. approved shipping container for the sample chamber and control unit.
8. **The Optional Serial Interface Cable** (Not Shown) connects the gauge to a printer or computer.

UNPACKING AND INSPECTION

Upon receipt of the gauge from the factory a complete inspection and inventory should be performed. If the shipping case or any other part of the container is damaged contact the shipper **immediately**.

Save the box and any packing material for possible shipment of the gauge to another location or back to the factory.

After removal from the transport case from the cardboard box, check to see if the following literature and accessories have been included:

- ◆ Operator's Reference Manual
- ◆ Gauge Warranty
- ◆ Source Certificate
- ◆ Data Sheet

- ◆ 3241-C Sample Chamber
- ◆ 3241-C Control Unit
- ◆ Power Adapter
- ◆ Power Adapter (for cigarette lighter)
- ◆ Control Unit/Chamber Interface Cable
- ◆ (4) Sample Pans

Lift the gauge from the case and inspect the outside surface for damage. Check the lock on the sample chamber. Make sure the keys fit the lock. Return the gauge to the transport case.

If the gauge appears to be damaged notify the carrier and your Troxler Representative **immediately**.

SITE SELECTION

When choosing a gauge location site, take into consideration the ambient temperature and location of power outlets, large objects and any other nuclear gauges.

- ◆ The room where the system is to be located should be well ventilated and should not experience abrupt temperature or humidity changes.
- ◆ The 3241-C must be placed on a level, sturdy surface.
- ◆ Install the 3241-C with the control unit within reach of the operator's workstation and the sample chamber, connected to the control unit, readily accessible for sampling. The background count will account for any external hydrogen sources (Chapter 3, *Taking the Background Count*). If the system is moved or objects containing hydrogen and/or larger objects are moved near the sample chamber after taking the background count, a new background count should be taken.
- ◆ Personnel should not stand in close proximity to the sample chamber due to possible measurement effects and radiation safety.
- ◆ The line voltage should not vary by more than $\pm 10\%$.
- ◆ The ambient temperature should be between 10 and 33 degrees Celsius (50 - 91 degrees Fahrenheit), and the relative humidity should be between 20 and 90 percent.
- ◆ The 3241-C must be installed at least ten meters (33 feet) from any other nuclear gauge!
- ◆ The 3241-C must not be exposed to open flames, dust, ammonia or any other corrosive fumes, or direct sunlight.

NOTES

CHAPTER II
THEORY OF OPERATION

This chapter provides information on the operating principles of the **Model 3241-C Asphalt Content Gauge**.

Contents:

THEORY 2-2

THEORY

The Model 3241-C Asphalt Content Gauge measures the amount of asphalt (bitumen) in a bituminous mixture by determining the hydrogen content of the material. The amount of asphalt and the amount of moisture can be related to hydrogen content since both contain hydrogen.

The Model 3241-C Asphalt Content Gauge with the 3.7 GBq (100 mCi) americium 241:beryllium source has a yield of 220,000 neutrons per second. In all 3241-C configurations, the fast neutrons emitted are *thermalized* (or slowed) by the hydrogen in the asphalt. The helium-3 detectors located in the gauge detect the slowed neutrons, since helium-3 detectors are insensitive to fast neutrons. The thermalized neutrons are counted over a period of time and this "count" is proportional to the asphalt content of the sample.

CHAPTER III
OPERATING THE GAUGE

This chapter explains the basic operation of the Model 3241-C Asphalt Content Gauge. Instructions for parameter set up, taking the daily background count, and asphalt content measurements are included.

Contents:

TURNING THE GAUGE "ON"	3-2
GAUGE PARAMETER SET UP	3-4
Setting the Count Time	3-4
Setting the Time/Date	3-5
Changing the Customer Name	3-6
TAKING THE BACKGROUND COUNT	3-8
SAMPLE PREPARATION	3-9
TAKING A MEASUREMENT	3-10

TURNING THE GAUGE "ON"

Figure 2 shows all 3241-C connections. Connect the sample chamber to the control unit with the main interface cable. Connect the power adapter to the control unit and a 120 VAC outlet.




Figure 2
3241 Connections

Turn the gauge on by pressing <ON>.

RAM TEST
Do not turn the
Gauge off during
this test.

After the RAM test the gauge will enter the 120 second *Self Test*. In this mode the version number and customer name are displayed. After the test the display will be:

- GAUGE READY -
hh:mm mm/dd
Time: x minutes
Calib# Factory

The second line displays the time and date. The third line displays the count time. The last line displays the current enabled calibration.

GAUGE PARAMETER SET UP

After unpacking and turning "On" the 3241-C, several parameters can be initialized. These parameters usually do not require changing and include the count time, time\date, and company name.

SETTING THE COUNT TIME

The longer the count time, the better the measurement precision.

Press <**TIME**> for the display:

- Count Time -
xx min.
Do you want
to change ?

To accept the displayed count time, press <**ENTER**>. To change the displayed count time, press <**YES**>.

Sel: 1- 1 min.
2- 4 min.
3- 8 min.
4- 16 min.

Make the selection by pressing <**1**>, <**2**>, <**3**> or <**4**>. The display will return to the *Ready* mode.

SETTING THE TIME / DATE

Press <**SHIFT**> and <**SPECIAL**>. The display will be:

SPECIAL FUNCTION
YES- (Next menu)
01- Stat test
2- Drift test

To select this feature, press <**4**>.

SPECIAL FUNCTION
Set Time/date
Enter code _____

The *Time/Date* function is a *restricted function* and requires an access code for operation. This is to ensure that the time and date are not changed by unauthorized personnel.

Input the access code and press <**ENTER**>. The display will be:

Date: mm/dd/yy
Do you want to
change date?

To accept the displayed date, press <**NO**>. To change the date, press <**YES**>.

Select the format to be used: *dd/mm/yy* or *mm/dd/yy*.

Input the new date and press <**ENTER**>.


To change the time, repeat the above procedure.

CHANGING THE CUSTOMER NAME

The gauge may be programmed to display your name or any other message (not to exceed 16 characters) during the power-up / self-test stage.


Press <**SHIFT**> and <**SPECIAL**>.

The display will be:




Scroll through the menu options by pressing <**YES**> twice.

Select *Customer Name* by pressing <**7**>.



To change the customer name, press <**YES**>.

The *Customer Name* function is a *restricted function* and requires an access code for operation. This is to ensure that the name/message is not changed by unauthorized personnel. Input the code and press <**ENTER**>.



To scroll up (increment) through the letters, press <**SHIFT**>. To scroll down (decrement) through the letters, press <**TIME**>.

To select the letter and move to the next position, press <**YES**>. Complete the operation by pressing <**ENTER**>.


TAKING THE BACKGROUND COUNT

Prior to performing any testing, measuring, or calibrating with the 3241-C, take a *background count*. The background count adjusts for changes in the gauge environment and location.

The 3241-C is influenced by external sources of hydrogen. Once a background count is made, do not change the surrounding sources of large hydrogen content (i.e., draining a water bath, moving large containers of liquids, etc.). Take a new background count if changes occur or are suspected. During and after a background count the test samples should not be within 1 meter (3 feet) of the sample chamber.

The neutron source used in the Model 3241-C is americium-241:beryllium and has a half-life of 432 years (or will undergo a natural decay of 0.2% per year). The *Background Count* also adjusts for source decay.

Press <**BKG**> for the display:



Background: xxxx
Time: xx minutes
Want to take a
new Background?

To take a new background count, press <**YES**>.

Prepare the sample chamber as instructed and press <**START**>.

After the count is complete and acceptable, press <**YES**>. To take another background count, press <**NO**>.

SAMPLE PREPARATION

NOTE

Prior to measuring asphalt content, the gauge must contain a calibration corresponding to the asphalt samples to be tested (Chapter 4). **The percent (%) asphalt of the test samples must be within the range of the gauge calibration (see example, page 4-5).**

To prepare measurement samples,

- ✓ Obtain the weight of an empty sample pan using an accurate balance scale or electronic scale. Record the pan weight.
- ✓ Partially fill (1/3 full) the pan with the asphalt mix. Lightly tamp the mix with a spoon or spatula. Do not pack the material with a press or hammer.
- ✓ Continue adding hot asphalt in layers, settling and tamping each layer until the pan is full and the asphalt is above the pan top. The asphalt sample should be level with the top of the pan, so place a piece of wax paper over the asphalt and press down on the sample with a wooden board or other flat object.
- ✓ Remove the wax paper and place the full sample pan on the scale and obtain the weight. Record the value.
- ✓ Repeat the above procedure for each sample. Make sure each sample has the same weight (± 4 g).
- ✓ Take a measurement as described the following section.
- ✓ Upon measurement completion, remove the asphalt from the sample pan by reheating the pan in an oven. Turn the pan upside down and lightly tap on the bottom. **Do Not Dent The Bottom Of The Pan.**

TAKING A MEASUREMENT

Place the unknown % asphalt sample into the test chamber and close the door.

NOTE

Ensure measurement consistency by marking the sample pans so they are inserted into the chamber the same way each time the pan is used.

If the *Pan Weight Display* function is enabled, the gauge will request the weight of the empty sample pan and the weight of the pan containing asphalt (see Chapter 7, page 7-18).

Enable the appropriate mix calibration by pressing <**CALIB**> (refer to page 4-14).

To begin the measurement sequence press <**START**>. The display will be:


Calib# 123.54
Input empty pan
weight: _____ g.
and Press ENTER

Input the recorded empty sample pan weight and press <**ENTER**>.

Fill Sample Pan
until weight =
xxx g.
(Press ENTER)

Make sure the unknown % AC sample is the same weight as the calibration samples (± 8 g) for the mix being tested.

Press <**START**> for the display:



The gauge will count down as the asphalt content measurement is obtained. After the count time has elapsed the results will be displayed. For storing results refer to Chapter 5.

NOTES

CHAPTER IV

PERFORMING A CALIBRATION

This chapter provides information on calibrating the **Model 3241-C Asphalt Content Gauge**. The user should refer to the following *standards* for additional information.

AASHTO Standards:

- T2 Sampling Aggregate
- T168 Sampling Bituminous Pavement Mixtures
- T110 Moisture or Volatile Distillates in Bituminous Paving Mixtures
- T287 Nuclear Method Asphalt Content Determination

ASTM Standards:

- D75 Sampling Aggregates
- D979 Sampling Bituminous Paving Mixtures
- D1461 Test for Moisture or Volatile Distillates in Bituminous Paving Mixtures
- D4125 Standard Test Method for Asphalt Content of Bituminous Mixtures by the Nuclear Method

Contents:

EQUIPMENT NEEDED	4-2
PREPARING THE CALIBRATION SAMPLES	4-3
Blank Sample Preparation	4-3
Calibration Sample Preparation	4-5
Sample Mixing	4-6
Filling Sample Pans	4-8
PERFORMING THE CALIBRATION	4-9
Reviewing a Calibration	4-13
Enabling a Stored Calibration	4-14
Manually Entering Calibration Data	4-15

EQUIPMENT NEEDED

In order to obtain precise asphalt content measurements, employ a consistent method of sample preparation. Using the same approved equipment for preparing each sample helps ensure the best possible results.

RECOMMENDED EQUIPMENT

The following equipment will be needed during calibration and test sample preparation:

- ◆ Balance/Electronic scale readable to 0.002 lb (1 g).
- ◆ Drying oven, capable of heating to 350°F (177°C).
- ◆ Two 30 x 12 x 2.5 in (76 x 30 x 6 cm) stainless steel utility pans.
- ◆ (2) 16" (41 cm) stainless steel mixing bowls.
- ◆ Steel straightedge, approximately 8 in (20 cm) long.
- ◆ Plywood or metal plate having an area slightly larger than the sample pans.
- ◆ Thermometer with temperature range of 50° to 500°F (10° to 260°C).
- ◆ Assorted spoons, spatulas, heat resistant gloves, etc.

SUGGESTED EQUIPMENT

The following equipment will aid mixing and sample preparation:

- ◆ Large commercial grade electric blender with a mixing bowl capable of holding a 22 lb (10 kg) sample.
- ◆ Heated asphalt reservoir with temperature control.

PREPARING THE CALIBRATION SAMPLES

Follow the procedures outlined below to prepare asphalt samples for gauge calibration. For gauge assistance in preparing the samples refer to page 6-11.


BLANK SAMPLE PREPARATION

Before preparing calibration samples, prepare a *blank sample* of aggregate. Use the blank sample to estimate the asphalt sample size or to adjust the calibration for changes in aggregate size or moisture content.

- ✓ Obtain a sample of the aggregate(s) being used in the asphalt mixture. For each calibration sample obtain a minimum of 20 lbs (9 kg) of aggregate. Sample enough aggregate for a minimum of three samples. Refer to AASHTO Standard Method T2.
- ✓ Obtain a sample of the liquid asphalt (bitumen) being used in the mixture. For each calibration sample, obtain at least 3 lbs (1.4 kg). Refer to AASHTO Method T168.
- ✓ Blend the aggregate(s) in the proper proportions (or obtain blended aggregate samples). The aggregate should be maintained at the proposed plant temperature or placed in an oven and baked for 3 hours at 250°F (121°C) to remove any moisture.
- ✓ Select an empty sample pan and obtain the weight (tare weight) using the balance or electronic scales.
- ✓ Fill the sample pan approximately ½ full with dry, hot aggregate (see Figure 3).
- ✓ Settle the aggregate by dropping the pan 1 inch onto a hard surface several times.
- ✓ Smooth the aggregate mixture into the corners of the pan.
- ✓ Fill the rest of the pan with aggregate, overfilling slightly.
- ✓ Scrape off the surface with the straightedge.

Do Not Compact The Sample With A Compaction Tool!

STEP 1: Fill pan ½ full.



STEP 2: Fill remaining portion of the pan and scrape off excess.




Figure 3
Filling the Blank Sample Pan

- ✓ Place the filled sample pan on the balance or electronic scale and record the weight.
- ✓ Subtract the weight of the empty pan to obtain the weight of the aggregate only.

Example:

<i>Weight of Sample Pan with aggregate</i>	<i>.7387 g</i>
<i>Less: Weight of empty sample pan</i>	<i>.571 g</i>
	<i>-----</i>
<i>Net Weight of Aggregate</i>	<i>.6816 g</i>

- ✓ Place the aggregate-only sample back in the oven and reheat to the proposed plant temperature.
- ✓ Measure this sample using a 16 minute count time. Record this count on the calibration form (Appendix F).

CALIBRATION SAMPLE PREPARATION

After preparing the blank sample, the calibration samples can be mixed. For the best measurement accuracy, each sample of asphalt mixture (calibration and production testing samples) should be the same weight (± 4 grams).

After determining the %AC for the known calibration sample (see example below), prepare the highest %AC sample first. Fill the pan as full as possible, determine the weight and prepare all samples at this weight (± 4 grams).

Calibration samples are prepared by mixing a known weight of hot, dry aggregate with a known weight of hot, liquid asphalt. The number of calibration samples is optional and may vary from two to twelve, with twelve providing the best accuracy. Calibration samples should be prepared with an asphalt content above and below the design content.

EX: If the Design Mix is 5.5% asphalt content and five calibration samples are to be used, then the asphalt content of the calibration samples should be 4%, 4.8%, 5.5%, 6.2%, and 7%.

Two methods for expressing the asphalt content percentage:

Method 1: % Asphalt by Aggregate Dry Weight

$$E = D + \left(\frac{A * C}{100} \right)$$

Method 2: % Asphalt by Total Mix Weight

$$E = D + \left(\frac{A * C}{100 - A} \right)$$

where: A = % Asphalt Content
 C = Dry Aggregate Weight
 D = Weight of Mixing Bowl + Dry Aggregate
 E = Total Design Weight

SAMPLE MIXING

Mixing Tips

- ◆ Prepare more asphalt than needed!
- ◆ It is recommended that the aggregate weight of the sample be equal or exceed that of the blank sample to ensure the preparation of slightly more asphalt than needed.
- ◆ When preparing a calibration mix, the aggregate and asphalt must be representative of the material normally produced by the asphalt plant. If the mix is not representative, the gauge readings will not accurately reflect the actual asphalt content.
- ◆ All mixing tools should be kept hot to prevent moisture from contaminating the mixture and to make mixing easier. Placing the mixing bowl on a hot plate will aid in mixing.
- ◆ Form a "crater" in the hot aggregate. Slowly pour the hot asphalt into the crater and mix until the aggregate is thoroughly distributed. Mixing time is approximately 15 minutes. If using an electric mixer, mixing time at medium speed is about 90 seconds.

Mixing Procedure

Use the *calibration forms* in Appendix F to record the values.

- ✓ Heat a mixing bowl and asphalt.
- ✓ To ensure any residual asphalt in the bowl represents the design mix, scrape out the bowl.
- ✓ Smear a small amount of hot, liquid asphalt and aggregate fines in the bowl.
- ✓ Weigh the mixing bowl and record the weight on line B of the form. If available, use the *tare* function on the scale to "zero" the bowl weight.

- ✓ Put hot, dry aggregate (see *Mixing Tips*) into the preheated mixing bowl. Use the same type of aggregate as in the blank sample. Record the weight on line C.
- ✓ Add lines B and C. Enter the subtotal on line D.
- ✓ Use the Method 1 or Method 2 formula on the previous page to calculate the *total design weight*. **Use the method that duplicates the asphalt plant method.** Enter the weight on line E.
- ✓ Slowly add hot asphalt to the aggregate until the *total design weight* is reached. If the actual weight is slightly over or under the design weight, record the value on line F.
- ✓ Calculate the actual % AC (see example below) and enter the value on line G.

For Method 1 use the following equation:

$$G = 100 * \left(\frac{F - D}{C} \right)$$

where: C = Weight of Dry Aggregate (line C)
 D = Mixing Bowl+Dry Aggr Weight (line D)
 F = Total Actual Weight (line F)
 G = Actual Asphalt Content (%)

For Method 2 use the following formula:

$$G = \frac{(100 * (F-D))}{(C + (F-D))}$$

where: C = Weight of Dry Aggregate (line C)
 D = Mixing Bowl + Dry Aggr. Weight (line D)
 F = Total Actual Weight (line F)
 G = Actual Asphalt Content (%)

FILLING SAMPLE PANS

Filling Tips

- ◆ Level the mixture on the top of the sample pan, spreading the mixture out to the edges of the pan. The calibration sample may be compressed with a piece of flat wood or flat metal plate to ensure that the asphalt is level with the top of the pan. **Do Not Compact The Sample With a Press or Compaction Tool!**
- ◆ Place a piece of wax paper over the pan to prevent the asphalt from sticking to the flat plate.

Filling Procedure

Use the Forms in Appendix F to record the values.

- ✓ Weigh the empty sample pan and enter the value on line H
- ✓ Write the sample number and pan weight on the pan.
- ✓ Enter the weight of the blank sample (line 3) on line J.
- ✓ Add lines H and J and enter the total on line K.
- ✓ Write the actual % AC (line G) on line L.
- ✓ Place the preheated sample pan on a table and fill about 1/3 full (see *Filling Tips*).
- ✓ Settle the asphalt mixture by tapping the pan on the table.
- ✓ Lightly press the mixture with a spoon or spatula.
- ✓ Continue adding the mixture in three layers, settling and tamping each layer until the sample pan is full.
- ✓ Place the sample pan on the scales and add or remove material until the weight equals the weight on line K.

PERFORMING THE CALIBRATION

After preparing all calibration samples, the calibration can be performed for the design mixture. This procedure refers to the calibration forms in Appendix F.

To access the *Calibration* function, press <**CALIB**>.

Calib# xxxxx
1- Review Calib.
2- Stored Calib.
3- New Calib.

For a *new* calibration press <**3**>.

**Select source
for New Calib.**
1- Keypad input
2- Gauge derived

To manually enter calibration data, press <**1**>. This option is commonly used to re-enter previously accumulated calibration data.

To have the gauge collect calibration data, press <**2**>.

The gauge will prompt for a new background count. Press <**YES**>. After accepting the count, the display will request the weight of the blank sample. The net weight is on line 3.

Blank sample
Net WT: _____ g.
**Input and
Press ENTER**

The gauge will request the number of calibration samples.

**How many samples
(2-12)? ____
Input and
Press ENTER**

Input the number of samples and press **<ENTER>**. The display will request the % asphalt content (AC) of the first sample.

**- Sample # 1 -
%AC: ____ %
Input and
Press ENTER**

Input the % AC, from line G. Press **<ENTER>**.

Place the first calibration sample in the sample chamber and press **<START>**. Record the counts on line M.

Repeat the above procedure for each sample. After all samples have been measured the display will be:

**Fit coeff: x.xxx
Want to review
input data?**

The gauge calculates the calibration curve and curve "fit." The "fit coefficient" will be a value between 0.0 and 1.0, with 1.0 being a perfect fit.

After calculation of the fit coefficient, the data may be viewed.

To view data, press **<YES>** at the *"Want to review input data?"* display.

If data is not to be reviewed, press **<NO>** at the prompt. The gauge proceeds to the calibration storage display (see page 4-12).

**Select method of
viewing data:
1 - Screen
2 - Printout**

To view the data on the screen, press <1>.

**- Review Data -
Weight: xxxx g.
Background: xxxx
(Press YES)**

To scroll through the displays, press <YES>.

**A1: x.xxxxxxx
A2: x.xxxxxxx
A3: x.xxxxxxx
(Press YES)**

Record the coefficients on the form in Appendix F. Press <YES>.

**# 1: x.xxx% AC
Counts: xxxx
Diff= x.xxx% AC
(Press YES)**

Continue to view the remaining samples by pressing <YES>.

**"Diff" is the difference between the actual % AC entered and
the % AC calculated from the calibration curve.**

**Calibration
Activated !
Want to store
Calibration?**

To store the calibration, press <YES>.

Calibration #?

**Input and
Press ENTER**

Input a calibration number. This number will be used to recall the calibration at a later date. Press <ENTER>.

What is Mix ID?

**Input and
Press ENTER**


Input the asphalt mixture number and press <ENTER>.

The calibration will be stored and the gauge will return to the *Ready* mode.


REVIEWING A CALIBRATION

Calibrations that have been stored in the gauge may be recalled and viewed at a later date.

Press <**CALIB**>.



To review a calibration, press <**1**>.



If the calibration number is known, press <**2**> and enter the number. The gauge displays the calibration data. To scroll through the data, press <**YES**>. After viewing all the calibration data, the gauge returns to the *Ready* mode.

To scroll through the calibration numbers, press <**1**>.




If the calibration number shown on the display is not correct, press <**1**> or <**2**> to scroll through the list of calibrations.

To select calibration for review, press <**3**>. The gauge displays the data and returns to the *Ready* mode after the review.

ENABLING A STORED CALIBRATION

Calibrations that have been stored in the gauge may be enabled at a later date.

To access the *Calibration* feature, press <**CALIB**>.



Calib# xxxxx
1- Review Calib.
2- Stored Calib.
3- New Calib.

To activate/enable an existing calibration, press <**2**>.



STORED CALIB.
1- View Calibs.
2- Known Calib.
3- Exit

If the calibration number is known, press <**2**> and enter the number. The gauge will indicate the activation and return to the *Ready* mode.

To view the list of calibrations, press <**1**>.



Calib# xxxxxxxx
1- Scroll Up
2- Scroll Down
3- Select Calib.

Scroll through the calibration numbers by pressing <**1**> or <**2**>.

Select the calibration number displayed by pressing <**3**>.

MANUALLY ENTERING CALIBRATION DATA

To access the *Calibration* feature, press <CALIB>.

Calib# xxxxx
1- Review Calib.
2- Stored Calib.
3- New Calib.

To enter calibration constants, press <3>.

**Select source
for New Calib.**
1- Keypad input
2- Gauge derived

Press <1>.

Blank sample
Net WT: _____ g.
Input and
Press ENTER

Input all information requested by the gauge.

NOTES

CHAPTER V

STORING PROJECT DATA

This chapter covers the procedures for storing gauge measurements, assigning project numbers, printing project data and erasing old projects from memory.

Contents:

THE PROJECT FUNCTION	5-2
Create a New Project	5-2
View an Existing Project	5-3
STORING A MEASUREMENT	5-4
PRINTING MEASUREMENT DATA	5-5
ERASING A PROJECT	5-6


THE PROJECT FUNCTION

Data is stored in the 3241-C under a *project number*. When a project is *active*, all readings are stored under this project number. This feature allows data retrieval and printing (or downloading to a computer).

The *Project* function allows projects to be created and viewed.


CREATE A NEW PROJECT

Press <**SHIFT**> and <**PROJECT**> for the display:



PR# XXXXX
1- View Projs.
2- Known Proj.
3- New Proj.


Press <**3**>.



Project Number:

Input and
Press ENTER

Input a project number (up to 12 numerics) and press <**ENTER**>. After a brief delay the display will be:



NEW PROJECT
NUMBER:
XXXX.XX

The gauge will return to the *Ready* mode.

VIEW AN EXISTING PROJECT

Press <**SHIFT**> and <**PROJECT**> for the display:

PR# XXXXX
1- View Projs.
2- Known Proj.
3- New Proj.

If the project number is known, press <**2**> and see the third display on this page. To view the project numbers, press <**1**>.

PR# XXXXX
1- Scroll Up
2- Scroll Down
3- Select Proj.

To scroll through the list of projects, press <**1**> or <**2**>. To select the project for viewing, press <**3**>.

PR# XXXXX
1- First Sample
2- Last Sample
3- Exit

To display the first data stored under the project number, press <**1**>.

To display the most recent data stored under the project, press <**2**>.

To exit to the *Ready* mode, press <**3**>.

STORING A MEASUREMENT

After taking a measurement the data may be stored under a *project number* for recalling and printing at a later time.

Press <**STORE**>.

Sample Number?

**Input and
Press ENTER**

Input a numeric sample number (up to six numerics) and press <**ENTER**>.

The asphalt sample data will be stored under the current project and sample number.

PRINTING MEASUREMENT DATA

Project data may be printed at any time after taking and storing the readings. Data may be printed (uploaded) to a computer file, with the control unit connected to a personal computer using an interface cable. To download data to a computer, use the HyperTerminal® application available from the Microsoft Windows® Accessories menu.

Press **<PRINT>**. The display will be:

**Select data
to Print:
1- Project data
2- Calib. data**

Press **<1>**.

**Connect serial
device & Select:
1- one Project
2- all Projects**

Connect the printer to the serial port located on the back of the console (refer to Chapter 7, page 7-16 for information on setting the baud rate and the location of the serial port).

To select a single project, press **<1>**. To print all projects, press **<2>**.

If printing only one project, the gauge allows the user to scroll through the project list or input a known project number.

**PRINT PROJECT
1- View Projs.
2- Known Proj.
3- Exit**

Scroll through the project numbers by pressing **<1>**. To input a known project number, press **<2>**.

ERASING A PROJECT

The *Erase* function allows project data (or a calibration) to be erased or removed from gauge memory. To erase a project from memory, press <**SHIFT**> and <**ERASE**>.

Select to ERASE:

- 1- one Project
- 2- all Projects
- 3- one Calib.

Erase all projects by pressing <**2**>. At the erase prompt, press <**SHIFT**> and <**YES**>. After erasing all projects, the gauge returns to the *Ready* mode.

Erase a single project by press <**1**>.

ERASE PROJECT

- 1- View Projs.
- 2- Known Proj.
- 3- Exit

To view the project list, press <**1**>.

PR# 123.45

- 1- Scroll Up
- 2- Scroll Down
- 3- Select Proj.

Scroll through the project list by pressing <**1**> or <**2**>. To select the project for erasure, press <**3**>.

To erase at the erasure prompt press <**SHIFT**> and <**YES**> to erase. After erasing the project, the gauge returns to the *Ready* mode.

ACCIDENTAL ERASURE

If data is accidentally erased press <**SHIFT**> and <**SPECIAL**>.

Press <**3**> to select *Recover Erase*.

NOTES

CHAPTER VI

THE SHIFT FUNCTIONS

This chapter gives brief explanations of the *Shift* functions available on the **Model 3241-C Asphalt Content Gauge**. These functions are displayed on the numeric keys of the keyboard and are accessed by pressing <**SHIFT**> and the corresponding function key.


Contents:

STATUS	6-2
OFFSET	6-2
SPECIAL	6-7
PROJECT	6-7
AUTO-STORE/AUTO-PRINT	6-7
ERASE	6-8
RECALL	6-9
TARGET PRECISION	6-9
CALCULATOR	6-10
CALIBRATION SAMPLE PREP	6-11

STATUS

The *Status* Function allows the user to view each gauge setting without accessing the individual function.

Press <**SHIFT**> and <**STATUS**> for the display:



To view settings, press <**YES**> at each subsequent screen. Exit by pressing <**NO**>.

OFFSET

The *Offset* function provides a method for adjusting an existing calibration to obtain higher accuracy when it is not practical to perform a new calibration.

A calibration is performed using the specific materials found in the test samples. Therefore, a new calibration ensures that the gauge will obtain the highest accuracy possible. Perform an *offset* only as an intermediate measure and if the materials (aggregate, additives, bitumen) vary slightly.

The Model 3241-C offers the user three different types of offset adjustments: *slope*, *relative*, and *slope/intercept*. The calibration curve will be adjusted according to the offset selected.

SLOPE OFFSET

If the asphalt source changes and recalibration is not possible, a *slope offset* can be performed (Figure 4). This offset uses a selected calibration and a new *offset sample* of known % AC to recalculate the slope of the calibration curve. A slope offset will

produce accurate results if the unknown samples are within 0.5% AC of the offset sample.

RELATIVE OFFSET (% AC Shift)

This offset can be used to correlate gauge readings and extraction results. A *relative offset* adds or subtracts the offset to adjust the calculated value (Figure 6).

RELATIVE OFFSET (Intercept)

If the aggregate moisture changes from the time the original calibration was performed, the *intercept relative offset* can be used. An offset sample of known % AC must be prepared and measured to provide the information relevant to this offset (see page 4-3).

SLOPE / INTERCEPT OFFSET

If the asphalt sample *gradation* has changed, the original calibration can be adjusted with the *slope/intercept offset* (Figure 7). Two samples of known % AC must be prepared and tested in the gauge. The gauge calculates a new curve slope and intercept based on the offset samples. The original calibration will be adjusted by the calculated slope and intercept. This method enables the user to quickly adjust a calibration when more than three samples were used for the original calibration.

NOTE

An original 2-point calibration can also be performed using the two offset samples.




Figure 4
Sample Slope Offset Graph




Figure 5
Example Relative Offset Graph




Figure 6
Example Slope/Intercept Offset Graph


To access the *Offset* function, press <**SHIFT**> and <**OFFSET**>.



Exit by pressing <**3**>.

If the calibration number is known, press <**2**>. To perform the offset, select the type of offset and follow the gauge displays.

To scroll through the calibrations stored in memory, press <**1**>.



To view the calibrations stored in memory, press <**1**> and <**2**>. Select the calibration for offset by pressing <**3**>.

Perform the offset by selecting the method and following the gauge displays.

SPECIAL

Refer to Chapter 7 for detailed information on all of the *Special* functions available on the Model 3241-C.

PROJECT

Refer to Chapter 5, page 5-2 to create, view and/or erase a project previously stored in gauge memory.

AUTO-STORE / AUTO-PRINT

NOTE

The *Auto-Store* and *Auto-Print* functions are independent of each other. One function can be "ON" while the other is "OFF."

AUTO-STORE READINGS

The *Auto-Store* function allows automatic storage of gauge readings after completion of the count. A sample number will be assigned to the reading and will increment by one (up to 99) after each reading.

Press <**SHIFT**> and <**AUTO**> for the display:



AUTO-STORE: OFF
AUTO-PRINT: OFF
Change: 1- Store
2-Print 3-Exit

To change the status of the *Auto-Store* function, press <**1**>.

AUTO PRINT READINGS

Auto-Print is a convenience function that configures the gauge to automatically print the results of sample readings after each measurement.

The status of this function may be changed after the *Auto-Store* option choice by pressing **<2>**.

ERASE

ERASE PROJECTS

Refer to Chapter 5, page 5-6 for details on erasing a project.

ERASING A CALIBRATION

To remove a calibration from memory press **<SHIFT>** and **<ERASE>**.


Select to ERASE:
1- one Project
2- all Projects
3- one Calib.

Press **<3>**.

ERASE CALIB.
1- View Calibs.
2- Known Calib.
3- Exit

If the calibration number is known, press **<2>**. Enter the calibration number and press **<SHIFT>** and **<YES>** at the erase prompt. The gauge will return to the *Ready* prompt.

To scroll through the list of calibrations stored in the gauge, press **<1>**.




View the calibrations by pressing **<1>** or **<2>**. To select the calibration, press **<3>**.

To erase the calibration at the erase prompt, press **<SHIFT>** and **<YES>**.

RECALL

Use the *Recall* function to view the results of the last reading taken with the Model 3241-C.

Press **<SHIFT>** and **<RECALL>** for:



TARGET PRECISION

If the user requires a higher precision, the 3241-C may be programmed to automatically increase the count time to reach the desired precision.

Using an ASTM precision equation, the 3241-C count time will be adjusted to obtain the required precision. The maximum time

allowed under this function is 60 minutes. The required precision time is rounded to the nearest 15 second interval.

Press **<SHIFT>** and **<PRECISION>** for:

Target Precision
_____%
Input Precision
& Press ENTER

Input the required precision and press **<ENTER>**.

The gauge will request the % Asphalt Content (AC). Input the %AC and press **<ENTER>**.

The gauge calculates the time required to obtain the requested precision.

Time to reach
xx.xx% Precision
xxxxx minutes
(Press ENTER)


The gauge automatically enables the count time calculated to reach the target precision.

CALCULATOR

The 3241-C Asphalt Content Gauge is equipped with a four function calculator. The function keys are located on the two left rows of the keypad. When the *Calculator* function is active these keys are enabled.

To activate the *Calculator* function, press **<SHIFT>** and **<CALC>**.

To perform the calculator operation, use the $\langle + \rangle$, $\langle - \rangle$, $\langle \times \rangle$, $\langle \div \rangle$ keys located in the lower left corner of the keypad. The $\langle = \rangle$ key is located on the $\langle \text{START/ENTER} \rangle$ key.



A rectangular box with a thick black border representing a calculator screen. Inside, the text is centered and reads: **- CALCULATOR -**
4.125
+ 3.273
= 7.398

Results may be stored in memory by pressing $\langle \text{MS} \rangle$.

Retrieve results from memory by pressing $\langle \text{MR} \rangle$.

Exit the calculator mode by pressing $\langle \text{EXIT} \rangle$.

CALIBRATION SAMPLE PREP

Refer to Chapter 4 for detailed information on preparing calibration samples.

The *Calibration Sample Prep* function allows the entry of the calibration values such as % Asphalt Content (AC), weight of mixing bowl, weight of aggregate, etc.

After prompting for the initial values, the gauge will automatically calculate the sample weight and prompt the user to add asphalt until the desired weight is reached. This information will be entered onto the *Calibration Forms* found in Appendix F.

Press $\langle \text{SHIFT} \rangle$ and $\langle \text{PREP} \rangle$.

**CAL. SAMPLE PREP
SELECT
1- % of DRY WT
2- % of TOTAL WT**

For the following example, **Method 1** (% Asphalt by Aggregate Dry Weight) will be used.

Press <**1**>. The gauge will request the % Asphalt Content.

**Input Desired
% Asphalt
_____ %
(Press ENTER)**

Input the % AC and press <**ENTER**>.

**Weight of empty
mixing bowl:
_____ g
(Press ENTER)**

Input the weight of the "scraped clean" mixing bowl (see Chapter 4).
Press <**ENTER**>.

Enter the weight of the aggregate that was used to prepare the blank sample. Press <**ENTER**>. The gauge will calculate the combined weight.

**Mixing bowl +
BLANK aggregate:
xxxxxg
ENTER when ready**

The gauge instructs the user to add asphalt to the aggregate until the displayed weight is reached.

**Add Asphalt till
asph.+bowl+aggr.
= XXXX g.
(Press ENTER)**

Press <**ENTER**>. Verify the weight and press <**YES**>.

The gauge will request the weight of the sample pan.

**Input weight of
empty Sample Pan
_____ g.
(Press ENTER)**

Input the weight of the empty sample pan. Press <**ENTER**>.

**Add material
till weight =
XXXX.X g.
(Press ENTER)**

The gauge will prompt the user to add the sample mixture to the pan until the displayed weight is reached. Press <**ENTER**>.

The sample is ready for calibration. Repeat the above procedure for each sample to be used.

NOTES

CHAPTER VII

SPECIAL FUNCTIONS

This chapter gives brief explanations of the *Special* functions available on the **Model 3241-C Asphalt Content Gauge**.

Contents:

STAT TEST	7-2
DRIFT TEST	7-5
RECOVER ERASE	7-7
TIME/DATE	7-7
CALIBRATION TRANSFER	7-8
BAUD RATE	7-16
CUSTOMER NAME	7-17
SERIAL NUMBER	7-17
PAN WEIGHT DISPLAY	7-18

STAT TEST

Erratic readings or readings that seem to fluctuate may indicate a problem with the gauge. In the event the readings are "suspect," the *Stat Test* may be executed to validate the normal operation of the gauge.

A *Stat Test* consists of twenty 1-minute counts. Although other count times are available (4, 8 and 16 minute) they are not recommended, since the temperature correction process is not utilized during a stat test. Long count times (causing the stat test to run overnight) could result in the gauge undergoing temperature changes. It is very important that the ambient temperature remain the same during the stat test. The longer count times, however, can be used to check long term gauge operation.

After the 20 counts, the gauge calculates the standard deviation. This standard deviation is compared to a theoretical standard deviation value. Ideally this ratio should be one. However, the 3241-C prescale (or divide) for one minute counts is 4. This results in an ideal ratio of (0.5). The acceptable limits for the ratio are from (0.35) to (0.71). The gauge is considered to be unstable if the ratio is outside these limits. The table below gives the limits for other count times.

RATIO TABLE

<u>Time</u>	<u>Limits</u>
1	0.35 to 0.71
4	0.17 to 0.35
8	0.12 to 0.25
16	0.09 to 0.18

Figure 7
Range of Standard Deviation Ratios

To execute a stat test place the gauge in an area free of other gauges or radioactive sources. Press <**SHIFT**> and <**SPECIAL**>.

Press <1> for the display:

- STAT TEST -
Time: xx min.
Do you want
to change?

To accept the displayed count time, press <NO>.

To change the count time press <YES> and enter the desired count time. The user may select count times of 1, 4, 8 and 16 minutes.

Press <ENTER>.

Remove any samples or sample pans from the gauge.

Close the door and press <START>.

After the 20 counts have been completed, the gauge will display the average counts and indicate if the test passed or failed. The individual count data may be viewed or printed at this time by pressing <YES> at the view data prompt. To return to the *Ready* mode without viewing the data, press <NO>. View the data by pressing <YES> at the view data prompt.

Select the method of viewing the data. If a printout is desired refer to page 7-16 for the location of the serial port and baud rate selection. A sample print out is shown on page 7-4.

```

*****
* Statistical Stability Test *
*****
Count Time = 1 min.
          9:23 AM    4/12/93
Serial #: 960

```

#	Counts	#	Counts
1	2486	2	2465
3	2455	4	2476
5	2500	6	2481
7	2454	8	2475
9	2427	10	2471
11	2443	12	2479
13	2474	14	2489
15	2443	16	2428
17	2453	18	2491
19	2469	20	2457

```

-----
Average counts:2466
Ratio: 0.41 PASS
*****

```

Figure 8
Sample Stat Test Print Out

DRIFT TEST

Assuming that the stat test has already been performed (and passed), but gauge readings seem to drift between tests, the *Drift Test* can be performed to check the long term drift of the gauge.

The drift test consists of five counts performed approximately 3-4 hours after completion of a stat test.

NOTE

The count time is based on the last stat test. The drift test count time should be four times the stat test count time. **The gauge should not be turned off between the stat test and drift test.** The stat test must be current.

To access the *Special* function menu, press <**SHIFT**> and <**SPECIAL**>.

To access the *Drift Test* feature, press <**2**> and <**ENTER**> for:

**Will take five
xx min. counts.
Close door and
Press START**

Remove any samples or sample pans from the gauge.

To start taking the 5 counts, press <**START**>.

After completion of the 5 counts, the gauge will display the average counts and indicate if the test passed or failed. The Pass/Fail criteria is $\pm 1.0\%$.

Avg Cnts: xxxx
Drift: x.xx% P
Want to view
DRIFT test data?

The individual count data may be viewed or printed at this time. To return to the *Ready* mode without viewing the results, press <NO>. View the data by pressing <YES> at the prompt. A sample print out is shown below.

```

*****
*   Statistical Drift test   *
*****
Troxler Gauge Serial #: 960
Current Stat test results:
      9:23 AM   4/12/93
Count Time:  1 min.
Average counts: 2466
Ratio:   0.41 PASS
-----
Drift test results:
      9:45 AM   4/12/93
      #   Counts   |       #   Counts
      1   2461   |       2   2450
      3   2462   |       4   2467
      5   2479   |
Five 4 minute counts
Average counts:2464
Drift:   0.08 PASS
*****

```


Figure 9
Sample Drift Test Print Out

RECOVER ERASE

In the event that project data is inadvertently erased the *Recover Erase* function may recover the lost information. There is no guarantee that the *Recover Erase* function will successfully recover the lost data. If data has been stored after an accidental erasure a successful recovery is impossible.

To access the *Special* function menu, press <**SHIFT**> and <**SPECIAL**>.

Access the *Recover Erase* feature by pressing <**3**>. If the recovery is successful the display will be:



TIME/DATE

Refer to page 3-5 for information on changing the time or date.

CALIBRATION TRANSFER

During paving operations several asphalt content gauges may be used for quality control of the asphalt mix . These gauges usually include one central "master" gauge and numerous "field" gauges. When more than one gauge is used to determine the asphalt content of a single asphalt mix, each gauge must be separately calibrated for that mix. This process can involve preparing calibration samples and manually calibrating each gauge. Performing individual gauge calibrations is labor intensive, time consuming and may also involve transporting the gauges between laboratories. Additionally, the gauges will be out of use during the time required for calibration.

Calibration Transfer overcomes many of the problems associated with using multiple gauges for one particular mix design. This procedure allows the transfer of a central "master" gauge calibration to multiple "field" gauges, without the need for individual gauge calibrations. Calibration transfer reduces gauge downtime, reduces labor and helps ensure more uniform asphalt content measurements among all gauges. Calibration transfer also reduces the chance of error produced by the sample preparation techniques preferred by different operators.

The "master" gauge resides in the central laboratory and is used to perform the different mix calibrations. The "field" gauge resides in the field laboratory and receives the calibration constants from the "master" gauge for the different mix designs. The "field" gauge does not perform any calibrations after the cross calibration procedure.

The first step of the calibration transfer process is the cross calibration of the "master" gauge to all of the "field" gauges. This procedure need only be performed once for each "field" gauge. A minimum of five calibration samples will be used to obtain an initial *relational curve* (or correlation) between the "master" and "field" gauges. These samples must include one sample with at least 0.5% asphalt above the normal mix range and one sample with at least 0.5% asphalt below the normal mix range. The five calibration samples must be prepared and measured on the same day.

If preparing sealed (special) calibration samples (Appendix E) that span the mix range, these samples may be used to determine the relational curve. For each "field" system, measurements of the special samples should be taken with both the "master" and "field" gauges.

After the cross calibration is completed, calibrations performed on the "master" gauge can be transferred to the "field" gauges without additional "field" gauge calibrations. This transfer is performed by entering the "master" gauge background count and calibration constants into the "field" gauges. Based on the cross calibration data, the constants will be adjusted to reflect the differences between the "master" gauge and each "field" gauge.

CROSS CALIBRATION

If a cross calibration has already been performed go to page 7-14 for information on transferring a calibration.

The following steps must be performed prior to transferring a calibration from a "master" gauge to a "field" gauge.

Prepare a minimum of five cross calibration samples. Refer to Chapter 4 for detailed instructions on preparing asphalt samples for calibration. These samples must be prepared with one sample containing at least 0.5% asphalt above the range of all the mixes used and one sample with 0.5% asphalt below the normal range.

Set the count time to 16 minutes.

On the "Master" Gauge...

- ✓ Press <**CALIB**>.
- ✓ Take a new background count and record the value.
- ✓ Perform a calibration with the five samples.
- ✓ Record the counts obtained on each of the samples.

On the "Field" Gauge...

Perform a cross calibration on the "field" gauge. This procedure, discussed in detail on the following pages, only needs to be performed one time to set up the relationship between the "master" and "field" gauges.

The following is an overview of the procedure:

- ✓ input the number of samples,
- ✓ perform a background count,
- ✓ measure the samples,
- ✓ input "master" gauge background count,
- ✓ input the five sample counts taken with the "master" gauge, and
- ✓ enter the transfer number.

This procedure should be repeated for each "field" gauge.

To access the *Special* functions menu, press <**SHIFT**> and <**SPECIAL**> on the "field" gauge.

To access the *Calibration Transfer* feature, press <**5**>. The display will be:



Calib. Transfer:
1- Cross Calib.
2- Transfer

Press <**1**> for *Cross Calibration* mode.

**How many samples
(5-12) ____
Input and
Press ENTER**

Input the number of asphalt samples (the same number of samples used with the "master" gauge.)

**Field Gauge
Measurement -
1- Keypad input
2- Gauge derived**

The user has the option of manually entering the count data using the keypad or automatically taking the measurements using the gauge.

To manually enter sample data, press <1>. The samples must have been previously measured in either the *Calibration* or *Cross Calibration* mode.

For gauge derived cross calibration data collection, press <2>.

This procedure assumes the *gauge derived* method.

The gauge will request a background count. If the background count is not current or the gauge has been moved, press <YES>. Empty the sample chamber and press <START>.

If the background count is acceptable, press <YES>.

Input the sample %AC. The display requests the first sample.

**Place Sample #1
in gauge, close
door, and
Press START**

To measure the first sample, press <**START**>.

After the measurement is complete, the gauge requests that the remaining samples be measured.

When all the samples have been measured, the gauge requests the background count from the "master" gauge (this value was recorded earlier, see page 7-9).

**Master Gauge
Background:**

Press ENTER

Input the background count from the "master" gauge.

The gauge requests the sample counts obtained with the "master" gauge. Input the "master" gauge sample counts. **The counts must be entered in the same order as the "field" counts that were taken above!**

After entering the "master" gauge sample counts the "field" gauge will calculate a *relational calibration curve*, used later for transferring calibrations from the "master" to the "field" gauge.

When the calculations are complete, the data may be viewed or printed.

Review data:

1- No review

2- Screen


3- Printout

To return to with the cross calibration process without reviewing the data, press <**NO**>.

To view the data on the display, press <**2**>. After reviewing the data, continue by pressing <**1**>.

To print the data, press <**3**>. Continue by pressing <**1**>.

The gauge will request a *transfer number*.



Input the transfer number (up to 8 numeric characters). This number can be composed of the gauge serial numbers. For example, if the "master" gauge serial number is 650 and the "field" gauge serial number is 658 the transfer number can be 650.658. *After entering the transfer number, press <ENTER>.*

The cross calibration is complete and will be store.

At this time the "master" gauge can be used to perform calibrations for different mix designs. Calibrations may now be transferred to the "field" gauges without additional "field" gauge calibrations.

TRANSFER

Once a cross calibration has been performed and stored, "master" gauge calibrations may be transferred to the "field" gauge without the need for a complete "field" gauge calibration.

On the "Master" Gauge...

Prepare asphalt samples for the particular mix being used and perform a calibration (see Chapter 4) on the "master" gauge. After completion of the calibration, record the sample weight, the "master" gauge background count, and calibration constants A1, A2 and A3.

On the "Field" Gauge...

To access the *Special* functions menu, press <**SHIFT**> and <**SPECIAL**>.

To access the *Calibration Transfer* feature, press <5>. The display will be:

Calib. Transfer:
1- Cross Calib.
2- Transfer

Press <2>.

Trans# XXXXX
1- Select
2- Next Trans #
3- Erase

The transfer number is established after the cross calibration of the "master" and "field" gauges (refer to page 7-14).

If the transfer number shown is correct press <1>.

To scroll through the list of stored transfer numbers, press <2>.

The transfer number currently displayed on the gauge screen may be erased by pressing <3>.

After selecting the correct transfer number, input the calibration information from the "master" gauge into the "field" gauge. Enter the sample weight, the background count, and calibration constants A1, A2, and A3.

Store this calibration. When a calibration is stored under the *Calibration Transfer* mode, /**x** is placed after the calibration number.

The "field" gauge is now ready to measure the unknown samples of asphalt.

BAUD RATE

The *Baud Rate* function allows the user to configure the gauge for communication with a RS-232 serial device such as a printer or computer.

The baud rate or communication speed should be set to match the peripheral device. Refer to the device owner's manual for the proper settings.

To access the *Special* features menu, press <**SHIFT**> and <**SPECIAL**>.

To access the *Baud Rate* function, press <**6**> for the display:

Baud Rate: xxx
Want to change?

Accept the displayed baud rate by pressing <**NO**>.

If the baud rate is incorrect, press <**YES**>.

Baud rate: XXXX
Select: 1- 110
2- 300 3- 600
4-1200 5-2400

Input the baud rate that matches the printer or computer.




Figure 10
Serial Device Connection

CUSTOMER NAME

Refer to Chapter 3, page 3-6 for information on this function.

SERIAL NUMBER

The *Serial Number* function allows the user to re-enter the gauge serial number.

To access the *Special* functions menu, press **<SHIFT>** and **<SPECIAL>**.

To access the *Serial Number* feature, press **<8>** for the display:

Serial Number:
xxxxxxx
Want to change
Serial NUMBER?

To change the gauge serial number, press **<YES>**.

This feature requires an access code to prevent tampering by unauthorized personnel. Input the access code and press **ENTER**.

Serial Number:

Input and
Press ENTER

Input the new serial number and press **<ENTER>**.

PAN WEIGHT DISPLAY

The *Pan Weight Display* function allows the user to configure the gauge to display the weight of the sample pan prior to taking a sample measurement.

With the *Pan Weight Display* enabled, the gauge will request the weight of the empty pan. After input of the weight, the gauge will instruct the user to fill the pan with asphalt until the proper weight is reached.

To access the *Special* functions menu, press <**SHIFT**> and <**SPECIAL**>.

To access the *Pan Weight Display* feature, press <**9**> for the display:



To enable the pan weight display, press <**YES**>.

NOTES

APPENDIX A

RADIOLOGICAL INFORMATION

This appendix is required reading for anyone who will operate the 3241-C nuclear system. Information covering radiation theory is contained in this appendix along with a brief explanation of radiation statistics and radiation terminology.

Contents:

RADIATION THEORY	A-2
Atomic Structure	A-2
Radiation Theory	A-3
Radiation Terminology	A-3
Radiation Statistics	A-4
RADIATION SAFETY	A-6
Types of Radiation	A-6
Limiting Exposure	A-7
3241-C (100 mCi) Radiation Profile	A-9
3241-C (300 mCi) Radiation Profile	A-10
Source Encapsulation	A-11

RADIATION THEORY

A more detailed discussion of radiological theory can be found in the *Troxler Nuclear Gauge Safety Training Program* manual, provided you have taken the Troxler safety class.

ATOMIC STRUCTURE

All materials consist of chemical elements that can not decompose by ordinary chemical methods. Some examples are:

(H) Hydrogen

(C) Carbon

(O) Oxygen

(U) Uranium

(Cf) Californium

(Co) Cobalt

Each element contains an atom with a unique structure. The atom consists of smaller particles such as protons, neutrons and electrons. The protons and neutrons are grouped together in the nucleus. The electrons orbit the nucleus (Figure 11). An atom is normally electrically neutral because the positive protons cancel out the negative electrons.




Figure 11
Diagram of an Atom

Protons carry a positive charge and are described as having a mass of one. Neutrons have a neutral charge and also have a mass of one. Electrons carry a negative charge and essentially have no mass.

MASS

(ATOMIC WEIGHT SCALE)

Protons	1.0073	+1
Neutrons	1.0087	0
Electrons	0.0006	-1

CHARGE

Since protons and neutrons are clustered together in the nucleus, the mass of an atom is concentrated in the nucleus. The atom shown in Figure 11 has two protons and two neutrons; therefore, it is a helium atom. The atomic weight of an atom is the sum of the protons and neutrons.

RADIATION THEORY

Radioactivity is the spontaneous breakdown of unstable nuclei (radioisotopes) with the resulting emission of radiation. The basic unit of radiation used in the U.S. is the curie (Ci) and is defined as 3.7×10^{10} disintegrations of nuclei per second. In the "Special Form," encapsulated sealed source used in the 3241-C, the unit of measure is the millicurie (1/1,000 of a curie). The SI unit of radiation is the Becquerel and is equal to one disintegration per second. Therefore, one curie equals 3.7×10^{10} Becquerels.

The strength of radioactive material is measured by its activity, or rate of decay. This activity decreases with time. The length of time it takes a given amount of radioactive material to decay to half of its original strength is referred to as the "half-life." The half-life of an americium-241 source is approximately 432 years.

RADIATION TERMINOLOGY

Various standards for the measurement of radiation exist, but only two concern the Troxler instrument user. These units are the curie and the roentgen equivalent man (rem). The curie, defined as the quantity of radioactive material giving 3.7×10^{10} disintegrations per second, is equal to the number of disintegrations/second of one gram of radium-226. Note that the source used in the 3241-C is small, with quantities expressed in millicurie (mCi).

The **rad** or "radiation absorbed dose," is the unit of absorbed dose that is equal to 0.01 Joules/kg in any medium. In order to take into consideration the effect of various types of radiation on biological tissue, the rem, or more appropriate for Troxler users - the millirem - is used to measure radiation dosage. The unit rem is derived from scaling the radiation absorbed dose (rad) by a quality factor (QF). One **rad** is equal to the exposure of one **rem** of photon radiation.

For example, the average neutron energy of an americium-241:beryllium source is approximately 4.5 MeV. The quality factor (QF) for this radiation is approximately 10. The absorbed dose of 1 rad of neutron radiation produces a dose equivalent of (absorbed dose x QF) 10 rem.

Occupational exposure limits are set by government agencies. The current limit in the United States and many other countries is 5,000 millirem per year. Under average conditions, a full time employee working with the 3241-C will receive less than 200 millirem per year.


Anyone working with or near radioactive materials is subject to the limits on occupational exposure mentioned earlier and must complete a radiation safety training course to be designated an authorized user. As an authorized user, an individual so designated must work in a "controlled" environment to the extent that their exposure to radiation must be monitored. Several means of personnel monitoring or *dosimetry* exist; the most common methods are film badges and TLD badges.

RADIATION STATISTICS

Radioactive emission is a random process. The number of emissions in a given time period is not constant but varies statistically about an average value. The variation about the true mean value is a Poisson distribution. In this distribution, the standard deviation (σ) about the mean (n) is defined as:

$$\sigma = \sqrt{n}.$$

When the mean is greater than 100, the Poisson distribution can be closely approximated by the normal distribution (Figure 12). The normal distribution predicts the probability that any given count rate will fall within a selected region about the mean.



Normal Distribution

Figure 12
Variation of Radioactive Emission

Using the mean of a larger number of counts to approximate the true mean, the distribution shows that 68.3% of the time the count rate obtained will be within ± 1 standard deviation of the mean.

Figure 12 shows the chance of counts falling within three standard deviations. A statistical stability test may be performed to compare the experimental standard deviation to the theoretical standard deviation (see page 7-2).

RADIATION SAFETY

This section provides a brief discussion of general radiation safety. The exposure profiles for the Model 3241-C gauge are also included, along with a discussion of the source encapsulation.

TYPES OF RADIATION

The radioactive sources in the Model 3241-C produce three types of radiation:

Alpha Particles
Photons
Neutrons

The alpha particles are stopped by the source capsule. Only the photon and neutron radiation contribute to the occupational radiation exposure.

Photon radiation is electromagnetic radiation, as are x-rays, radio waves, and visible light. Visible light and photons have no mass, a zero electrical charge and travel at the speed of light. Photons are energetic and penetrating. Dense materials provide the best shielding against photon radiation.

Neutron radiation allows measurement of the hydrogen content in a material because the neutrons are slowed by collisions with materials containing hydrogen atoms (i.e. water, polyethylene, etc). Neutrons have a neutral charge and are very penetrating.

LIMITING EXPOSURE

Current regulations for both NRC and Agreement States have established a whole body occupational exposure limit of 5,000 millirem per year. Under normal conditions a full time operator of the 3241-C will receive less than 200 millirem per year.

Taking advantage of all available means to limit radiation exposure is always recommended. The three methods of limiting exposure are:

TIME
DISTANCE
SHIELDING

These methods are a part of an "ALARA" (As Low As Reasonably Achievable) program.

TIME

The simplest way to reduce exposure is to keep the time spent around a radioactive source to a minimum. If time is cut in half, so is the exposure, with all other factors remaining constant.

DISTANCE

Distance is another effective means to reduce radiation exposure. A formula known as the "inverse square law" relates the radiation exposure rate to distance (Figure 13). Doubling the distance from a radiation source reduces the exposure to one-fourth its original value. If the distance is tripled, the exposure is reduced by a factor of nine, etc.





Figure 13
Effect of Distance on Exposure

SHIELDING

Shielding is any material used to reduce the radiation reaching the user from a radioactive source. While some types of radiation such as alpha particles may be stopped by a single sheet of paper, other particles such as neutrons and photons require much more shielding. Materials containing large amounts of hydrogen, such as polyethylene, are used to shield neutrons. Dense materials, such as lead, are used to shield photons. The Model 3241-C has shielding built into the system which reduces the exposure.

3241-C (100 mCi) RADIATION PROFILE



RADIATION PROFILE FOR 3241-C GAUGE (100 mCi)

LOCATION	SURFACE			10 cm.			30 cm.			1 Meter		
	Gamma	Neutron	Total	Gamma	Neutron	Total	Gamma	Neutron	Total	Gamma	Neutron	Total
FRONT	1.5	3.5	5.0				0.2	0.8	1.0	*	0.1	0.1
BACK	0.5	1.9	2.4				0.1	0.6	0.7	*	*	*
LF. SIDE	0.7	4.0	4.7				*	1.1	1.1	*	*	*
RT. SIDE	1.5	4.0	5.5				0.2	1.4	1.6	*	0.1	0.1
TOP	3.0	8.0	11.0				0.2	1.4	1.6	*	0.1	0.1
BOTTOM	2.0	4.0	6.0				0.15	1.4	1.55	*	0.1	0.1


RADIATION PROFILE FOR 3241-C IN PLASTIC CASE (100 mCi)

LOCATION	SURFACE			10 cm.			30 cm.			1 Meter		
	Gamma	Neutron	Total	Gamma	Neutron	Total	Gamma	Neutron	Total	Gamma	Neutron	Total
FRONT	0.3	1.4	1.7				0.1	0.4	0.5	*	0.1	0.1
BACK	0.3	1.2	1.5				0.1	0.4	0.5	*	0.1	0.1
LF. SIDE	*	0.3	0.3				*	0.1	0.1	*	*	*
RT. SIDE	0.3	1.2	1.5				*	0.4	0.4	*	0.1	0.1
TOP	0.9	1.6	2.5				0.1	0.6	0.7	*	0.1	0.1
BOTTOM	0.2	1.1	1.3				*	0.3	0.3	*	0.1	0.1

1. All readings in mrem/h.
2. "*" indicates reading less than or equal to 0.1 mrem/h.
3. Measurements made with Nuclear Research Corp., Model NP-2 Survey Meter, Calibrated March 1989.
4. Dose Rates for 100 mCi americium-241:beryllium source

Figure 14
3241-C (100 mCi) Radiation Profile

3241-C (300 mCi) RADIATION PROFILE



RADIATION PROFILE FOR 3241-C GAUGE (300 mCi)

LOCATION	SURFACE			10 cm.			30 cm.			1 Meter		
	Gamma	Neutron	Total	Gamma	Neutron	Total	Gamma	Neutron	Total	Gamma	Neutron	Total
FRONT	3.0	9.0	12.0				0.4	3.0	3.4	*	0.4	0.4
BACK	1.5	6.0	7.5				0.3	1.8	2.1	*	0.4	0.4
LF. SIDE	3.0	10.0	13.0				0.3	3.0	3.3	*	0.4	0.4
RT. SIDE	3.0	9.0	12.0				0.2	3.0	3.3	*	0.5	0.5
TOP	11.0	30.0	41.0				0.4	5.0	5.4	*	0.5	0.5
BOTTOM	4.0	10.0	14.0				0.3	4.0	4.3	*	0.5	0.5

RADIATION PROFILE FOR 3241-C IN PLASTIC TRANSPORT CASE (300 mCi)

LOCATION	SURFACE			10 cm.			30 cm.			1 Meter		
	Gamma	Neutron	Total	Gamma	Neutron	Total	Gamma	Neutron	Total	Gamma	Neutron	Total
FRONT	1.2	4.0	5.2				0.4	1.1	1.5	*	0.4	0.4
BACK	0.9	6.0	6.9				0.2	1.2	1.4	*	0.3	0.3
LF. SIDE	0.1	1.0	1.1				*	0.5	0.5	*	0.2	0.2
RT. SIDE	0.6	5.0	5.6				0.2	1.2	1.4	*	0.3	0.3
TOP	2.0	6.0	8.0				0.3	1.8	2.1	0.1	0.4	0.5
BOTTOM	0.6	4.0	4.6				0.2	1.5	1.7	*	0.4	0.4

1. All readings in mrem/h.
2. "*" indicates reading less than or equal to 0.1 mrem/h.
3. Measurements made with Nuclear Research Corp., Model NP-2 Survey Meter, Calibrated March 1989.
4. Dose Rates for 300 mCi americium-241:beryllium source

Figure 15
3241-C (300 mCi) Radiation Profile

SOURCE ENCAPSULATION

The source in the Model 3241-C meets regulatory requirements of U.S. and international authorities as "SPECIAL FORM," or encapsulated, sealed source material. The "sealed" sources are encapsulated to prevent leakage of the radioactive material and meet radiation safety requirements.

The neutron source (americium-241:beryllium) is compressed and welded inside stainless steel capsules.

The only radiological health concerns to Troxler instrument users are the photon and neutron emissions for moisture measurement. Proper use of this instrument (following the instructions in this manual) and the shielding design of the instrument will keep the exposure levels at a minimum under normal conditions. It is, however, required that personnel dosimetry be used when operating the 3241-C.

NOTE

APPENDIX B
3241-C SPECIFICATIONS

This appendix contains gauge and measurement specifications for the Model 3241-C Asphalt Content Gauge.

Contents:

MEASUREMENT SPECIFICATIONS B-2

RADIOLOGICAL SPECIFICATIONS B-3

ELECTRICAL SPECIFICATIONS B-4

MECHANICAL SPECIFICATIONS B-6

MEASUREMENT SPECIFICATIONS

Gauge Precision at 6% ASPHALT (one standard deviation)

100 mCi americium-241:beryllium

<u>1 Min.</u>	<u>4 Min.</u>	<u>8 Min.</u>	<u>16 Min.</u>
±0.084%	±0.042%	±0.029%	±0.021%

300 mCi americium-241:beryllium

<u>1 Min.</u>	<u>4 Min.</u>	<u>8 Min.</u>	<u>16 Min.</u>
±0.070%	±0.035%	±0.025%	±0.018%

NOTES:

- ◆ Range of control mix = 0 to 14% asphalt
- ◆ Gauge precision is calculated using the ASTM precision equation:

$$Precision = \frac{\sqrt{Count}}{slope}$$

Where:

Slope = slope of the calibration curve at a given % AC

Count = gauge count at a given % AC

RADIOLOGICAL SPECIFICATIONS

Neutron Source	3.7 \pm 0.37 GBq (100 \pm 10 mCi) Am-241:Be, <i>or</i> 11.1 \pm 1.11 GBq (300 \pm 30 mCi) Am-241:Be
Source Type	Sealed Source - Special Form
Source Housing	Stainless Steel, Double Encapsulated
Shielding	Polyethylene and Lead
Surface Dose Rate	See Radiation Profiles on pages A-9 and A-10
Shipping Case	DOT 7A, Type A

ELECTRICAL SPECIFICATIONS

Time Accuracy and Stability	$\pm 0.005\%$ $\pm 0.0002\%$ / °C
Power Supply Stability	$\pm 0.01\%$ / °C
Charge Source	110/220 VAC, 50-60 Hz / 12 VDC
Liquid Crystal Display	4 line x 16 character
Keypad	22 key sealed membrane
Power Consumption	0.2 watts average
RAM	8 kbytes non-volatile
ROM	64 kbytes
Max Test Data Storage	99 files
Max Calibration Storage	64 files
Serial Data Format:	8 Data Bits 2 Stop Bits No Parity

Gauge to PC Compatible Computer Cable (PN 104334.1000):

Gnd (pin 1)	-----	Gnd (pin 1)
Tx (pin 2)	-----	Rx (pin 3)
Rx (pin 3)	-----	Tx (pin 2)
DSR (pin 6)	-----	DTR (pin 20)
DTR (pin 20)	-----	DSR (pin 6)
Gnd (pin 7)	-----	Gnd (pin 7)

Gauge to WEIGH-TRONIX® Printer Cable (PN 104324.1000):

Gnd (pin 1)	-----	Gnd (pin 1)
Tx (pin 2)	-----	Rx (pin 2)
CTS (pin 5)	-----	DSR (pin 6)
DSR (pin 6)	-----	CTS (pin 5)
Gnd (pin 7)	-----	Gnd (pin 7)

MECHANICAL SPECIFICATIONS

Enclosure	Aluminum and Stainless Steel
Sample Chamber Size	14.75 x 11.0 x 10.5 in 375 x 279 x 267 mm
Console Size	8.6 x 11.0 x 3.5 in 219 x 279 x 90 mm
Weight	35 lbs 15.9 kgs
Shipping Weight	70 lbs 31.9 kgs
Operating Temperature Ambient	14 to 158 °F -10 to 70 °C
Sample Chamber Temperature (Maximum)	170 °F 77 °C
Storage Temperature	-70 to 185 °F -57 to 85 °C
Vibration Test	0.1 in (2.54 mm) at 12.5 Hz
Drop Test	300 mm onto 25 mm steel ball

This gauge contains sensitive electronic components and radioactive materials. This gauge must not be subjected to stress, abuse or operation other than in accordance with the standard operating procedures listed in this manual.

NOTES

APPENDIX C

TROUBLESHOOTING AND SERVICE

This appendix contains important information for troubleshooting and servicing the Model 3241-C Asphalt Content Gauge. The following procedures should be performed to keep the 3241-C in good working order. In the event that a serious problem with the gauge arises, contact the nearest Troxler Service Center or representative for instructions.

Contents:

TROUBLESHOOTING	C-2
LEAK TESTING	C-5
3241-C WITH RECHARGEABLE BATTERIES	C-6
REPLACEMENT PARTS	C-7
RETURNING A GAUGE FOR SERVICE	C-8
TROXLER SERVICE CENTERS	C-9

TROUBLESHOOTING

If any of the listed problems should arise, follow the procedure under the difficulty heading before contacting service personnel.

◆ GAUGE FAILS SELF TEST - ^3He tube error

- ✓ Make sure the sample chamber is empty! Test will fail if a sample is in the chamber.
- ✓ Check ^3He tube connections at the baseboard (open rear panel on sample chamber).
- ✓ Exchange high voltage module with good module. The high voltage module is located on the baseboard.
- ✓ The electrical connection between the sample chamber and the control unit may not be good. Check the cable with an ohm meter.
- ✓ Perform gauge initialization.

◆ GAUGE DOES NOT TURN "ON"

- ✓ With an ohm meter, check the fuse inside the control unit.
- ✓ Ensure AC adapter is supplying at least 12 VDC.
- ✓ Check wall outlet for 120 VAC.

◆ CONTROL UNIT DISPLAYS "Gauge Too Hot" ERROR

- ✓ Check for overheated condition.
- ✓ Check heat sensor connections to baseboard.
- ✓ Replace heat sensors. One is located above and one below the sample chamber.

◆ **CONTROL UNIT DISPLAYS TWO BLACK LINES OR "GARBAGE"**

- ✓ CPU board to display cable may not be making good connection. Open the control unit and reseat the cable.
- ✓ Check all chips and I.C.'s for proper seating in sockets.
- ✓ If the smartwatch is defective - replace (part no. 104620, chip designation U-12) Call customer service for assistance.

◆ **SOFTWARE IS NOT FUNCTIONING PROPERLY**

- ✓ Re-initialize the gauge. Contact customer service.

◆ **GAUGE APPEARS TO BE UNSTABLE**

- ✓ Perform a stability (stat) test (20 - 1 minute counts). Perform a drift test (5 - 4 minute counts).
- ✓ If the above tests pass, recheck the calibration parameters and samples.

◆ **GAUGE WILL NOT COMMUNICATE WITH PRINTER**

- ✓ Check the cable for continuity.
- ✓ Check baud rates.
- ✓ Check cable pin-out (see page B-4).
- ✓ Make sure all other parameters match:
 - Data bits = 8
 - Stop bits = 2
 - Parity = none
 - Protocol = DSR/DTR

◆ GAUGE READINGS ARE NOT ACCURATE

- ✓ Check the background count. If the counts have changed by more than 2%, check for other radiation sources or hydrogen bearing materials in the area.
- ✓ Perform (20 - 1 minute) stability (stat) test. If first test fails, repeat. Record all results.
- ✓ Perform drift test. If the gauge is unstable or drifts, replace the High Voltage Module with a good module.
- ✓ Enable the factory calibration in the "problem" gauge and in a good gauge (if available). Measure a sample in both gauges and compare the result. The % Asphalt Content (AC) readings should be similar if the gauge is functioning properly.

If only one gauge is available place a "sealed" sample in the gauge. Recall the calibration curve that corresponds to the sample. Measure the "sealed" sample and compare the results to the original calibration data. Ensure that the background count is current. Refer to Appendix E for preparing a "sealed" calibration sample.

- ✓ If software has recently been updated or the gauge has been re-initialized, the reference voltage may need to be reentered. Refer to the tag on the back of the gauge. Reenter the voltage even if the correct voltage is displayed.

LEAK TESTING

To ensure the integrity of the radioactive source encapsulation, the 3241-C must be leak tested at intervals not exceeding six months **unless otherwise indicated by your license**. Some countries may require leak testing be performed only by authorized, licensed institutions.

Each individual who leak tests the gauge is required to wear appropriate personnel monitoring during this duty.

Using the Troxler Model 3880 Leak Test Kit and accompanying instructions perform the following procedure:

- ✓ Write the Date, Gauge Model # and Serial # on the wipe disk.
- ✓ Open the sample chamber door and locate the round indentation on the inside top plate (centered between the two screw heads).
- ✓ Using the wipe disk, wipe the area around the indentation.
- ✓ Pack the disk, as instructed, in the envelope and mail to Troxler Electronic Laboratories, Inc. for analysis.
- ✓ Secure the gauge properly.

3241-C WITH RECHARGEABLE BATTERIES

If the user's Model 3241-C Asphalt Content gauge is equipped with rechargeable batteries follow the instructions below:

- ✓ Do Not Put Alkaline Batteries in the Model 3241-C Gauge!
- ✓ The batteries should be charged as often as possible. Unlike other gauges that use Ni-Cad batteries, the 3241-C batteries require continuous charging.

REPLACEMENT PARTS

<u>PART #</u>	<u>DESCRIPTION</u>
104410	AC Charger 12VDC 500MA
104155	AC Charger 13.6VDC 500MA(int'l)
104156	DC Charger (cig. lighter adapter)
104639	Power Module Assy.
104584	3241-C Cable Assy Scaler/Base
104544	3241-C Overlay (keypad)
012158	Latch Corbin (door lock)
104523	Latch Strike
012104	Foam Grip 3241-C (for handle)
100101.0100	Knob with Shaft (for handle)
105327	He-3 Tube Assembly
104095	900 VDC Helium Detector
105950	Assembly, CPU Board (3241X)
106797	3241-C Baseboard Assembly
105244	High Voltage PCB Assembly
016210.0025	Fuse, 3AG, ¼ Amp, Normal Blow
104620	Smartwatch w/ 8Kx8RAM
104588	Temperature Sensor Assy
104575	3241-C Operator's Ref. Manual
012177	Lock with 2 Keys (H-1209)

ACCESSORIES

105446	Cover, Asphalt Pan
012402	Pan Sample For Asphalt Content
021140	Radiation sign kit
102868	3880 Leak test kit w/ 4 Packets
102876.0005	Leak Test Packet (4 replacement)
102873	1 oz solution detergent
104340	Printer (Weigh-tronix)
104324.1000	Cable, (Weigh-tronix)Printer-to-Gauge (M/M)
104334.1000	Cable, PC-to-Gauge (FEM/MAL)
109661	Survey Meter

RETURNING THE GAUGE FOR SERVICE

All shipments to the factory must be accompanied by a RGA (Returned Goods Authorization) number. This will provide information to shipping and service personnel for expediting the repair work. Please call or fax the factory or branch office to obtain the RGA number.

Please have the following information available when calling:

- ◆ System model and serial number.
- ◆ Part number/serial number (if applicable).
- ◆ Is system still under warranty?
- ◆ Problem or difficulty you are having with the instrument.
- ◆ Shipment method to Troxler and for return shipment.
- ◆ Delivery address (not PO Box) - street address and zip.
- ◆ Phone number / contact (for questions from Troxler).
- ◆ Will estimate be required prior to performing any work on the system?
- ◆ Purchase Order Number. All Government Agencies (city, county, state and federal) must send purchase order numbers.

TO PREVENT ORDER DUPLICATION WHEN ORDERING BY TELEPHONE, PLEASE WRITE "CONFIRMING ORDER" ON FOLLOW-UP, WRITTEN REQUESTS.

RETURNING A 3241-C WILL REQUIRE SPECIAL HANDLING AND SHIPPING PROCEDURES, FOLLOW THE INSTRUCTIONS IN **APPENDIX D**. PLEASE CONTACT TROXLER WITH ANY QUESTIONS.

TROXLER SERVICE CENTERS

Troxler Corporate Headquarters

3008 Cornwallis Road
P.O. Box 12057
Research Triangle Park, NC 27709
Phone: 1.877.TROXLER (1.877.876.9537)
Outside the U.S.A.: +1.919.549.8661
Fax: +1.919.549.0761
Web: www.troxlerlabs.com

Technical Support

Phone: 1.877.TROXLER (1.877.876.9537)
E-mail: TroxTechSupport@troxlerlabs.com

Midwestern Branch Office

1430 Brook Drive
Downers Grove, IL 60515
Fax: 630.261.9341

Florida Service Center

2376 Forsyth Road
Orlando, FL 32807
Fax: 407.681.3188

Western Regional Branch Office

11300 Sanders Drive, Suite 7
Rancho Cordova, CA 95742
Fax: 916.631.0541

Troxler European Subsidiary

Troxler Electronics GmbH
Gilchinger Strasse 33
D.82239 Alling nr. Munich, Germany
Phone: ++49.8141.71063
Fax: ++49.8141.80731
E-mail: troxler@t-online.de

Southwestern Branch Office

2016 East Randol Mill Road
Suite 406
Arlington, TX 76011
Fax: 817.275.8562

NOTES

APPENDIX D

TRANSPORTATION AND SHIPPING

Devices containing radioactive materials must be transported in accordance with the rules of the U.S. Department of Transportation (DOT) and the International Atomic Energy Agency (IAEA). The IAEA recommendations have been codified in the International Air Transport Association (IATA) Dangerous Goods Regulations. International customers should consult their local government or licensing authority for applicable regulations.

Contents:

U.S. SHIPPING REQUIREMENTS	D-2
CANADIAN SHIPPING REQUIREMENTS	D-4

U.S. SHIPPING REQUIREMENTS

The U.S. DOT hazmat regulations (49 CFR, Parts 100–185) apply any time a nuclear device is transported by motor vehicle on a public highway or by other means of transport (rail, air, ship).

The major requirements for transporting a nuclear gauge in the United States are listed below. For more detailed information about these requirements, please refer to the *Troxler Transportation Guide*.

- ◆ A copy of the current IAEA Certificate of Competent Authority for each source in the gauge (Special Form Certificate) must be kept on file. Current versions can be downloaded from the Troxler website, www.troxlerlabs.com.
- ◆ A copy of the results of the "TYPE A" package testing must be on file.
- ◆ Hazmat employee training records must be kept on file.
- ◆ An "Emergency Response Information" document must be in the vehicle and immediately accessible to the driver.
- ◆ A properly completed "Bill of Lading" must be in the vehicle and immediately accessible to the driver. The shipping papers must include a 24-hour emergency response telephone number.
- ◆ If shipping by air, a "Shipper's Declaration for Dangerous Goods" must accompany the air waybill.
- ◆ The package must be properly marked and labeled in accordance with hazmat regulations.
- ◆ The package must have a tamper-evident seal.
- ◆ The package must be inspected prior to each shipment.
- ◆ The package must be securely blocked and braced in the vehicle to prevent shifting during transport.

ACCIDENT NOTIFICATION REQUIREMENTS

In the event of a reportable incident involving radioactive material, notify the licensing agency as soon as practical. The operator is also required to notify, at the earliest practical moment, the U.S. DOT at 1-800-424-8802 of an accident that occurs during the course of transportation (including loading, unloading, and temporary storage) in which fire, breakage, spillage, or suspected contamination occurs involving shipment of radioactive materials.

HAZMAT TRAINING

The U.S. DOT regulations require every hazmat employer to train, test, certify, and maintain records for each hazmat employee. Hazmat training applies to anyone who transports or prepares for transport radioactive materials. Refresher training is required every three years.

CANADIAN SHIPPING REQUIREMENTS

The *Transportation of Dangerous Goods Act and Regulations* (TDG) and *Transport Packaging of Radioactive Materials Regulations* (TPRM) apply any time a nuclear device used in commerce is transported by any means in Canada.

For training and accident notification requirements, consult the *Transportation Of Dangerous Goods Regulations*. For further information on transporting a nuclear device, contact the transportation section of the Canadian Nuclear Safety Commission (CNSC).

APPENDIX E

SPECIAL CALIBRATION SAMPLES

This appendix contains information on preparing special calibration samples.

Contents:

SEALED ASPHALT SAMPLES	E-2
------------------------------	-----

SEALED ASPHALT SAMPLES

To prepare *sealed asphalt samples* follow the procedure below:

- ✓ Fill the sample pan to within 0.25 inches of the top. Refer to Chapter 4 for preparing calibration samples.
- ✓ Apply a bead of "siliconized acrylic latex caulk" around the edge of the asphalt sample pan.
- ✓ Place the 0.032 in (1 mm) aluminum cover plate down on top of the caulking. Gently press down to seal the sample.
- ✓ Spread a bead of caulk around the edge of the pan on top of the plate.
- ✓ Inspect the sample and seal any visible gaps, cracks or holes.




Figure 20
Sealed Asphalt Sample

NOTES

APPENDIX F

3241-C CALIBRATION FORMS

This appendix contains forms for use during calibration sample preparation.

Contents:

MIXING FORMS F-3

CALIBRATION FORMS F-6

NOTES

CALIBRATION TEST RECORD

GAUGE MODEL _____ SERIAL NO. _____ DATE _____ REF _____
 PROJECT _____ LOCATION _____

Aggregate:

SOURCE	SIZE	AMOUNT

Asphalt:

SOURCE	TYPE	GRADE

Background Count _____

**Figure 21
Mixing Forms**

		Calibration Coefficients
A1 =		
A2 =		
A3 =		

		Blank Sample
1	Empty Pan Weight	
2	Weight of Pan + Aggr	
3	Blank Smpl Wt. (2-1)	

	Pan 1	Pan 2	Pan 3	Pan 4	Pan 5	Pan 6
A	Desired AC %					
B	Mixing bowl Weight					
C	Dry Aggregate Weight					
D	Subtotal (B+C)					
E	Total Design Weight					
F	Total Actual Weight					
G	Actual AC %					
H	Calib. Pan Weight					
J	Aggr + Asphalt Weight					
K	Gross Weight (H+J)					
L	Asphalt Content (%AC)					
M	Counts (MC)					

Calibration Data Sheet

NUCLEAR ASPHALT CONTENT GAUGE w/ PAN METHOD

Calib. # _____

Date: _____

Mix Type: _____

Mix ID: _____

Project: _____

Background (16 minutes): _____						
Aggregate Only Sample Count (16 minutes): _____						
16 MIN.CNTS	1	2	3	4	5	CHECK
% AC						
COUNT:						

Pan						
Weight						

Fit Coeff: _____	
A1:	Diff 1:
A2:	Diff 2:
A3:	Diff 3:
	Diff 4:
	Diff 5:

TROXLER ELECTRONIC LABORATORIES, INC.

F.O. Box 12257, R.T.P., N.C. 27709

Figure 22
Calibration Form

NOTES

INDEX

A

AASHTO standard	4-1
Access code	vii
Accessories	1-4, C-7
Accidental Erasure	7-7
Activity, source	B-3
Adapter, power	1-5, C-7
Air, shipping	D-2
Americium-241:Beryllium	A-11
ASTM standard	4-1
Atomic structure	A-2
Auto-Print	6-7
Auto-Store	6-7

B

Background count	3-8
Batteries	C-6
Baud rate	7-16

C

Calculator	6-10
Calibration	4-1
Equipment	4-2
Form	F-7
Offset	6-2
Performing	4-9
Sample mixing	4-6
Sample preparation	4-3, 4-5
Transfer	7-14
Code, access	vii
Computer	5-5
Count time	3-4
Counts, viewing	5-3, 6-9
Curie	A-3
Customer name	3-6

D

Data

Auto-Print	6-7
Auto-Store	6-7
Erase	5-6, 6-8
Print	5-5
Store	5-4
Date, changing	3-5
Detectors	2-2, C-7
Dosimetry	A-4, A-11
Drift test	7-5

E

Electrical specifications	B-4
Encapsulation	A-11
Erase	
Calibration	6-8
Project	5-6
Recover	7-7
Erase function	6-8

F

Filling, sample	4-8
Form	
Calibration	F-7
Mixing	F-4
Functions	
Shift	6-1
Special	7-1

G

Gauge weight	B-6
--------------------	-----

H

High voltage	C-7
Hydrogen	2-2

I

Incorrect readings	C-3
Interface	
Computer	7-16, B-4
Printer	7-16, B-4
International shipping	D-2

L

Leak testing	C-5
Limits	
Drift test	7-5
Stat test	7-2

M

mCi	A-3
Measurement	
Auto-Print	6-7
Auto-Store	6-7
Erase	5-6, 6-8
Incorrect	C-3
Print	5-5
Recall	6-9
Sample preparation	3-9
Specifications	B-2
Store	5-4
Taking	3-10
Mechanical specifications	B-6
Memory	B-4
Mixing	
Form	F-3
Sample	4-6

N

Name, customer	3-6
Number, maximum	
Calibration files	B-4
Test data files	B-4

O

Offset calibration	6-2
Operating	
General	3-1
Temperature	B-6
Theory	2-1
Optional equipment	1-5, C-7

P

Pan	
Sample	C-7
Sealed sample	E-2
Weight display	7-18
Parameter set up	3-4
Parts	
Gauge	1-4
Replacement	C-7
Precision	3-4
Target	6-9
Print function	5-5
Print out	
Drift test	7-6
Stat test	7-4
Printer, optional	1-5, C-7
Project function	5-2

Q

Quantity, source	B-3
------------------------	-----

R

Rad	A-3
Radiation	
Safety	A-6
Statistics	A-4
Terminology	A-3
Theory	A-2, A-3
Types	A-6
Radiation Profile	
100 mCi	A-9
300 mCi	A-10

Radiological specifications	B-3
RAM	B-4
Reading, taking a	3-10
Recall function	6-9
Recove erase	7-7
Rem	A-3
Replacement parts	C-7
Requirements, shipping	D-1
Returning for service	C-8
Reviewing Data	5-3
ROM	B-4

S

Sample

Blank	4-3
Calibration	4-5
Filling	4-8
Mixing	4-6
Preparation	3-9

Sample pans	1-5
--------------------------	------------

Samples

Pan	C-7
Sealed	E-1

Sealed sample pans	E-2
---------------------------------	------------

Self test	3-3
------------------------	------------

Serial port	7-16
--------------------------	-------------

Service	C-1, C-8
----------------------	-----------------

Centers	C-9
----------------------	------------

Set up, gauge	3-4
----------------------------	------------

Shift functions	6-1
------------------------------	------------

Shippers Declaration of Dangerous Goods	D-2
--	------------

Shipping	D-1
-----------------------	------------

Air	D-2
------------------	------------

International	D-2
----------------------------	------------

Requirements	D-1
---------------------------	------------

Site selection	1-7
-----------------------------	------------

Size, gauge	B-6
--------------------------	------------

Source	B-3
---------------------	------------

Source activity	B-3
Special functions	7-1
SpecificationsB-1	
Electrical	B-4
Measurement	B-2
Mechanical	B-6
Radiological	B-3
Standards	
AASHTO	4-1
ASTM	4-1
Stat test	7-2
Status function	6-2
Store	
Function	5-4
Neasurements	6-7

T

Target precision	6-9
Temperature, operating	B-6
Testing	3-10
Testing, leak	C-5
Theory, operational	2-1
Time function	3-4
Time	
Changing	3-5
Count	3-4
TLD	A-4
Training, Hazmat	D-3
Transfer calibration	7-14
Transportation	D-1
Troubleshooting	C-2

U, V, W

Upacking and inspection	1-6
Upload Data to a Computer	5-5
Weight, gauge	B-6

NOTES

TROXLER ELECTRONIC LABORATORIES, INC.

LIMITED WARRANTY

TROXLER ELECTRONIC LABORATORIES, INC., and subsidiary, TROXLER INTERNATIONAL, LTD., hereinafter referred to as "TROXLER," warrants this Model 3241-C Asphalt Content Gauge, Serial Number _____, against defects in material and workmanship for a period of twelve (12) months from date of shipment. For gauges sold through authorized TROXLER representatives, the date of shipment will be as of the transfer from representative to purchaser. During the applicable warranty period, TROXLER's obligation under this warranty shall be limited exclusively to the repair at no charge, except for shipping to and from TROXLER'S plant, of any instrument which may prove defective under normal use and which TROXLER's examination shall disclose to its satisfaction to be thus defective. Normal use is defined for the purpose of this warranty as operation under normal load, usage, and conditions with proper care and maintenance and competent supervision. In no event shall TROXLER be held liable for damages, delays, or losses consequential, incidental, or otherwise attributable to the failure of this instrument or radioactive material contained therein. TROXLER's liability being specifically limited to repair as stated hereinabove. This warranty is automatically initiated except where modified by contractual or other written and signed agreement.

THERE ARE NO WARRANTIES WHICH EXTEND BEYOND THE DESCRIPTION ON THE FACE HEREOF, AND THIS WARRANTY IS EXPRESSLY IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED, AND TROXLER NEITHER ASSUMES, NOR AUTHORIZES ANYONE TO ASSUME FOR IT ANY OTHER LIABILITY IN CONNECTION WITH THE SALE OF THE INSTRUMENT. THIS WARRANTY SHALL NOT APPLY TO THE INSTRUMENT OR ANY PART THEREOF, WHICH HAS BEEN SUBJECTED TO DAMAGE BY ACCIDENT, NEGLIGENCE, ALTERATION, ABUSE, MISUSE, OR SERVICE NOT AUTHORIZED IN WRITING BY TROXLER. SUCH DAMAGE TO INCLUDE BUT NOT BE LIMITED TO BURNING OF CIRCUIT BOARDS AND HARNESS FROM IMPROPER SOLDERING TECHNIQUES AND DAMAGE TO THE INSTRUMENT DUE TO PURCHASER'S FAILURE TO PERFORM MAINTENANCE AS OUTLINED IN THE AUTHORIZED OPERATOR'S MANUAL. DUE TO THE NATURE OF THEIR USE, MECHANICAL ACCESSORY PARTS AND BATTERIES ARE WARRANTED FOR 90 DAYS ONLY FROM DATE OF SHIPMENT.

TROXLER ELECTRONIC LABORATORIES, INC.

Troxler International, Ltd.

Troxler Electronics (Canada), Ltd.

3008 Cornwallis Road

Post Office Box 12057

Research Triangle Park, NC 27709 USA

NOTICE TO CONSUMERS

Any disclaimer or limitation on the remedies expressed above shall not be effective to the extent prohibited by state or federal law.

NOTE: THIS WARRANTY EXCLUDES DAMAGE INCURRED IN SHIPMENT. IF THIS INSTRUMENT IS RECEIVED IN DAMAGED CONDITION, THE CARRIER SHOULD BE CONTACTED IMMEDIATELY. ALL CLAIMS FOR DAMAGE IN TRANSIT SHOULD BE FILED WITH THE CARRIER. IF REQUESTED, TROXLER WILL AID IN FILING OF CLAIMS AND/OR LOCATING GAUGES LOST IN TRANSIT.