

Power Calculation (to select suitable transformer)

Sensors :

Sensors	Current (A)	Voltage (V)	P = VI (W)
IR x 3	0.02	5	$0.02 \times 5 \times 3 = 0.3$
Ultrasonic x 3	0.015	5	$0.015 \times 5 \times 3 = 0.225$
inductive	0.02	10	$0.2 \times 10 = 0.2$
keypad	0.03	5	$0.03 \times 5 = 0.15$
Lcd	0.0025	5	$0.0025 \times 5 = 0.0125$
Total	0.158		0.8825 W

Motors :

Motor	Current (A)	Voltage (V)	P = VI
Stepper x 4	1.5	12	$12 \times 1.5 \times 4 = 72$
DC x 3	1.5	12	$12 \times 1.5 \times 3 = 54$
Total	3		126 W

- If we assume that all the sensors work together, then we need total power of 0.8825W. (approximately 1W) .Since these all the sensors are not working together we need a power less than 1W and we can **get maximum power needed for sensors as 1W** and it is a very small value when comparing to the motors.
- If we assume that all the 7 motors are working together, then we need 126W power. But according to our machine ,maximum 4 motors are working together at a time. So, we **need maximum power of 72W ($12 \times 1.5 \times 4$) for motors.**
- So, maximum power we need for this machine = $1W + 72W = 73 W$
- After assuming that transformer has 20% loss ,
$$P = 73 \times 120/100$$
$$= 87.6 W$$
- So we need a transformer which can generate 90W power for this project.