



Aalto University
School of Electrical
Engineering

Lecture 10: Field-Oriented Control

ELEC-E8405 Electric Drives (5 ECTS)

Mikko Routimo (lecturer), Marko Hinkkanen (slides)

Autumn 2017

Learning Outcomes

After this lecture and exercises you will be able to:

- ▶ Explain the basic principles of field-oriented control of a permanent-magnet synchronous motor
- ▶ Draw and explain the block diagram of field-oriented control
- ▶ Calculate the operating points of the motor in rotor coordinates


Outline

3-Phase Inverter



Field-Oriented Control

Current and Voltage Limits


3-Phase Inverter



DC-DC Converter vs. 3-Phase Inverter



Space Vector of the Converter Output Voltages



- ▶ Zero-sequence voltage does not affect the phase currents
- ▶ Reference potential of the phase voltages can be freely chosen

$$\underline{u}_s^s = \frac{2}{3} \left(u_{an} + u_{bn} e^{j2\pi/3} + u_{cn} e^{j4\pi/3} \right) \quad \text{Neutral } \mathbf{n} \text{ as a reference}$$
$$= \frac{2}{3} \left(u_{aN} + u_{bN} e^{j2\pi/3} + u_{cN} e^{j4\pi/3} \right) \quad \text{Negative DC bus } \mathbf{N} \text{ as a reference}$$


► Converter output voltage vector

$$\begin{aligned}\underline{u}_s^s &= \frac{2}{3} \left(u_{aN} + u_{bN}e^{j2\pi/3} + u_{cN}e^{j4\pi/3} \right) \\ &= \frac{2}{3} \left(q_a + q_b e^{j2\pi/3} + q_c e^{j4\pi/3} \right) U_{dc}\end{aligned}$$

where q_{abc} are the switching states (either 0 or 1)

► Vector (1, 0, 0) as an example

$$\underline{u}_s^s = \frac{2U_{dc}}{3}$$



Switching-Cycle Averaged Voltage

- ▶ Using PWM, any voltage vector inside the voltage hexagon can be produced in average over the switching period

$$\underline{\bar{u}}_s^s = \frac{2}{3} \left(d_a + d_b e^{j2\pi/3} + d_c e^{j4\pi/3} \right) U_{dc}$$

where d_{abc} are the duty ratios (between 0...1)

- ▶ Maximum magnitude of the voltage vector is $u_{\max} = U_{dc}/\sqrt{3}$ in linear modulation (the circle inside the hexagon)
- ▶ PWM can be implemented using the carrier comparison
- ▶ Only switching-cycle averaged quantities will be needed in the following (overlining will be omitted for simplicity)

Outline


3-Phase Inverter

Field-Oriented Control

Current and Voltage Limits

Permanent-Magnet Synchronous Motor

- ▶ Current distribution produced by the 3-phase winding is illustrated in the figure
- ▶ Torque is constant only if the supply frequency equals the electrical rotor speed
 $\omega_m = d\vartheta_m/dt$
- ▶ For controlling the torque, the current distribution has to be properly placed in relation to the rotor
- ▶ Rotor position has to be measured (or estimated)



Field-Oriented Control

- ▶ Resembles cascaded control of DC motors
- ▶ Automatically synchronises the supply frequency with the rotating rotor field
- ▶ Torque can be controlled simply via i_q in rotor coordinates
- ▶ Field-oriented control of other AC motors is quite similar to that of a surface-mounted permanent-magnet synchronous motor considered in these lectures

Synchronous Motor Model in Rotor Coordinates

- ▶ Stator voltage

$$\underline{u}_s = R_s \underline{i}_s + \frac{d\underline{\psi}_s}{dt} + j\omega_m \underline{\psi}_s$$

- ▶ Stator flux linkage

$$\underline{\psi}_s = L_s \underline{i}_s + \underline{\psi}_f$$

- ▶ Torque is proportional to the q component of the current

$$T_M = \frac{3p}{2} \operatorname{Im} \left\{ \underline{i}_s \underline{\psi}_s^* \right\} = \frac{3p}{2} \psi_f i_q$$

Space-Vector and Coordinate Transformations


- ▶ Space-vector transformation (abc/ $\alpha\beta$)

$$\underline{i}_s^s = \frac{2}{3} \left(i_a + i_b e^{j2\pi/3} + i_c e^{j4\pi/3} \right)$$


- ▶ Transformation to rotor coordinates ($\alpha\beta$ /dq)

$$\underline{i}_s = \underline{i}_s^s e^{-j\vartheta_m}$$

- ▶ Combination of these two transformations is often referred to as an abc/dq transformation
- ▶ Similarly, the inverse transformation is referred to as a dq/abc transformation




Fast Current Controller in Rotor Coordinates






- ▶ Absolute rotor position ϑ_M has to be measured (or estimated)
- ▶ Current reference $\underline{i}_{s,ref} = i_{d,ref} + j i_{q,ref}$ is calculated in rotor coordinates

The current controller could consist, for example, of two similar real-valued PI-type controllers (one for i_d and another for i_q).

Field-Oriented Controller



- ▶ Control principle $i_{d,ref} = 0$ minimises the resistive losses
- ▶ Speed controller is not needed in some applications



Outline

3-Phase Inverter

Field-Oriented Control

Current and Voltage Limits


Stator Voltage

- ▶ In steady state, $d/dt = 0$ holds in rotor coordinates
- ▶ Steady-state stator voltage


$$\begin{aligned}\underline{u}_s &= j\omega_m \underline{\psi}_s \\ &= j\omega_m (L_s \underline{i}_s + \psi_f) \\ &= j\omega_m (L_s i_d + \psi_f + jL_s i_q)\end{aligned}$$

when $R_s = 0$ is assumed


- ▶ Voltage increases with the speed
- ▶ Maximum voltage magnitude u_{\max} is limited by the DC-bus voltage U_{dc}



Field Weakening Above the Base Speed



Below the base speed: $i_d = 0$



Above the base speed: $i_d < 0$
in order to reduce $|\underline{\psi}_s|$


Current Limit

- ▶ Current limit

$$i_s^2 = i_d^2 + i_q^2 \leq i_{\max}^2$$

- ▶ Example figure

- ▶ Rated motor current i_N
- ▶ Maximum converter current is assumed to be $1.5i_N$
- ▶ Motor tolerates short-time overload currents due to its longer thermal time constant



Voltage Limit


- Voltage limit

$$u_s^2 = \omega_m^2 \psi_s^2 \leq u_{\max}^2$$

can be represented as a
speed-dependent stator-flux limit

$$\psi_s^2 = (L_s i_d + \psi_f)^2 + (L_s i_q)^2 \leq \frac{u_{\max}^2}{\omega_m^2}$$

- Example figure: current loci at two different speeds as the torque varies



Summary of Control Principles

- ▶ Control principle below the base speed

$$i_{d,\text{ref}} = 0 \quad \text{and} \quad i_{q,\text{ref}} = \frac{2T_{M,\text{ref}}}{3p\psi_f}$$

- ▶ Field weakening ($i_d < 0$) can be used to reach higher speeds
 - ▶ Nonzero i_d causes losses $(3/2)R_s i_d^2$
 - ▶ Risk of overvoltages if the current control is lost
 - ▶ Risk of demagnetizing the permanent magnets in some machines
- ▶ Current and voltage limits have to be taken into account