

### **Control Limits for Control Charts**

Process Mean	Control limits = $\bar{\bar{X}} \pm 3 \frac{\bar{s}}{c_4 \sqrt{n}}$
Process Standard Deviation	Control limits = $\bar{s} \pm 3 \frac{c_5 \bar{s}}{c_4}$
Process Range	Lower control limit = $\bar{R}D_3$ Upper control limit = $\bar{R}D_4$

### **Process Capability Indices**

	Population Known	Population Unknown
<b><i>C<sub>p</sub></i></b>	$C_p = \frac{USL - LSL}{6\sigma}$	$\hat{C}_p = \frac{USL - LSL}{6s}$
<b><i>C<sub>pk</sub></i></b>	$C_{pk} = \min \left[ \frac{USL - \mu}{3\sigma}, \frac{\mu - LSL}{3\sigma} \right]$	$\hat{C}_{pk} = \min \left[ \frac{USL - \bar{x}}{3s}, \frac{\bar{x} - LSL}{3s} \right]$
<b><i>C<sub>pm</sub></i></b>	$C_{pm} = \frac{USL - LSL}{6\sqrt{\sigma^2 + (\mu - T)^2}}$	$\hat{C}_{pm} = \frac{USL - LSL}{6\sqrt{s^2 + (\bar{x} - T)^2}}$

### **Question 1A (Theory Questions)**

1. Differentiate common (or chance) causes of variation in the quality of process output from assignable (or special) causes.
2. Differentiate a stable process from an unstable process.
3. Other than applying the 3-sigma rule for detecting the presence of an assignable cause, what else do we look for when studying a control chart?
4. Describe how the output of a stable process can be improved. What actions do not improve a stable process, but rather, make the output more variable?
5. What is the purpose of maintaining control charts?
6. What is tampering in the context of process control?

### **Question 1b**

. A normally distributed quality characteristic is monitored through the use of an  $\bar{X}$ /R chart. These charts have the following parameters. Both charts are in control.

	LCL	Centre Line	UCL
$\bar{X}$ -Chart:	614.0	620.0	626.0
R-Chart:	0	8.236	18.795

- (i) What sample size is being used?
- (ii) Estimate the standard deviation of the process.
- (iii) Compute the control limits for the process standard deviation chart.


### **Question 2**

For the following x.bar chart, compute the control limits given that the following information

Number of groups = 25  
Center = 33.5944  
StdDev = 2.184007

Sample size =5

Comment on the chart, with reference to two separate tests. Is the process on control?




### Question 3A

Suppose the specifications for the process state that the Lower and Upper Specification Levels are 25 and 40 respectively.

Determine the Process Capability Indices ***C<sub>p</sub>*** and ***C<sub>pk</sub>*** , commenting on the respective values.

Comment on the graphical output of the Process Capability Analysis.



- (c) Is the process capable? Give reasons. 4
- (d) Calculate the ARL i.e. average run length for a change of + 0.5 mm in the average. In words give a practical interpretation of the ARL. 4
- (e) What is a CUSUM chart? What type of departures from the production target value is this type of chart useful for detecting? Explain how it works. 4

### **Question 3B**

Suppose the specifications for the process state that the Lower and Upper Specification Levels are 30 and 36 respectively. Again determine the Process Capability Indices ***C<sub>p</sub>*** and ***C<sub>pk</sub>***, commenting on the respective values.

Comment on the graphical output of the Process Capability Analysis.

