

---

# EE564 First Project: Transformer Design a for X-Ray Device

## Table of Contents

ID .....	1
Specifications .....	1
Choosing Initial Material .....	2
Choosing Operation Flux Density .....	3
Determination of Core Dimensions & Number of turns .....	3
Determination of Core and Copper Losses .....	3
Determination of Operating Temperature .....	3
Determination of mass, cost etc. ....	3

## ID

**NAME :** Mehmet Kaan Mutlu

**STUDENT NUMBER :** 2121408

**E-mail :** [kaan.mutlu@metu.edu.tr](mailto:kaan.mutlu@metu.edu.tr)

`function []=meka_mutlu_XRAY()`

## Specifications

- **Single Phase, High Frequency High Voltage Transformer**
- **Primary Winding Voltage:**  $\pm 417$  V (peak to peak 834 V for pulsing)
- **Secondary Winding Voltage:**  $\pm 12.5$  kV (peak to peak 25 kV for pulsing)
- **Rated Power:** 30 kW (for maximum 100 millisecond)
- **Switching Frequency:** Minimum 100 kHz
- **Ambient Temperature:** 0-40 °C


```
Prated      = 30e3;  
fs          = 100e3;  
  
Vp_peak     = 417;  
Vp_fund_peak= Vp_peak*4/pi;  
Vp_f_rms    = Vp_fund_peak/sqrt(2);  
  
Vs_peak     = 12.5e3;  
Vs_fund_peak= Vs_peak*4/pi;  
Vs_f_rms    = Vs_fund_peak/sqrt(2);
```

$$\begin{aligned} I_{p\_rms} &= P_{rated}/V_{p\_f\_rms}; \\ I_{s\_rms} &= P_{rated}/V_{s\_f\_rms}; \end{aligned}$$

## Choosing Initial Material

First step of transformer design is selecting an appropriate core material. After some researches on internet and company application guides, it is decided to use a ferrite material for XRAY transformer application at 100kHz switching frequency.

After this decision, Magnetics' ferrite catalog is read and different types of materials are compared. In that comparison, power losses of materials at 25°C and 100kHz is used as basic elimination parameter and it is decided to use T material. It is possible to find its parameters below:



## Choosing Operation Flux Density

For the second phase of design, it is going to be chosen operation flux density. The material's saturation flux density is 470mT for this project's defined temperature range. Our value should be smaller than saturation point. But how much? Let's consider over the formula below:

$$e = -\frac{2\pi}{\sqrt{2}} N 2\pi f B_{peak} * A$$

If only selectable parameters are considered, it is possible to see the trade-off between number of turns, flux density and area. Selecting high number of turns come with difficulties of cabling and copper losses. Cable size is decided over current values so it is constant in this discussion. Area is important for transformer's size and weight values. It also effects cable length and core loss (over weight). Flux density is directly related with core losses.

As B is increased, core loss is increased (nonlinearly). If we take BxA value constant, then increasing B will decrease A and therefore volume and weight will be less and it means less core loss. So here, by assuming area and weight are proportional, an optimization will be made over core loss.

## Determination of Core Dimensions & Number of turns

Comments

## Determination of Core and Copper Losses

Comments

## Determination of Operating Temperature

Comments

## Determination of mass, cost etc.

Comments

end

*Published with MATLAB® R2013a*