

Tesla Model S Induction Motor

RWD 85 Model

Hüseyin YÜRÜK

Table of Contents

1. Introduction	1
2. Main Dimensions of Stator Core	2
3. The Stator Winding	4
4. Stator Slot Sizing	6
5. Rotor Slots	8
6. The Magnetizing Current	10
7. Resistance and Inductances	11
8. Losses and Efficiency	12
9. Operation Characteristics	14
10. Temperature Rise	15
11. Motor Analysis	16

Chapter 1. Introduction

The specs of the induction motor are as follows:

```
% Input Parameters of the
% Tesla Model S Induction Motor
power_max = 270;           % [kW] from project2
torque_max = 440;          % [Nm] from project2
speed_max = 225;           % [km/sa] from project2
m = 3;                     % [-] three phases
p1 = 2;                    % [-] pole pair from Hendershot-FIU-Lecture
power Rated = 288 * 0.746 ; % [kW] from Hendershot-FIU-Lecture
tire_diameter = 27.7 * 25.4; % [mm] from
                             % https://tiresize.com/tires/Tesla/Model-S/
                             % https://tiresize.com/tiresizes/245-45R19.htm
gear = 9.73;               % [-] 9.73:1 (transmission) from
                             % https://en.wikipedia.org/wiki/Tesla_Model_S
speed_rpm_max = (speed_max*10^3/3600)/(tire_diameter*10^-3/2)*(60/2*pi())*gear;
                             % [rpm]
speed_rpm Rated = 6000;    % [rpm] from Hendershot-FIU-Lecture
                             % approx. knee of the torque-speed curve
f1 = speed_rpm Rated*2*p1/120; % [Hz] frequency of the driver unit
Vd = 400;                  % [V] nominal bus voltage 85kWh from
                             % http://teslatap.com/undocumented/
u0 = 4*pi*10^-7;           % [-]

input parameters are given above.
calculated values from the input parameters given below
maximum speed of the rotor 1.6292e+05rpm
frequency of the driver 200Hz
```

Chapter 2. Main Dimensions of Stator Core

```
Dis^2 * L output constant concept is used to determine parameters.

% Based on the The Induction Machine Handbook Chapter 14 & 15
neff = 0.96; % [-] targetted efficiency (IE3)
pwr_factor = 0.88; % [-] typ. power factor for induction motors
% at full load varies between 0.85-0.90
Ke = 0.98 - 0.005*p1; % [-] Ke defined as  $E_1 / V_{1n}$  (eq. 14.8)
% and approx. given as eq. 14.10
Sgap = Ke * powerRated * 10^3 / (neff * pwr_factor); % [VA] (eq. 15.2)
stack_aspect = 1.25; % [-] stack aspect ratio define as
% stack length to pole pitch ratio (eq. 14.19)
% (table 15.1)
Co = 250*10^3; % [J/m^3] extracted from figure 14.14
Dis = ((2*p1*p1*Sgap)/(pi()*stack_aspect*f1*Co))^(1/3); % [m] (eq. 15.1)
pole_pitch = pi()*Dis/(2*p1); % [m] pole pitch (eq. 15.2)
L = stack_aspect * pole_pitch; % [m] stack length (eq. 15.2)
Ftan_max = torque_max / (Dis/2); % [N] tangential force
Sr = pi()*Dis*L; % [m^2] surface area
shear_stress_max = Ftan_max / Sr; % [N/m^2], [Pascal] tangential shear stress
Cmech = power_max / (Dis^2*L*f1/p1); % [kWs/m^3] specific machine constant
max_stator_num = round(pi()*Dis/0.007); % [-] max. stator number from
% ee564_basic_machine_design2, 8/23
min_stator_num = ceil(pi()*Dis/0.045); % [-] min. stator number
Kd = 0.63; % [-] for 2p1 pole number (Table 15.2)
Dout = Dis / Kd; % [m] outer diameter of the stator (eq. 15.4)
g1 = 0.1+0.012*(powerRated*10^3)^(1/3); % [mm] airgap (eq. 15.5)
g2 = 0.18+0.006*(powerRated*10^3)^(0.4); % [mm] airgap from
% ee564_basic_machine_design 16/18

if (g1 > g2)
    g = g1;
else
    g = g2;
end;
g = g * 1.2; % [mm] to add safety factor
```

```
main dimensions of the stator are calculated as above
air gap Sgap = 2.4669e+05 [VA]
inner diameter of stator Dis = 0.2158 [m]
pole pitch = 0.1695 [m]
stack length L = 0.2119 [m]
tangential force Ftan = 4.0777e+03 [N]
tangential shear stress 2.8387e+04 [N/m^2]
specific machine constant Cmech = 273.6243 [kWs/m^3]
maximum stator number 97
minimum stator number 16
outer diameter of the stator Dout = 0.3426 [m]
```

air gap $g = 1.1937$ [mm] with safety factor

Chapter 3. The Stator Winding

```
% Based on the The Induction Machine Handbook Chapter 14 & 15
Ns = 2*p1*m*4;           % [-] number of stator slots
q = Ns/(2*p1*m);         % [-] slots per pole per phase
pitch_factor = 5/6;      % [-] to minimize 5th and 7th harmonics
pitch_angle = 5/6*180;   % [°] pitch angle
slot_angle_alpha = 180/(Ns/(2*p1)); % [°] slot angle (eq. 15.7)
Kp1 = sind(pitch_angle/2); % [-] fundamental pitch factor (eq. 15.9)
Kd1 = sind(q*slot_angle_alpha/2)/(q*sind(slot_angle_alpha/2));
                        % [-] fundamental distribution factor (eq. 15.8)
Kw1 = Kp1*Kd1;           % [-] fundamental winding factor
Bg = 0.65;               % [Tesla] (e.q. 15.11)
Kst = 0.4;                % [-] so 1+Kst = 1.4
den_shape = 0.729;        % [-] density shape factor fig.14.13, where 1+Kst=1.4
Kf = 1.085;               % [-] form factor fig.14.13
flux_airgap = den_shape*pole_pitch*L*Bg; % [Wb] airgap flux (eq. 15.10)
Vph_rms = 4/pi()*Vd/2*(1/sqrt(2)); % [V] (eq. 8.56 Mohan) rms phase voltage
N_per_ph = Ke*Vph_rms/(4*Kf*Kw1*f1*flux_airgap); % [turns/phase] (eq. 15.12)
a1 = 1;                   % [-] the number of current path in parallel
ns = a1*N_per_ph/(p1*q); % [*] the number of conductors per slot
% to get even number conductors because of double layer winding
if ns<=2
    ns = 2;
else
    ns = ceil(ns);
    if 1 == mod(ns,2)
        ns = ns +1;
    end
end
N_per_ph_req = p1*q*ns; % [turns/phase] required turns/phase
Bg_req = Bg * N_per_ph/N_per_ph_req; % [Tesla] required Bg
Vll_rms = Vph_rms * sqrt(3); % [V] line-line rms voltage
IphRated_rms = powerRated*10^3/(neff*pwr_factor*sqrt(3)*Vll_rms);
                        % [A] rated phase current (eq. 15.16)
Jcos = 5.5;            % [A/mm^2] current density for 2p1=2,4 (eq. 15.17)
Aco = IphRated_rms/(Jcos*a1); % [mm^2] stator wire cross section
dco = sqrt(4*Aco/pi); % [mm] wire gauge diameter (eq. 15.19)
ap = 4;                % [-] number of conductor in parallel
dcop = sqrt(4*Aco/(pi*ap)); % [mm] wire gauge diameter (eq. 15.20)
dcop_sta = 5.189;      % [mm] AWG4 size is chosen by regarding above value
```

The number of stator slots (N_s) should be multiple of 12.
By referring the suggested stator slot pitch for induction machines (7-45mm), N_s should be between 16-97.
Let's choose N_s as 48.
To reduce harmonic frequency components let's use fractional pitch.
5/6 fraction is used to reduce 5th and 7th harmonics.
Note that
5/6 pitch will
minimize the 5th harmonic but not eliminate it as will 4/5 pitch

minimize the 7th harmonic but not eliminate it as will 6/7 pitch

slots per pole per phase is 4

fundamental pitch factor $k_{p1} = 0.9659$

fundamental distribution factor $k_{d1} = 0.9577$

fundamental winding factor $k_{w1} = 0.9250$

airgap flux 0.0170 [weber]

phase voltage rms 180.0633 [V]

number of conductors per slot $n_s = 2$

number of turns per phase 16

air gap flux density $B_g = 0.5193$ [Tesla]

rated phase current $I_{ph} = 470.7941$ [A]

stator wire cross section $A_{co} = 85.5989$ [mm²]

AWG4 size is selected

Chapter 4. Stator Slot Sizing




Figure 15.4 Recommended stator slot shapes




Figure 15.5 Stator slot geometry

```
% Based on the The Induction Machine Handbook Chapter 14 & 15
% stator slot sizing will be determined
Kfill = 0.44; % [-] slot fill factor for above 10kW
Asu = pi*dcop^2*ap*ns/(4*Kfill); % [mm^2] useful slot area (eq. 15.21)

% see figure stator slot geometry
bos = 2.5*10^-3; % [m]
hos = 1*10^-3; % [m]
hws = 4*10^-3; % [m]
Kfe = 0.96; % [-]
```



```

Bts = 1.625;          % [Tesla] stator tooth flux density
sta_slot_pitch = pole_pitch/(3*q); % [m] stator slot pitch (eq. 15.3)
bts = Bg_req*sta_slot_pitch/(Bts*Kfe); % [m] tooth width (eq. 15.22)
bs1 = (pi*(Dis+2*hos*+2*hws)/Ns)-bts; % [m] slot lower width bs1 (eq. 15.23)
bs2 = sqrt(4*Asu*10^-6*tan(pi/Ns)+bs1^2); % [m] slot upper width bs1 (eq. 15.27)
hs = 2*Asu*10^-6/(bs1+bs2); % [m] slot useful height (eq. 15.24)
Fmg = 1.2*g*10^-3*Bg_req/u0; % [Aturns] airgap mmf (eq. 15.29)
% note that carter coe. is taken 1.2
Hts = 3100; % [A/m] (table 15.4) interpolation
Fmts = Hts*(hs+hos+hws); % [Aturns] stator tooth mmf (eq. 15.30)
Fmtr = Kst*Fmg - Fmts; % [Aturns] rotor tooth mmf (eq. 15.31)
hcs = (Dout-(Dis+2*(hos+hws+hs)))/2; % [m] stator back iron height (eq. 15.32)
Bcs = flux_airgap/(2*L*hcs); % [Tesla] back core flux density (15.33)

```

Stator slot geometry dimensions are shown in figure 15.5.

```

Asu = 389.0861 [mm^2]
bos = 0.0025 [mm]
hos = 1.0000e-03 [mm]
hws = 0.0040 [mm]
bts = 0.0047 [mm]
bs1 = 0.0094 [mm]
bs2 = 0.0138 [mm]
hs = 0.0335 [mm]
hcs = 0.0249 [mm]

```

Resultant mmfs

```

Fmg = 591.9621 [Aturns]
Fmts = 119.3143 [Aturns]
Fmtr = 117.4706 [Aturns]

```

The back core flux density is calculated as 1.6138T where within 1.4-1.7T.

Chapter 5. Rotor Slots




Figure 15.6 Typical rotor cage slots




Figure 15.7 Rotor slot geometry

```
% Based on the The Induction Machine Handbook Chapter 14 & 15
% rotor slot sizing will be determined
Nr = 60; % [-] rotor slot number
    % http://keysan.me/presentations/ee564_basic_machine_design2.html#32
    % 17/23 slayt table 7.5 most advantageous slot numbers for rotors
    % with slots skewed for a stator slot pitch 1-2
Ki = 0.8*pwr_factor+0.2; % [-] (eq. 15.35)
Ib = Ki*(2*m*N_per_ph_req*Kwl/Nr)*Iph_rated_rms;
    % [A] rated rotor bar current (eq. 15.34)
Jb = 3.42; % [A/mm] current density in the rotor bar
Ab = Ib/(Jb*10^6); % [m^2] rotor slot area (eq. 15.36)
Ier = Ib/(2*sin(pi*p1/Nr)); % [A] end ring current (eq. 15.37)
Jer = 0.75*Jb*10^6; % [A/m^2] current density in the end ring
Aer = Ier / Jer; % [m^2] end ring cross section (eq. 15.38)
hor = 1*10^-3; % [m] refer to figure 15.7
hwr = 4*10^-3; % [m] refer to figure 15.5
bor = 2.5*10^-3; % [m] refer to figure 15.7
rot_slot_pitch = pi*(Dis-2*g*10^-3)/Nr; % [m] rotor slot pitch (eq. 15.39)
Btr = 1.675; % [Tesla] rotor tooth flux density
btr = Bg_req*rot_slot_pitch/(Kfe*Btr); % [m] rotor tooth width (eq. 15.40)
% Let me calculate rotor slot dimensions like stator slot
```

```

br1 = pi*(Dis-2*hor-2*hwr)/Nr - btr; % [m] changed from (eq. 15.23)
br2 = sqrt(4*Ab*tan(pi/Nr)+br1^2); % [m] changed from (eq. 15.27)
hr = 2*Ab/(br1+br2); % [m] changed from (eq. 15.24)
Htr = 4200; % [A/m] from table 15.4 interpolation
Fmtr_res = Htr*(hr+hor+hwr); % [Aturns] rotor teeth mmf changed from (eq. 15.30)
Bcr = 1.65; % [Tesla] rotor back core flux density
hcr = flux_airgap/(2*L*Bcr); % [m] rotor back core height (eq. 15.46)
Dshaft_max = Dis-2*g*10^-3-2*(hor+hwr+hr+hcr);
% [m] max. shaft diameter (eq. 15.47)
b = 1.0*(hr+hor+hwr); % [m] end rind cross section b (eq. 15.50)
a = Aer/b; % [m] end rind cross section a (eq. 15.51)

```

Rotor slot geometry dimensions are shown in figure 15.7.
 But rotor slot geometry type is assumed 15.6d.
 And dimension calculations are computed like stator slot as in figure 15.5.
 But this time bs1 and bs2 are reversed.

```

Ib = 629.9058 [A]
Ab = 1.8418e-04 [m^2]
Ier = 3.0131e+03 [A]
Aer = 0.0012 [m^2]
bor = 0.0025 [mm]
hor = 1.0000e-03 [mm]
hwr = 0.0040 [mm]
btr = 0.0036 [mm]
br1 = 0.0072 [mm]
br2 = 0.0095 [mm]
hr = 0.0221 [mm]
hcr = 0.0243 [mm]

```

Resultant mmf
 Fmtr_res = 113.9060 [Aturns]
 so close to calculated as in stator slot sizing part Fmtr=117.4706.

The maximum diameter shaft 0.1105 [m].

Chapter 6. The Magnetizing Current

```
% Based on the The Induction Machine Handbook Chapter 14 & 15
% magnetizing current will be determined
y1 = bos^2/(5*g*10^-3+bos); % [m] (eq. 15.53)
y2 = bor^2/(5*g*10^-3+bor); % [m] (eq. 15.53)
Kc1 = sta_slot_pitch/(sta_slot_pitch-y1); % [-] (eq. 15.55)
Kc2 = rot_slot_pitch/(rot_slot_pitch-y2); % [-] (eq. 15.56)
Kc = Kc1*Kc2; % [-] total Carter coefficient Kc
Ccs = 0.88*exp(-0.4*Bcs^2); % [-] subunitary empirical coe. (eq 15.60)
Ccr = 0.88*exp(-0.4*Bcr^2); % [-] subunitary empirical coe. (eq 15.60)
Hcs = 2500; % [A/m] Hcs value at Bcs (table 15.4)
Hcr = 3460; % [A/m] Hcs value at Bcs (table 15.4)
Fmcs = Ccs*pi*(Dout-hcs)/(2*p1)*Hcs;
% [Aturns] stator back core mmfs (eq. 15.58)

Fmcr = Ccr*pi*(Dshaft_max+hcr)/(2*p1)*Hcr;
% [Aturns] rotor back core mmfs (eq. 15.59)
Flm = 2*(Fmg+Fmts+Fmtr+Fmcs+Fmcr); % [Aturns] magnetizing mmf (eq. 15.52)
Ks = Flm/(2*Fmg)-1; % [-] total saturation factor (eq. 15.61)
Im = pi*p1*(Flm/2)/(3*2^(0.5)*N_per_ph_req*Kw1); % [A] magnetizing current
% (eq. 15.62)
im = Im/IphRated_rms; % [-] relative (p.u) value of Im (eq. 15.62')
```

To find magnetizing current first of all magnetizing mmf should be calculated.

Carter's coefficient is calculated and the result is 1.1297 which was taken 1.2 in eq. 15.29.

Back core mmfs are also calculated.

Fmcs = 193.6720 [Aturns]

Fmcr = 108.5249 [Aturns]

total magnetizing mmf

Flm = 2.2619e+03 [Aturns]

total saturation factor Ks is 0.9105

magnetizing current Im is 113.1641 [A]

relative p.u value of the Im is 0.2404.

Chapter 7. Resistance and Inductances

```
% Based on the The Induction Machine Handbook Chapter 14 & 15
% resistance and inductances refer to eq. circuit (figure 15.9)
y = pitch_factor*pole_pitch; % [m] coil span (eq. 15.67)
lend = 2*y-0.02; % [m] coil end connection length (eq. 15.65)
lc = 2*(L+lend); % [m] coil length (eq. 15.64)
pco_80deg = 2.1712*10^-8; % [ohm.m] copper resistivity at @80° (eq. 15.69)
Rs = pco_80deg*(lc*N_per_ph_req)/(Aco*10^-6*a1); % [Ohm] stator resistance
% (eq. 15.63)

lambdaec = 0.34*(q/L)*(lend-0.64*pitch_factor*pole_pitch);
% [-] (eq. 15.79) two-layer, end connection
% specific geometric permeance coefficient
Lec = 2*u0*L*N_per_ph_req^2/(p1*q)*lambdaec; % [H] end winding inductance
% derived from (eq. 15.75)
ler = pi*(Dis-(2*g*10^-3)-(3*10^-3)-b)/Nr; % [m] end ring segment
% (eq. 15.71 & Dre-Der~3-4mm

pal_20deg = 3.1*10^-8;
pal_80deg = pal_20deg*(1+(80-20)/273); % [ohm.m] aluminium resistivity
Rer = pal_80deg*(ler/(2*Aer*sin(pi*p1/Nr)^2)); % [ohm] rotor end ring segment
% derived from (eq. 15.70)
mbetas = sqrt((2*pi*f1*u0)/(2*pal_20deg)); % [m^-1] (eq. 15.73)
S = 1;
meps = mbetas*hr*sqrt(S); % [-] (eq. 15.73)
Kr = meps; % [-] (eq. 15.72)
Rbes1 = pal_80deg*(L/Ab)*Kr+Rer; % [ohm] rotor bar/end ring segment
% eq. circuit (eq. 15.70)
Rrps1 = (4*m/Nr)*(N_per_ph_req*Kw1)^2*Rbes1; % [ohm] rotor cage resistance
% referred to stator at S=1 (eq. 15.74)
Rbesn = pal_80deg*(L/Ab)+Rer; % [ohm] for rated slip
Rrpsn = Rrps1*(Rbesn/Rbes1); % [ohm] (eq. 15.87)

stator resistance is calculated as 0.0039 Ohm. (cupper at 80°)
End winding inductance Lec 1.8823e-05H
resistance of the end ring of the rotor is 1.4138e-05 (aliminium at 80°)
resistance of the rotor bar/end ring segment
equivalent resistance Rbes1 = 1.6770e-04 [ohm]
rotor cage resistance referred to stator Rrpsn = 0.0025 [ohm]
```

Chapter 8. Losses and Efficiency

```
% Based on the The Induction Machine Handbook Chapter 14 & 15
%losses and efficiency will be calculated
Pco = 3*Rs*Iph_rated_rms^2; % [W] stator winding losses
Pal = 3*Rrpsn*Ki^2*Iph_rated_rms^2; % [W] rotor cage losses (eq. 15.97)
Pmv = 0.012*power_rated*10^3; % [W] mechanical/ventilation losses for p1=2
Pstray = 0.01*power_rated*10^3; % [W] stray losses
yiron = 7800;
Gt1 = yiron*Ns*bts*(hs+hws+hos)*L*Kfe; % [kg] stator tooth weight
Kt = 1.7; % [-] (eq. 15.98) core loss augmentation
p10 = 2.5; % [W/kg] specific losses in W/kg at 1.0 Tesla and 50Hz
Pt1 = Kt*p10*(f1/50)^1.3*Bts^1.7*Gt1; % [W] stator teeth fund. losses
% (eq. 15.98)
Gy1 = yiron*pi/4*(Dout^2-(Dout-2*hcs)^2)*L*Kfe; % [kg] stator back iron weight
% (eq. 15.101)
Ky = 1.75; % [-] influence of mechanical machining
Py1 = Ky*p10*(f1/50)^1.3*Bcs^1.7*Gt1; % [W] stator back iron (yoke) losses
% (eq. 15.100)
Piron1 = Pt1+Py1; % [W] fund. iron losses
Kps = 1/(2.2-Bts); % [-] (eq. 15.104)
Kpr = 1/(2.2-Btr); % [-] (eq. 15.104)
Bps = (Kc2-1)*Bg_req; % [Tesla] (eq. 15.105)
Bpr = (Kc1-1)*Bg_req; % [Tesla] (eq. 15.105)

Gtr = yiron*Nr*btr*(hr+hwr+hor)*L*Kfe; % [kg] rotor teeth weight

Pirons = 0.5*10^-4*((Nr*f1/p1*Kps*Bps)^2*Gt1+(Ns*f1/p1*Kpr*Bpr)^2*Gtr);
% [W] tooth flux pulsation core loss constitutes
% the main components of stray losses (eq. 15.103)
Piron = Pirons+Piron1; % [W] total iron core loss
Ploss_total = Pco+Pal+Piron+Pmv+Pstray; % [W] total losses (eq. 15.95)
neff_cal = power_rated*10^3/(power_rated*10^3+Ploss_total); % [-]
% efficiency (eq. 15.94)

loss components are calculated in this chapter
stator tooth weight Gt1 = 13.7818 [kg]
stator back iron weight Gy1 = 39.3987 [kg]
rotor teeth weight Gtr = 9.3171 [kg]

stator winding losses Pco = 2.5602e+03 W
rotor cage losses Pal = 1.3721e+03 W
mechanical/ventilation losses Pmv = 2.5782e+03 W
stray losses Pstray = 2.1485e+03 W
stator teeth fund. losses Pt1 = 810.6309 W
stator back iron (yoke) losses Py1 = 824.7193 W
fund. iron loss Piron1 = 1.6354e+03 W
tooth flux pulsation core loss constitutes the main
components of stray losses Pirons = 133.1240 W
total iron loss Piron = 1.7685e+03 W
total loss Ploss_total = 1.0427e+04 W
efficiency, neff_cal = 0.9537
```

Note that calculated efficiency value is so close to the targeted efficiency which was $neff = 0.9600$

Chapter 9. Operation Characteristics

```
% Based on the The Induction Machine Handbook Chapter 14 & 15
% operating characteristics will be investigated
I0a = (Piron+Pmv+(3*Im^2*Rs))/(3*Vph_rms); % [A] no load active current
                                           % (eq. 15.109)
Sn = Pal/(powerRated*10^3+Pal+Pmv+Pstray); % [-] rated slip (eq. 15.110)
Tn = powerRated*10^3/(2*pi*(f1/p1)*(1-Sn)); % [Nm] rated shaft torque
                                           % (eq. 15.111)
pwr_factor_cal = powerRated*10^3/(3*Vph_rms*IphRated_rms*neff_cal); % [-]
                                           % rated power factor (eq. 15.117)
```

The operation characteristics are calculated as below

active no load current I0a = 8.3204A

rated slip Sn = 0.0062

rated shaft torque Tn = 344.0780Nm

rated power factor pwr_factor_cal = 0.8858

note that it is so closed to first assumption value (0.8800)

Chapter 10. Temperature Rise

```
% Based on the The Induction Machine Handbook Chapter 14 & 15
% a coarse verification of temperature rise is given here
aconv1 = 50; % [W/m^2.K] IM with selfventilators (below 100Kw) (eq. 15.123)
% it is not enough to cool
% http://www.engineersedge.com/thermodynamics/overall_heat_transfer-table.htm
% forced water cooling heat transfer structure should be used
aconv2 = 650; % [W/m^2.K]
acond = 833; % [W/m^2.K] slot insulation conductivity (eq. 15.124)
Als = (2*hs+bs2)*L*Ns; % [m^2] stator slot lateral area (eq. 15.125)
Kfin = 3; % [-] finn factor (eq. 15.126)
Aframe = pi*Dout*(L+pole_pitch)*Kfin; % [m^2] frame area including finn area
% (eq. 15.126)
delta_co = Pco/(acond*Als); % [°] temperature differential between conductors
% in slots and the slot wall (eq. 15.121)

delta_frame2 = Ploss_total/(aconv2*Aframe); % [°] frame temperature rise
% with respect to ambient air (eq. 15.122)
delta_frame1 = Ploss_total/(aconv1*Aframe); % [°] frame temperature rise
% with respect to ambient air (eq. 15.122)


temp_ambient = 40; % [°] ambient temperature
temp_co = temp_ambient+delta_frame2+delta_co; % [°] winding temperature
% (eq. 15.127)
% should be <80°
```

temperature rise of the winding will be calculated roughly
note that if selfventilators are used to cool the motor
the frame temperature rise will be $\text{delta_frame1}=169.3815^\circ$
which is not suitable for this motor design
so forced water cool method should be used.
the frame temprature rise $\text{delta_frame2} = 13.0293^\circ$
temperature differential between conductors in slots and the slot wall
 $\text{delta_co} = 3.7408^\circ$


with ambient temperature 40°
winding temperature will be $56.7701^\circ < 80^\circ$
at rated power (214.8480kW)

Chapter 11. Motor Analysis


Geometry editor



stator slot



rotor slot



winding diagram

