




# Technical Service Information

## THM 440-T4 HARSH 4-3 DOWNSHIFT (NEW PROM)

**COMPLAINT:** Harsh 4-3 downshift on 1985 Oldsmobile 98 vehicles.

**CAUSE:** Converter clutch not releasing on the 4-3 downshift.

**CORRECTION:** Replace the PROM in the ECM with updated OEM part number 16047215



Copyright © 2001 ATSG

Figure 1