



Technical Service Information

ACURA 4 SPEED HYDRAULIC SLIPPING OR NO FIRST GEAR

COMPLAINT: Slipping or no 1st gear.

CAUSE: Snap ring is not fully seated causing a sever leak at the first clutch feed pipe.

CORRECTION: Replace the o-ring and reinstall the snap ring pressing down all the way around the snap ring to make sure it is properly seated.




Figure 1

Copyright © 2000 ATSG