



Technical Service Information

THM 4L60-E 2ND GEAR START, 2-3 SHIFT ONLY OR LACK OF LINE PRESSURE RISE


COMPLAINT: Before and/or after rebuild the vehicle exhibits a 2nd gear start with only a 2-3 shift and possibly a lack of proper line pressure rise with throttle opening.

CAUSE: The cause may be, one or both of the screens in the spacer plate collapsed shut, and restricting solenoid feed oil or actuator feed oil to the Pressure Control Solenoid.

CORRECTION: Replace both screens in the spacer plate as shown in Figure 1, with the part numbers listed below. These *new part numbers* are screens with a larger micron screen that will pass more oil easier.

SERVICE INFORMATION:

Electronic Pressure Control Solenoid Screen	24209145
Shift Solenoid Screen	24209144



Copyright © 1998 ATSG