



Technical Service Information

THM 4L80-E VENT SHIELD LOCATION


CHANGE: Beginning at start of production for all 1994 model THM 4L80-E/4L80-EHD transmissions, there was a Vent Shield added to the back side of the pump cover, and retained by, a pump cover to pump body retaining bolt as shown in Figure 1.

REASON: To eliminate fluid from exhausting from the transmission air vent.

PARTS AFFECTED:
(1) VENT SHIELD - Added to the oil pump assembly in model year 1994 (See Figure I).

INTERCHANGEABILITY:
The Vent Shield will retro-fit back to all previous models

SERVICE INFORMATION:
Vent Shield, Oil Pump 24200357



Copyright © 2001 ATSG