

KM 175 BIND UP OR 2ND GEAR STARTS

COMPLAINT: A bind up on a 2-3 shift and or 2nd gear starts. Or a bind up in reverse after overhaul.

CAUSE: The snap ring that holds the center support into the case may have been mis-positioned and when pulse generator A was installed, one end of the snap-ring came out of its groove and jammed against the sun shell

CORRECTION: Install the snap-ring so that the open end of the snap-ring faces the entrance hole in the case for pulse generator A. See figure 1 below.




Figure 1