




Technical Service Information

THM 3T40 (125C) DIFFERENTIAL LOCKING SWITCH

COMPLAINT: 1. AWD LOCK - indicator will remain on, but differential will not lock.
2. ANTI-LOOK - indicator will remain on, and ABS operation would be disabled.

CAUSE: The cause may be an inoperative and/or intermittent Center Differential Locking Switch (See Figure 1) due to moisture entry during the manufacturing process.

CORRECTION: Replace the Center Differential Locking Switch with a new one, now available under OEM part number 8665329.



43 CENTER DIFFERENTIAL LOCKING SWITCH
45 SEAL, O-RING ELECTRICAL CONNECTOR HOUSING

Figure 1