



# Technical Service Information

## ZF5HP24 (A5S 440Z)

### “E” CLUTCH PISTON FAILURE

**COMPLAINT:** The transmission exhibits flared 1-2 and 2-3 shifts. P0732 and P0733 “Gear Control Malfunction 2nd and 3rd” codes are stored. Disassembly and inspection of the transmission reveals that the “E” clutch piston is badly cracked (Refer to Figure 1).

**CAUSE:** This condition is primarily seen in the Audi A8 and Jaguar XK8/XJ8 models. At this time the cause is unclear, however, it may be non-commanded line pressure spikes.

**CORRECTION:** Replace the “E” clutch piston.

**SERVICE INFORMATION:**

*“E” Clutch Piston.....1058-375-020*




Figure 1