



Technical Service Information

SUBARU 3 SPEED BINDS UP IN REVERSE AFTER REBUILD

COMPLAINT: Transmission binds up in reverse after rebuild. Also transmission shifts 1-3 with no possibility of obtaining 2nd gear.

CAUSE: Valve body to servo tubes incorrectly installed. Direct clutch oil can be fed to the apply side of the servo causing the band to come on in reverse.

CORRECTION: Install tubes to look like the letter T as shown in figure below.




Figure 1

Copyright © 2000 ATSG