



# Technical Service Information

## **VOLVO "850" 50-42LE SLIPPING OR "NO" FORWARD ENGAGEMENT**

**COMPLAINT:** Volvo "850" series equipped with 50-42LE transmissions may exhibit a slipping or "NO" forward engagement condition.

**CAUSE:** The cause may be, the forward or C1 clutch drum is cracked (See Figure 1).

**CORRECTION:** Locate the crack as shown in Figure 1 and have the drum welded on the inside as well as the outside of the drum. At the time of this printing, the forward or C1 drum is not sold separately from the transmission.




Figure 1