



Technical Service Information

THM 3T40 (125C) HARSH 1-2 SHIFT

COMPLAINT: Harsh 1-2 shift encountered on 1985-86 Thm 125C transmissions.

CAUSE: Too small an orifice in separator plate (.040) 1-2 ACCUMULATOR FEED BACK ORIFICE.

CORRECTION Drill orifice to (.125) or replace with part number 8660581




Figure 1