



Technical Service Information

CHRYSLER A604

SLIPS IN REVERSE AND/OR NO REVERSE


COMPLAINT: On any 1990-1991 model Chrysler A604 transaxle, A slipping in reverse and/or no reverse condition.

CAUSE: The cause may be an undersized input clutch hub, in the area of the hub outer seal. This undersize condition will result in the Overdrive/ Reverse piston contacting the input clutch hub. This contact results in a scratching/scoring of the Overdrive/Reverse piston in the seal area (See Figure 1).

CORRECTION: Replace the Input Clutch Hub and the Overdrive/Reverse piston. The Overdrive/Reverse piston may be the 8 slot design, or the 4 slot design (See Figure 2).

SERVICE INFORMATION:

Input Clutch Hub	4531637
Front (Blue) "O" Ring Seal	6502271
Rear (Red) "O" Ring Seal	6502269
Overdrive/Reverse Piston (4 Slot)	4531492
Overdrive/Reverse Piston (8 Slot)	4431613



Copyright © 2000 ATSG

Figure 1




Figure 2