




Technical Service Information

MERCEDES 722.3 /.4 HARSH ENGAGEMENT INTO REVERSE ONLY

- COMPLAINT:** Harsh engagement in reverse only.
- CAUSE:** Ball valve in the front transmission cover is defective.
- CORRECTION:** Replace ball valve, part #201270 03 89, and install retaining washer (24), part number 000 463 008403 (Figure 1).
- Production Phase-in of retaining washer: As of trans end #316 257.
- NOTE** Take ball from package only shortly before installation, otherwise the plastic becomes brittle when it dries out and can break during installation.



- 8 - Mounting screw, primary pump
23- Ball valve
24- Retaining washer

Copyright © 2000 ATSG