



Technical Service Information

THM 4L60 (700-R4) NO 4TH GEAR

COMPLAINT: No 4th gear; 2nd and 4th pressure lower than line pressure.

CAUSE: The cause could be the bleed orifice cup plug missing from the case in the bottom of the 3-4 accumulator bore (see Figure 1).

CORRECTION: Install bleed orifice cup plug, OEM Part Number 8628864.




Figure 1

Copyright © 2000 ATSG