



Technical Service Information

THM 325/325-4L NO UPSHIFT, CUP PLUG MISSING

COMPLAINT: No upshift at any vehicle speed.

CAUSE: The cause may be the governor passage cup plug missing from the case (See Figure 1).

CORRECTION: Replace cup plug, available under OEM part number 8620318. This is a 3/8" diameter cup plug and may be available locally.




Figure 1