

THM 3T40 (125C) NO TCC ON RELEASE ON COAST DOWN OR STALLS AFTER DRIVEN

A complaint of no converter release on coast down shift or stalls engine after vehicle has been driven, can be caused by mismatch of gasket Figure 1 (1984 installed in 1982) or a cup plug off location in the Aux Valve body. A mismatch of a 1982 gasket in a 1984 gives a no converter clutch apply condition




Figure 1