



Technical Service Information

ZF5HP24

SLIPPING OR NO REVERSE


COMPLAINT: Some 1999 to 2000 vehicles equipped with the 5HP24 transmission may exhibit a slipping or no engagement in Reverse.

CAUSE: The cause may be, a defective "F" clutch bonded piston. The "F" clutch is the Low and Reverse Clutch, which holds to provide Reverse application and Engine braking in Manual Low. The "F" clutch piston on some of these later versions have had problems with the bonding coming off of the piston.

CORRECTION: Replace the "F" clutch piston as shown in Figure 1.

SERVICE INFORMATION:

"F" CLUTCH BONDED PISTON (ZF part number).....0501-212-967



Copyright © 2004 ATSG

Figure 1