



Technical Service Information

FORD AXOD-E 3-NEUTRAL KICKDOWN

COMPLAINT: A delayed shift may occur during 3-2 forced downshifts, or "Kickdown".

CAUSE: The cause may be, a broken spring retainer clip between the pull-in control valve spring and the 3-2 control valve spring, as shown in Figure 1.

CORRECTION: Replace the spring retainer clip with OEM part number F1DZ-7F194-A.




Figure 1




Figure 1