



Technical Service Information

CHRYSLER A500/518 OVERDRIVE SUN GEAR

- COMPLAINT:** The retaining ring snap ring groove in a newly purchased sun gear does not seem to retain the retaining ring properly.
- CAUSE:** The retaining ring snap ring groove is not machined deep enough to accommodate the snap ring.
- CORRECTION:** The snap ring groove should be machined the same depth as the splines. You can machine the groove down all the way yourself or reorder a new sungear.




Figure 1

Copyright © 2000 ATSG