



Technical Service Information

FORD E4OD DELAYED ENGAGEMENT

COMPLAINT: A delayed engagement of 10 to 30 seconds, after setting for an extended period of time.

CAUSE: The cause may be, converter drain back through the cooler.

CAUSE: Install an in-line check valve, OEM part number F0TZ-7D174-A, in the "COOLER RETURN LINE" going to the REAR case fitting. (See Figure 1).

NOTE: MAKE SURE THAT THE FLOW DIRECTION ARROW STAMPED ON THE CHECK VALVE POINTS TOWARDS THE REAR COOLER FITTING, OR A TRANSMISSION FAILURE WILL RESULT.




Figure 1