



Technical Service Information

ACURA 4 SPEED HYDRAULIC HIGH LINE PRESSURE

COMPLAINT: Harsh engagement, harsh shifts, high line pressure.

CAUSE: Pressure regulator retaining bolt jamming spring retainer (figure 1).

CORRECTION: When installing retainer and bolt make sure that the slot on the retainer lines up with the bolt hole before installing the bolt (figure 2).




Figure 1




Figure 2

Copyright © 2000 ATSG