



Technical Service Information

CHRYSLER A604 DELAYED REVERSE ENGAGEMENT

COMPLAINT: Delayed engagement when the selector lever is placed in reverse, and the forward engagement is OK.

CAUSE: NUMBER ONE - The cause may be, a defective PRNODL Switch located in the case (See Figure 1 for Location), because of no signal to the controller that reverse was selected.

NUMBER TWO - The cause may be, not enough reverse oil flow through the orifice to the reverse clutch.

CORRECTION: NUMBER ONE - Replace the PRNODL Switch located in the case with the appropriate OEM part number (See Figure 2).

NUMBER TWO - If the condition still exists after checking, or replacing the PRNODL Switch, drill the hole in spacer plate marked "I", as shown in Figure 3.

SERVICE INFORMATION:

PRNODL Switch (1989 Model)	5234022
PRNODL Switch (1990-UP Models)	5234393
Neutral Safety Switch (1989 Model)	3747361
Neutral Safety Switch (1990-UP Models)	5234319

Copyright © 2000 ATSG






Figure 1

PRNDL SWITCH AND CONNECTOR



THESE PRNDL SWITCHES WILL NOT INTERCHANGE.

Figure 2



DRILL HOLE MARKED "I" TO .093" AS SHOWN ABOVE

A604 SPACER PLATE

Figure 3
AUTOMATIC TRANSMISSION SERVICE GROUP