



Technical Service Information

THM 3T40 (125C) CONVERTER CLUTCH SHUDDER 1987 OR LATER ONLY

COMPLAINT: Converter clutch apply shudder, only on 1987 or late THM 125C (3T40) Transaxles.

CAUSE: Not enough converter clutch apply oil.

CORRECTION: Install the 1988 (KDC) auxilliary valve body gasket with the large hole (See Figure 1), or modify the 1987 gasket with the small hole, by cutting on the dotted line (See Figure 1).




Figure 1