




# Technical Service Information

## THM 4L80-E NO LINE PRESSURE RISE

**COMPLAINT:** No line pressure rise when the throttle is opened. Line pressure remains at approximately 45 psi. and will produce soft mushy shifts. When the case connector is removed and/or the force motor voltage is removed, line pressure remains at minimum.

**CAUSE:** The cause may be that the cup plug has blown out of the torque signal passage in the accumulator body. See figure 1 for the location of the cup Plug

**CORRECTION:** Replace the cup plug and stake it in place to prevent it from coming out again.



Copyright © 2001 ATSG

Figure 1

AUTOMATIC TRANSMISSION SERVICE GROUP

93-40  
Page 1 of 1