



Technical Service Information

THM 440-T4 HARSH REVERSE ENGAGEMENT

COMPLAINT: Harsh Garage Shift From Park/Neutral To Reverse.

CAUSE: The cause may be:

1. Low vacuum supply to the vacuum modulator.
2. Stuck modulator valve in case.
3. No. 9 checkball missing or off location.

CORRECTION: AFTER ALL OF THE ABOVE ARE ELIMINATED:
There is now available a new Reverse Servo Cushion Spring, and a new Reverse Servo Return Spring. Replacing these springs should correct the harsh reverse condition. The reverse servo return spring should only be replaced on the 2.8L engines.

Spring, Reverse Servo Cushion (All).....	8668121
Spring, Reverse Servo Return (2.8L Only).....	8668127




Figure 1