

## THM 4L30-E SLIPPING OR NO 2ND GEAR

**COMPLAINT:** Before and/or after overhaul, the vehicle exhibits a slipping condition when going into second gear, or possibly no second gear at all.

**CAUSE:** The cause may be, a cracked 2nd clutch housing that is barely perceptible, as shown in Figure 1.

**CORRECTION:** Replace the 2nd clutch housing as necessary. Refer to Figure 1.




Figure 1