




Technical Service Information

THM 4L60 (700-R4) BIND-UP IN REVERSE

- COMPLAINT:** Binding or "Tie-up" when selector lever is placed in the averse position.
- CAUSE:** This condition may be caused by the 4-3 sequence valve or the 2-3 shift valve, stuck in the upshifted position, because of burrs or contamination.
- CORRESTION:** Clean the contamination or remove burrs from the problem valves. Refer to Figure 1 for valve location.



Copyright © 2000 ATSG