



Technical Service Information

THM 440-T4 1-2 SLIP AND/OR SHUDDER


COMPLAINT: 1-2 slide shudder on THM 440-T4, 1984-87.

CAUSE: Can be caused by clutch lining compatability of lined plates. This can also be a problem encountered with SRTA or factory rebuilt units.

CORRECTION: Install kit number 8662913 for 1984 thru 1986, which comes with five (5) lined plates and five (5) steel (koline) plates. The koline plates in this kit are .088-.090 thick. For the 1987 units, use kit number 8662914, which comes with six (6) lined plates and six (6) steel (koline) plates. The koline plates in this kit are .075-.077 thick.

8662913 - (5) CLUTCH KIT - 1984 - 86

8662914 - (6) CLUTCH KIT - 1987



Copyright © 2001 ATSG