



# Technical Service Information

## THM 440-T4 EXTERNAL 1-2 SERVO LEAK

**COMPLAINT:** On some 1991 models only, the 1-2 servo may exhibit an External oil leak even after the o-ring on the cover has been replaced.

**CAUSE:** The cause may be due to stress cracks in the case by the Servo window at the 6 o'clock position (see Figure 1). Vehicles prone to having this problem are 1991 Pontiac 6000, Bonnevilles or Grand Prixes that are built between Julian date 172 (June 17, 1991) and 186 (July 28, 1991) (see Figure 2), and has a casting die number of 594 located on the bell housing (see Figure 3).

**CORRECTION:** Replace the case

<u>MODEL NUMBER</u>	<u>PART NUMBER</u>
IWJH, IWMH, IWPH IWXH, IWWH, IYDH, IYHH	8668986
IWFH, WYSH, WYTH	8668985




Figure 1





Figure 1