



Technical Service Information

CHRYSLER A500/A518 LATE OR NO UPSHIFTS, OR NO UPSHIFT AFTER KICKDOWN

COMPLAINT: Any vehicle equipped with a A500/518 transmission may exhibit a complaint of late, or no upshifts, or no upshift after passing gear.

CAUSE: One cause may be a worn governor valve in the governor assembly, not allowing governor pressure to increase properly. Refer to Figure 1 for identification of the governor valve.

CORRECTION: Replace the governor valve, as shown in Figure 1.

SERVICE INFORMATION:


Governor Valve 4617064

Copyright © 2001 ATSG

AUTOMATIC TRANSMISSION SERVICE GROUP

01-07R
Page 1 of 2

EXPLODED VIEW OF THE 3 STAGE GOVERNOR



Copyright © 2001 ATSG

Figure 1