



1995 SEMINAR INFORMATION  
"HOW TO SURVIVE IN 95"

**INDEX**

*IMPORTS*

MITSUBISHI.....	4
HONDA/ACURA.....	31
MAZDA/FORD.....	46
NISSAN.....	59
INFINITI.....	61
ELECTROMATIC.....	70
SAAB/PREMIER.....	71
VOLVO/BMW.....	73
VOLKSWAGEN.....	79

*GENERAL MOTORS*

125.....	94
SATURN.....	98
4T40-E.....	107



# "HOW TO SURVIVE IN '95"

## INTRODUCTION

In this years "HOW TO SURVIVE IN 95 SEMINAR" ATSG will once again present solutions for the common problems the technician is facing in the shops today. This years seminar will also give the technicians **THREE** manuals that can be brought back to the shop for future reference. Each manual is packed with up to date fixes and information on both domestic and import vehicles alike. These manuals are also keyed to the video and live presentation of the seminar, so the technician can place his entire attention on the seminar, without having to try to write it all down. The seminar starts by covering a wide variety of imports, followed by G.M., Ford and Chrysler vehicles. The entire day will be filled with tips on code retrieval, scanners, fixes, part changes and interchangeability. ATSG has been and always will be dedicated in helping the shops to survive not only in 95, but in the years to come as well.

The information and part numbers contained in this booklet have been carefully compiled from industry sources known for their reliability, but ATSG does not guarantee its accuracy.

Copyright © ATSG 1995

ROBERT D. CHERRNAY  
TECHNICAL DIRECTOR

DALE ENGLAND  
FIELD SERVICE CONSULTANT

WAYNE COLONNA  
TECHNICAL SUPERVISOR

ED KRUSE  
TECHNICAL CONSULTANT

PETE LUBAN  
TECHNICAL CONSULTANT

JIM DIAL  
TECHNICAL CONSULTANT

GREGORY LIPNICK  
TECHNICAL CONSULTANT


JERRY GOTT  
TECHNICAL CONSULTANT

DAVID CHALKER  
TECHNICAL CONSULTANT

*AUTOMATIC TRANSMISSION SERVICE GROUP*  
9200 S. DADELAND BLVD.  
SUITE 720  
MIAMI, FL 33156  
(305) 670-4161

# BRYCO


... YOUR No. 1 SUPPLIER



**TIMING COMPONENTS**



**AUTOMATIC TRANSMISSION REPAIR KITS**



**STANDARD CLUTCH PRODUCTS**



**AUTOMATIC TRANSMISSION COMPONENTS**

# BRYCO

PROVEN THE BEST!

BRYCO has a complete line of foreign and domestic timing components, standard clutches with bearings and covers, automatic transmission parts and repair kits. All of our products are made with the highest quality materials and under the strictest supervision—providing an excellent product at a great price!

**STAY ON "BRYCO" — IT DOESN'T COST MORE TO GET THE BEST!**

**CARFEL INC.**  
7495 N.W. 40th St.  
Miami, FL 33166 USA  
TEL: 305-582-2780  
FAX: 305-582-7543

EXPORT CUSTOMERS — PLEASE USE TEL: 305-584-2205

## 1985-1988 MITSUBISHI CODE RETRIEVAL IDENTIFICATION

**COMPLAINT:** Fault code identification on early Mitsubishi vehicles equipped with KM transaxles.

**CAUSE:** Failure to properly identify code charts, or a "no code stored" after a malfunction, or failure to understand voltmeter code signals, or failure to identify correct year of vehicle manufacture.

**CORRECTION: ALWAYS** identify the year of manufacture by the 10th vin digit as follows:

F=1985; G=1986; H=1987; J=1988

1985-1988 transaxle computers have no "keep alive" memory! Therefore, if the ignition is shut off, ALL fault codes will be ERASED. Drive the vehicle and leave it running while you check for codes.

Shown below in figure 1 is an example of a 1986 Galant code chart. The numbers in the far left column have NOTHING to do with codes. They are simply listed in numeric order. Any reference to these numbers will relate to that particular needle sweep that is seen on your voltmeter. For example, Code #3 seen below will be displayed on the voltmeter as 1 short sweep, 1 long and 3 short sweeps.

	Malfunction indication code	Diagnosis	Assumed location
1		Microprocessor (computer) malfunction; not remedied by resetting.	<ul style="list-style-type: none"> <li>● Low power-supply voltage (recharging system)</li> <li>● TCU</li> </ul>
2		First gear signal is detected at high vehicle speed.	<ul style="list-style-type: none"> <li>● Pulse generator B</li> <li>● Vehicle speed sensor</li> <li>● TCU</li> </ul>
3		Vehicle speed detected by pulse generator B is much lower than actual vehicle speed.	<ul style="list-style-type: none"> <li>● Pulse generator B</li> <li>● Vehicle speed sensor</li> <li>● TCU</li> </ul>

Figure 1

Illustrated on the following page in figure 2 is the numerically listed #3 malfunction code shown in the chart above, which has been singled out for clarity. The first multimeter 12 volt sweep is the "BEGIN CODE" indicator. This sweep will be 4 seconds long and must be 12 volts. If this sweep is not 12 volts, this may be an indication of a poor ground or a faulty computer.

The second, third, fourth, fifth and sixth sweeps are the actual code. The long and short sweeps MUST match to the code illustration in the chart. This means you will see 1 short sweep, 1 long sweep and 3 short sweeps indicating a possible problem with Pulse Generator B. After each code is output, or a repeat of a code, there will be a 2 second pause signifying "End of Code". After all codes are output, the 4 second "begin code" sweep will repeat itself before code output starts again.

**NOTE:** Code charts can be found in the ATSG Import Pass Book, Volume 1.

We would like to thank John Strenfel of Balco, INC. for the information included here.

### Automatic Transmission Service Group




Figure 2

#### NOTE #1:

- 1) ALWAYS check the battery feed circuit going into the transaxle computer and,
- 2) ALWAYS check the voltage supply from the transaxle computer to the inhibitor switch.

Failure to have battery voltage (approximately 12 volts D.C.) at either of these points will result in **THIRD GEAR ONLY** as soon as the vehicle is in drive. This is NOT "Failsafe Mode"! This is a DEAD system!

A true "Failsafe Mode" is when the transaxle will attempt an upshift, and due to slippage in the transaxle or switched pulse generators or an extremely harsh shift into third or another failsafe related problem, the transaxle computer will then be informed there is a problem and prevent the flow of electrical signal to the shift solenoids, putting the transaxle into third gear.

The difference between these two situations is, a GENUINE "Failsafe Mode" will not interrupt electrical supply TO THE COMPUTER. A DEAD SYSTEM will!

See figures 17-22 on pages 15-17 for transaxle computer locations and refer to the charts on pages 18-30 to locate and check power supplies to the computer and inhibitor switches. A lack of power to either of these items will cause a DEAD SYSTEM. The power supply terminals in the charts are identified by *bold italics*.

#### NOTE #2:

When the transaxle computer is not in "Failsafe" and the system is not dead, the computer should be sending on/off 12 volt commands to the shift solenoids in order for the transaxle to shift through the gears. This on/off signal can be checked and should be checked with a multimeter to ensure that there is in fact 12 volts being sent to the shift solenoids. If there is anything less than 12 volts but more than 0 volts, this would indicate poor grounds or a faulty computer.

#### NOTE #3:

When checking the system for codes as explained on the previous page, remember to ALWAYS verify vehicle year of manufacture. The numerically listed code configurations will vary from year to year. For example, illustrated on the following page in figure 3 is an example of 3 different numerically listed #9 malfunctions. One is for a 1985 vehicle, another is for a 1986 vehicle, and the remaining sequence is for a 1987 vehicle. This is why it is imperative that you verify the year of the vehicle that you are working on, and that you choose the appropriate malfunction chart and compare it to your analog meter needle sweeps. The diagnostic connector locations for the various models can be found on pages 7-14, figures 5-16.




Figure 3

Illustrated below in figure 4 is a wiring schematic found in a typical KM equipped vehicle. A further explanation of what is meant by a "DEAD SYSTEM" and what to check for can be seen below by finding terminal #1 in the 13 pin connector, we see that it is the computers power supply. This terminal must be checked for battery voltage. Next, terminal #19 in the 20 pin connector would be checked for battery voltage. This is the circuit that the inhibitor switch inputs to the computer. If either of these circuits do not have battery voltage, a "DEAD SYSTEM" would exist, resulting in third gear only as soon as the vehicle is put in drive.





Figure 4

## KM VOLTMETER DIAGNOSTIC CONNECTOR LOCATOR

1985-1986 GALANT SYSTEMS



POSITIVE=TRANSAXLE COMPUTER  
NEGATIVE=GROUND




Figure 5

## KM VOLTMETER DIAGNOSTIC CONNECTOR LOCATOR




Figure 6




Figure 7



## KM SCANNER DIAGNOSTIC CONNECTOR LOCATOR

1989-1993 GALANT SYSTEMS  
1990-1994 ECLIPSE SYSTEMS  
1991-1993 STEALTH & 3000GT SYSTEMS  
1991-1994 LASER & TALON SYSTEMS  
1992-1993 EXPO SYSTEMS  
1992-1993 SUMMIT & VISTA WAGON SYSTEMS  
1992-1993 DIAMANTE & DIAMANTE WAGON SYSTEMS




Figure 8

## KM SCANNER DIAGNOSTIC CONNECTOR LOCATOR





Figure 9

If you're lucky enough to  
have a shop in one of the  
shaded areas below,



# CONGRATULATIONS!

THERE ARE MANY CHOICES, BUT ONLY TWO SOLUTIONS FOR ALL YOUR TRANSMISSION NEEDS.  
HTP AND RPM HAVE JOINED FORCES TO BRING YOUR SHOP ALL THE BEST IN HARD PARTS, SOFT PARTS,  
TORQUE CONVERTERS, CLUTCH KITS, AND MORE AT COMPETITIVE PRICES.

WE ALSO OFFER YOUR SHOP THE BEST MIX OF PRICE, QUALITY, AND SERVICE ON OUR FULL LINE OF  
HARD AND SOFT PARTS! TAKE ADVANTAGE OF OUR NUMEROUS TRUCK RUNS.

FOR MORE INFORMATION CONTACT THE LOCATION NEAREST YOU.

<b>ARIZONA</b>		<b>GEORGIA</b>		<b>NEVADA</b>		<b>WASHINGTON</b>	
PHOENIX	800-275-9709	ATLANTA	800-938-4776	LAS VEGAS	702-253-9814	SEATTLE	800-275-0951
TUCSON	602-622-1971					SPOKANE	800-275-0355
<b>CALIFORNIA</b>		<b>KENTUCKY</b>		<b>NORTH CAROLINA</b>		<b>BRITISH COLUMBIA</b>	
AZUSA	800-275-9736	LOUISVILLE	800-289-1487	CHARLOTTE	800-374-3487	VANCOUVER	800-667-6388
FRESNO	800-275-3961	<b>MICHIGAN</b>		<b>OREGON</b>			
LOS ANGELES	213-730-9131	JACKSON	800-477-2487	PORTLAND	800-275-0984		
OAKLAND	800-275-2588	<b>MISSOURI</b>		<b>TEXAS</b>			
SACRAMENTO	800-275-7606	KANSAS CITY	800-221-6176	DALLAS	800-275-8569		
SAN DIEGO	800-275-6223	ST. LOUIS	800-928-3370	<b>UTAH</b>			
SANTA CLARA	800-275-2113	SPRINGFIELD	800-749-3939				
<b>COLORADO</b>		<b>NEW MEXICO</b>					
COLORADO SPRINGS	800-748-2568	ALBUQUERQUE	800-275-1229				
DENVER	800-275-1014						

AND  
GROWING!

## KM SCANNER DIAGNOSTIC CONNECTOR LOCATOR

1994 GALANT SYSTEMS  
1994 STEALTH & 3000GT SYSTEMS





Figure 10



1994 MIRAGE SYSTEMS  
1994 DIAMANTE SYSTEMS  
1994 COLT & SUMMIT SYSTEMS

Figure 11

## KM SCANNER DIAGNOSTIC CONNECTOR LOCATOR

1990-1993 EXCEL SYSTEMS  
1991-1993 SCOUPE SYSTEMS  
1990-1993 PRECIS SYSTEMS





Figure 12



1992-1994 ELANTRA

Figure 13

## KM SCANNER DIAGNOSTIC CONNECTOR LOCATOR

1990-1994 SONATA WITH PASSIVE SEAT BELT SYSTEMS






Figure 14



1989-1994 SONATA (USA) WITH NON-PASSIVE SEAT BELT SYSTEM

Figure 15



1989-1994 SONATA (NON-USA) WITH PASSIVE SEAT BELT SYSTEMS

Figure 16

## TRANSAXLE COMPUTER LOCATOR




Figure 17




Figure 18

## TRANSAXLE COMPUTER LOCATOR




Figure 19




Figure 20



## TRANSAXLE COMPUTER LOCATOR




Figure 21




Figure 22



## 1985-86 GALANT

### Transaxle Computer Pin ID

#### 17 PIN CONNECTOR

A9	A1
A10	A2
A11	A3
A12	A4
A13	X
A14	A5
A15	A6
A16	A7
A17	A8

- A-1 ENGINE COOLANT TEMPERATURE
- A-2 OVERDRIVE SWITCH
- A-3 INHIBITOR SWITCH (R)
- A-4 INHIBITOR SWITCH (D)
- A-5 INHIBITOR SWITCH (L)
- A-6 DCCSV (DAMPER CLUTCH CONTROL SOLENOID)
- A-7 SHIFT CONTROL SOLENOID B
- A-8 ACCELERATOR SWITCH
- A-9 COMPUTER GROUND (17 PIN CONNECTOR)
- A-10 12V POWER SOURCE (FUSE #10) (1986 GALANT FUSE #11)*
- A-11 INHIBITOR SWITCH (P)
- A-12 INHIBITOR SWITCH (N)
- A-13 INHIBITOR SWITCH (2)
- A-14 PCSV (OIL PRESSURE CONTROL SOLENOID)
- A-15 SHIFT CONTROL SOLENOID A
- A-16 BLANK
- A-17 IGNITION COIL

#### 13 PIN CONNECTOR

B7	B1
B8	B2
B9	B3
B10	X
B11	B4
B12	B5
B13	B6

- B-1 PULSE GENERATOR A
- B-2 PULSE GENERATOR B
- B-3 BLANK
- B-4 BLANK
- B-5 BLANK
- B-6 BLANK
- B-7 PULSE GENERATOR A
- B-8 PULSE GENERATOR B
- B-9 KICKDOWN SERVO SWITCH
- B-10 THROTTLE POSITION SENSOR
- B-11 VEHICLE SPEED SENSOR
- B-12 DIAGNOSTIC OUTPUT
- B-13 COMPUTER GROUND (13 PIN CONNECTOR)

**\*NOTE:** ALL CONNECTORS ARE VIEWED FROM THE PIN SIDE



## 1987-88 GALANT

### Transaxle Computer Pin ID

#### 17 PIN CONNECTOR

A9	A1
A10	A2
A11	A3
A12	A4
A13	X
A14	A5
A15	A6
A16	A7
A17	A8

- A-1 INHIBITOR SWITCH (R)
- A-2 INHIBITOR SWITCH (D)
- A-3 INHIBITOR SWITCH (L)
- A-4 INHIBITOR SWITCH (P)
- A-5 INHIBITOR SWITCH (N)
- A-6 INHIBITOR SWITCH (2)
- A-7 BLANK
- A-8 12V POWER SOURCE (FUSE #11)
- A-9 IGNITION COIL
- A-10 CRUISE CONTROL
- A-11 ACCELERATOR SWITCH
- A-12 OIL PRESSURE CONTROL SOLENOID (PCSV)
- A-13 DAMPER CLUTCH CONTROL SOLENOID (DCCSV)
- A-14 SHIFT SOLENOID B
- A-15 SHIFT SOLENOID A
- A-16 THERMO SWITCH
- A-17 COMPUTER GROUND (17 PIN CONNECTOR)

#### 13 PIN CONNECTOR

B7	B1
B8	B2
B9	B3
B10	X
B11	B4
B12	B5
B13	B6

- B-1 THROTTLE POSITION SENSOR
- B-2 BLANK
- B-3 VEHICLE SPEED SENSOR
- B-4 BLANK
- B-5 BLANK
- B-6 DIAGNOSTIC CONNECTOR
- B-7 KICKDOWN SERVO SWITCH
- B-8 COMPUTER GROUND (13 PIN CONNECTOR)
- B-9 PULSE GENERATOR B
- B-10 PULSE GENERATOR B
- B-11 PULSE GENERATOR A
- B-12 PULSE GENERATOR A
- B-13 BLANK



## 1989-90 SIGMA

### TRANSAXLE COMPUTER PIN ID

#### 20 PIN CONNECTOR

10	1
11	2
12	3
13	4
14	5
15	X
16	X
17	6
18	7
19	8
20	9

- 1 BLANK
- 2 CRUISE CONTROL
- 3 INHIBITOR SWITCH (R)
- 4 INHIBITOR SWITCH (D)
- 5 INHIBITOR SWITCH (L)
- 6 BLANK
- 7 SHIFT CONTROL SOLENOID A\*
- 8 ACCELERATOR PEDAL SWITCH
- 9 POWER/ECONOMY MODE SWITCH
- 10 COMPUTER GROUND (20 PIN CONNECTOR)\*
- 11 INHIBITOR SWITCH 12V POWER SUPPLY (FUSE #10)*
- 12 INHIBITOR SWITCH (P)
- 13 INHIBITOR SWITCH (N)
- 14 INHIBITOR SWITCH (2)
- 15 OIL PRESSURE CONTROL SOLENOID (PCSV)
- 16 SHIFT CONTROL SOLENOID B\*
- 17 BLANK\*
- 18 ENGINE RPM SIGNAL\*
- 19 DIAGNOSTIC CONNECTOR\*
- 20 A/C CONTROL UNIT\*

#### 13 PIN CONNECTOR

57	51
58	52
59	53
60	X
61	54
62	55
63	56

- 51 PULSE GENERATOR A
- 52 PULSE GENERATOR B
- 53 KICKDOWN SERVO SWITCH
- 54 KICKDOWN SERVO SWITCH
- 55 BLANK
- 56 COMPUTER 12V POWER SUPPLY (FUSE #1)*
- 57 PULSE GENERATOR A
- 58 PULSE GENERATOR B
- 59 KICKDOWN SERVO SWITCH
- 60 THROTTLE POSITION SENSOR
- 61 VEHICLE SPEED SENSOR
- 62 A/T FLUID TEMPERATURE SENSOR
- 63 COMPUTER GROUND (13 PIN CONNECTOR)

\* INDICATES PIN DIFFERENCES FOR 1989-90 SIGMA 20 PIN CONNECTOR  
SEE PAGE 21 FOR 1990 DIFFERENCES



## 1990 SIGMA ONLY

### 20 PIN CONNECTOR ID

20 PIN  
CONNECTOR

10	1
11	2
12	3
13	4
14	5
15	X
16	X
17	6
18	7
19	8
20	9

- 1 BLANK
- 2 CRUISE CONTROL
- 3 INHIBITOR SWITCH (R)
- 4 INHIBITOR SWITCH (D)
- 5 INHIBITOR SWITCH (L)
- 6 BLANK
- 7 SHIFT CONTROL SOLENOID B\*
- 8 ACCELERATOR PEDAL SWITCH
- 9 POWER/ECONOMY MODE SWITCH
- 10 DIAGNOSTIC CONNECTOR\*
- 11 INHIBITOR SWITCH 12V POWER SUPPLY (FUSE #10)
- 12 INHIBITOR SWITCH (P)
- 13 INHIBITOR SWITCH (N)
- 14 INHIBITOR SWITCH (2)
- 15 OIL PRESSURE CONTROL SOLENOID (PCSV)
- 16 SHIFT CONTROL SOLENOID A\*
- 17 MPI COMPUTER\*
- 18 NOISE FILTER\*
- 19 COMPUTER GROUND (20 PIN CONNECTOR)
- 20 MPI COMPUTER\*

\*INDICATES 1989-90 SIGMA 20 PIN CONNECTOR DIFFERENCES  
THE 13 PIN CONNECTORS ARE IDENTICAL

# OEM's use

- Softens harsh shifts with no loss of lock-up time
- Eliminates objectionable noises during shifts
- Optimizes overall transmission performance
- Prevents lock-up torque converter shudder
- Inhibits oxidation and overheating
- Eliminates hung-up governors
- Prevents clutch chatter
- Increases fluid life
- Keeps valves free
- OEM endorsed

## shouldn't you?



**SAAB**

### Parts & Service Information

**Subject: Automatic Transmission  
Upshift Noise**

**Application: 9000 Models with ZF Automatic  
Transmission**

CATEGORY	
Transmission	
SECTION 4	PAGE 14
ISSUE 06/93-0352	CODE 442

Some complaints have been received from owners of 9000 cars equipped with the ZF 4HP18 automatic transmission of a noise that occurs at the 2 - 3 upshift point. The noise may be described as a "squawk" or "moan" that usually occurs under light throttle pressure. A transmission fluid additive has been tested and approved for use as a service solution to address these complaints.

Before this fluid supplement can be added, the condition of the transmission fluid must be checked. If there are any indications of either burned or contaminated fluid, this may be the actual cause of the noise. In this case, addition of the fluid supplement will not cure the complaint.

It should be noted that the specific noise described in this PSI does not indicate any mechanical failure, or impending failure. It may, however, be an irritant to the car owner and should be addressed.

#### Cars Affected:

9000 models with ZF automatic transmission.

#### Parts:

LUBEGARD ATF SUPPLEMENT, 10 fl.oz. (296ml) bottle (5.0 fl.oz. (150ml) required per car).

#### NOTE

LUBEGARD ATF SUPPLEMENT can be obtained through any of the distributors listed on the following pages. Minimum order quantities and prices may vary.

#### Action:

1. Evaluate the condition of the transmission fluid. If coolant or other contaminants are found in the fluid, do not add this supplement. The source of the contamination must be determined and rectified.
2. Add 5.0 fl.oz. (150ml) of LUBEGARD to the transmission fluid. Check the fluid level and top off with Dexron II if necessary.
3. Road test the vehicle to ensure that no other transmission related problems exist.
4. Return the vehicle to the owner and counsel them on the following:

The vehicle should be driven under their normal driving conditions to allow the LUBEGARD to circulate throughout the transmission.





Figure 1. LUBEGARD ATF SUPPLEMENT



<input type="checkbox"/> FILE	<input type="checkbox"/> CIRCULATE			
-------------------------------	------------------------------------	--	--	--

**INTERNATIONAL  
LUBRICANTS INC.**

SEATTLE, WA 98108  
(206) 762-5343  
1-800-333-LUBE (5823)



# 1995 SEMINAR INFORMATION VIDEO

23

## 1989-90 GALANT 1990 ECLIPSE 1990 LASER/TALON

### Transaxle Computer Pin ID

#### 20 PIN CONNECTOR

10	1
11	2
12	3
13	4
14	5
15	X
16	X
17	6
18	7
19	8
20	9

- 1 DIAGNOSTIC CONNECTOR
- \*2 CRUISE CONTROL
- 3 INHIBITOR SWITCH (R)
- 4 INHIBITOR SWITCH (D)
- 5 INHIBITOR SWITCH (L)
- 6 DAMPER CLUTCH CONTROL SOLENOID (DCCSV)
- \*7 SHIFT SOLENOID A
- 8 ACCELERATOR SWITCH
- 9 POWER / ECONOMY SWITCH
- 10 COMPUTER GROUND (20 PIN CONNECTOR)
- 11 INHIBITOR SWITCH 12V POWER SOURCE (FUSE #6)**  
**(FUSE #7-LASER/TALON)**
- 12 INHIBITOR SWITCH (P)
- 13 INHIBITOR SWITCH (N)
- 14 INHIBITOR SWITCH (2)
- 15 OIL PRESSURE CONTROL SOLENOID (PCSV)
- \*16 SHIFT SOLENOID B
- \*17 OVERDRIVE SWITCH
- \*18 IGNITION COIL
- 19 DIAGNOSTIC CONNECTOR
- \*20 ENGINE COMPUTER

#### 13 PIN CONNECTOR

57	51
58	52
59	53
60	X
61	54
62	55
63	56

- 51 PULSE GENERATOR A
- 52 PULSE GENERATOR B
- 53 KICKDOWN SERVO SWITCH / A/T FLUID TEMP SENSOR
- 54 KICKDOWN SERVO SWITCH
- 55 BLANK
- \*56 COMPUTER 12V POWER SOURCE (FUSE #17)**
- 57 PULSE GENERATOR A
- 58 PULSE GENERATOR B
- 59 KICKDOWN SERVO SWITCH
- 60 THROTTLE POSITION SENSOR
- 61 VEHICLE SPEED SENSOR
- 62 A/T FLUID TEMPERATURE SENSOR
- 63 COMPUTER GROUND (13 PIN CONNECTOR)

#### \*1990 ECLIPSE ONLY

- 2 OVERDRIVE SWITCH/CRUISE CONTROL
- 7 SHIFT SOLENOID B
- 16 SHIFT SOLENOID A
- 17 BLANK
- 18 NOISE FILTER
- 20 DUAL PRESSURE SWITCH
- 56 COMPUTER 12V POWER SOURCE (FUSE #19)**



## 1995 SEMINAR INFORMATION

24

### VIDEO

1991-92 GALANT

1991-93 ECLIPSE

1991-92 LASER/TALON


1992 EXPO, SUMMIT WAGON & VISTA WAGON

1991-92 STEALTH & 3000GT

1992 DIAMANTE


### TRANSAXLE COMPUTER PIN ID

18 PIN  
CONNECTOR




- 1 COMPUTER GROUND (18 PIN CONNECTOR)
- 2 BLANK
- 3 ACCELERATOR PEDAL SWITCH
- 4 BLANK
- 5 DIAGNOSTIC CONNECTOR
- 6 ENGINE COOLANT TEMP SWITCH\A/C DUAL PRESSURE SWITCH
- 7 BLANK (ENGINE COMPUTER-DIAMANTE ONLY)
- 8 DIAGNOSTIC CONNECTOR
- 9 BLANK (ENGINE COMPUTER-DIAMANTE ONLY)
- 10 *COMPUTER 12V POWER SOURCE (FUSE #17-GALANT, FUSE #19-ECLIPSE, LASER & TALON)*
- 11 KICKDOWN SERVO SWITCH
- 12 BLANK (ENGINE COMPUTER-ECLIPSE, LASER & TALON)(THROTTLE POSITION SENSOR-DIAMANTE ONLY)
- 13 BLANK (TRACTION CONTROL-DIAMANTE ONLY)
- 14 A/T FLUID TEMPERATURE SENSOR
- 15 A/T FLUID TEMPERATURE SENSOR
- 16 THROTTLE POSITION SENSOR
- 17 A/T FLUID TEMPERATURE SENSOR
- 18 VEHICLE SPEED SENSOR (AUTOMATIC CLIMATE CONTROL-DIAMANTE ONLY)

10 PIN  
CONNECTOR



- 101 DAMPER CLUTCH CONTROL SOLENOID (DCCSV)
- 102 SHIFT CONTROL SOLENOID A
- 103 BLANK (GALANT) A/T FLUID TEMP INDICATOR (ECLIPSE, LASER & TALON)
- 104 *COMPUTER 12V POWER SUPPLY (FUSE #6-GALANT ONLY) (INHIBITOR SWITCH 12V POWER SUPPLY-FUSE #7, ECON/POWER SWITCH, CRUISE CONTROL-STEALTH, 3000GT & DIAMANTE ONLY)*
- 105 COMPUTER GROUND
- 106 OIL PRESSURE CONTROL SOLENOID (PCSV)
- 107 SHIFT CONTROL SOLENOID B
- 108 BLANK(GALANT) (ENGINE COMPUTER-STEALTH, 3000GT & DIAMANTE ONLY)
- 109 *INHIBITOR SWITCH 12V POWER SUPPLY (FUSE #18) (FUSE #6 GALANT ONLY) COMPUTER 12V POWER (FUSE #7-STEALTH, 3000GT & DIAMANTE ONLY)*
- 110 COMPUTER GROUND (10 PIN CONNECTOR)

14 PIN  
CONNECTOR



- 51 INHIBITOR SWITCH (P)
- 52 INHIBITOR SWITCH (R)
- 53 INHIBITOR SWITCH (N)
- 54 INHIBITOR SWITCH (D)
- 55 INHIBITOR SWITCH (2)
- 56 INHIBITOR SWITCH (L)
- 57 CRUISE CONTROL
- 58 PULSE GENERATOR B
- 59 PULSE GENERATOR B
- 60 PULSE GENERATOR A
- 61 PULSE GENERATOR A
- 62 COMPUTER GROUND (14 PIN CONNECTOR)
- 63 NOISE FILTER/POWER TRANSISTOR
- 64 POWER/ECONOMY SWITCH/OVERDRIVE SWITCH

*Automatic Transmission Service Group*





## VIDEO

### 1993-94 GALANT

### 1993 COLT VISTA, EXPO & SUMMIT WAGON

### 1993 STEALTH, 3000GT & DIAMANTE

#### TRANSAXLE COMPUTER PIN ID

26 PIN  
CONNECTOR

14	1
15	2
16	3
17	4
18	5
19	6
20	7
21	8
22	9
23	10
24	11
25	12
26	13

16 PIN  
CONNECTOR

59	51
60	52
61	53
62	54
63	55
64	56
65	57
66	58

- 1 DAMPER CLUTCH CONTROL SOLENOID (DCCSV)
- 2 SHIFT CONTROL SOLENOID A
- 3 BLANK-GALANT & DIAMANTE (A/T TEMP.INDICATOR LAMP-EXPO, SUMMIT & VISTA)(ACCELERATOR SWITCH-STEALTH & 3000GT ONLY)
- 4 BLANK (ENGINE COMPUTER-STEALTH, 3000GT & DIAMANTE ONLY)
- 5 BLANK
- 6 BLANK
- 7 KICKDOWN SERVO SWITCH
- 8 DUAL PRESSURE SWITCH
- 9 DIAGNOSTIC CONNECTOR
- 10 BLANK (TRACTION CONTROL-DIAMANTE ONLY)
- 11 DIAGNOSTIC CONNECTOR
- 12 *INHIBITOR SWITCH 12V POWER SUPPLY (FUSE #6)(O/D SWITCH-VISTA, EXPO & SUMMIT)(INHIBITOR SWITCH 12V POWER SUPPLY, POWER/ECONOMY SWITCH & CRUISE CONTROL-STEALTH, 3000GT & DIAMANTE ONLY-FUSE #7)*
- 13 COMPUTER GROUND (26 PIN CONNECTOR)
- 14 OIL PRESSURE CONTROL SOLENOID (PCSV)
- 15 SHIFT CONTROL SOLENOID B
- 16 BLANK
- 17 BLANK (ENGINE COMPUTER-DOHC STEALTH, 3000GT & DIAMANTE)
- 18 BLANK (ENGINE COOLANT TEMP. SENSOR-STEALTH & 3000GT ONLY)(ENGINE COMPUTER-DIAMANTE ONLY)
- 19 BLANK
- 20 THROTTLE POSITION SENSOR (5V POWER SUPPLY)
- 21 THROTTLE POSITION SENSOR (SENSOR OUTPUT)
- 22 BLANK
- 23 ATF FLUID TEMPERATURE SENSOR
- 24 ATF FLUID TEMPERATURE SENSOR
- 25 *COMPUTER 12V POWER SUPPLY (FUSE #6)(FUSE #7 STEALTH & 3000GT ONLY)(SAME AS PIN #12 DIAMANTE ONLY)*
- 26 COMPUTER GROUND (26 PIN CONNECTOR)
- 51 INHIBITOR SWITCH (P)
- 52 INHIBITOR SWITCH (R)
- 53 INHIBITOR SWITCH (N)
- 54 INHIBITOR SWITCH (D)
- 55 INHIBITOR SWITCH (2)
- 56 INHIBITOR SWITCH (L)
- 57 CRUISE CONTROL (O/D SWITCH-STEALTH & 3000GT ONLY)
- 58 POWER/ECONOMY MODE SWITCH (BLANK-EXPO, SUMMIT & VISTA)
- 59 *COMPUTER 12V POWER SOURCE (FUSE #17)(CRUISE CONTROL SWITCH-STEALTH, 3000GT & DIAMANTE ONLY)*
- 60 VEHICLE SPEED SENSOR (CLIMATE CONTROL-DIAMANTE ONLY)
- 61 PULSE GENERATOR B
- 62 PULSE GENERATOR B
- 63 PULSE GENERATOR A
- 64 PULSE GENERATOR A
- 65 COMPUTER GROUND (16 PIN CONNECTOR)
- 66 ENGINE RPM SIGNAL

## 1990 COLT, MIRAGE & SUMMIT

### TRANSAXLE COMPUTER PIN ID

#### 20 PIN CONNECTOR

10	1
11	2
12	3
13	4
14	5
15	X
16	X
17	6
18	7
19	8
20	9

- 1 DIAGNOSTIC CONNECTOR
- 2 CRUISE CONTROL
- 3 INHIBITOR SWITCH (R)
- 4 INHIBITOR SWITCH (D)
- 5 INHIBITOR SWITCH (L)
- 6 DAMPER CLUTCH CONTROL VALVE (DCCSV)
- 7 SHIFT CONTROL SOLENOID B
- 8 ACCELERATOR PEDAL SWITCH
- 9 BLANK
- 10 COMPUTER GROUND (20 PIN CONNECTOR)
- 11 **COMPUTER 12V POWER SUPPLY (FUSE #4)**
- 12 INHIBITOR SWITCH (P)
- 13 INHIBITOR SWITCH (N)
- 14 INHIBITOR SWITCH (2)
- 15 OIL PRESSURE CONTROL SOLENOID (PCSV)
- 16 SHIFT CONTROL SOLENOID A
- 17 BLANK
- 18 POWER TRANSISTOR
- 19 DIAGNOSTIC CONNECTOR
- 20 DUAL PRESSURE SWITCH

#### 13 PIN CONNECTOR

57	51
58	52
59	53
60	X
61	54
62	55
63	56


- 51 PULSE GENERATOR A
- 52 PULSE GENERATOR B
- 53 A/T FLUID TEMPERATURE SENSOR
- 54 KICKDOWN SERVO SWITCH
- 55 BLANK
- 56 **COMPUTER 12V POWER SUPPLY (FUSE #8)**
- 57 PULSE GENERATOR A
- 58 PULSE GENERATOR B
- 59 KICKDOWN SERVO SWITCH
- 60 MPI COMPUTER/THROTTLE POSITION SENSOR
- 61 VEHICLE SPEED SENSOR
- 62 A/T FLUID TEMPERATURE SENSOR
- 63 COMPUTER GROUND (13 PIN CONNECTOR)



## 1991-92 COLT, MIRAGE & SUMMIT


### TRANSAXLE COMPUTER PIN ID

#### 18 PIN CONNECTOR




- 1 COMPUTER GROUND
- 2 BLANK
- 3 ACCELERATOR PEDAL SWITCH
- 4 BLANK
- 5 DIAGNOSTIC CONNECTOR
- 6 DUAL PRESSURE SWITCH (A/C)
- 7 BLANK
- 8 DIAGNOSTIC CONNECTOR
- 9 BLANK
- 10 COMPUTER 12V POWER SUPPLY (FUSE #8)**
- 11 KICKDOWN SERVO SWITCH
- 12 COMPUTER GROUND
- 13 POWER TRANSISTOR/NOISE FILTER
- 14 A/T FLUID TEMPERATURE SENSOR
- 15 BLANK
- 16 THROTTLE POSITION SENSOR
- 17 A/T FLUID TEMPERATURE SENSOR
- 18 VEHICLE SPEED SENSOR

#### 10 PIN CONNECTOR



- 101 DAMPER CLUTCH CONTROL SOLENOID (DCCSV)
- 102 SHIFT CONTROL SOLENOID A
- 103 BLANK
- 104 COMPUTER 12V POWER SUPPLY (FUSE # 4)**
- 105 COMPUTER GROUND
- 106 OIL PRESSURE CONTROL VALVE (PCSV)
- 107 SHIFT CONTROL VALVE B
- 108 BLANK
- 109 INHIBITOR SWITCH 12V POWER SUPPLY (FUSE #4)/O/D SWITCH**
- 110 COMPUTER GROUND

#### 14 PIN CONNECTOR



- 51 INHIBITOR SWITCH (P)
- 52 INHIBITOR SWITCH (R)
- 53 INHIBITOR SWITCH (N)
- 54 INHIBITOR SWITCH (D)
- 55 INHIBITOR SWITCH (2)
- 56 INHIBITOR SWITCH (L)
- 57 CRUISE CONTROL
- 58 PULSE GENERATOR B
- 59 PULSE GENERATOR B
- 60 PULSE GENERATOR A
- 61 PULSE GENERATOR A
- 62 BLANK
- 63 BLANK
- 64 BLANK



## 1993 COLT, MIRAGE & SUMMIT TRANSAXLE COMPUTER PIN ID

26 PIN  
CONNECTOR

14	1
15	2
16	3
17	4
18	5
19	6
20	7
21	8
22	9
23	10
24	11
25	12
26	13

- 1 DAMPER CLUTCH CONTROL SOLENOID (DCCSV)
- 2 SHIFT CONTROL SOLENOID B
- 3 BLANK
- 4 BLANK
- 5 BLANK
- 6 BLANK
- 7 KICKDOWN SERVO SWITCH
- 8 A/C TRIPLE SWITCH
- 9 DATA LINK CONNECTOR
- 10 BLANK
- 11 DATA LINK CONNECTOR
- 12 *COMPUTER 12V POWER SOURCE (FUSE #17)*
- 13 COMPUTER GROUND
- 14 OIL PRESSURE CONTROL SOLENOID (PCSV)
- 15 SHIFT CONTROL SOLENOID A
- 16 BLANK
- 17 BLANK
- 18 BLANK
- 19 BLANK
- 20 ENGINE COMPUTER (ECM)
- 21 ENGINE COMPUTER (ECM)
- 22 BLANK
- 23 A/T FLUID TEMPERATURE SENSOR
- 24 A/T FLUID TEMPERATURE SENSOR
- 25 OVERDRIVE SWITCH
- 26 COMPUTER GROUND

16 PIN  
CONNECTOR

59	51
60	52
61	53
62	54
63	55
64	56
65	57
66	58

- 31 INHIBITOR SWITCH (P)
- 32 INHIBITOR SWITCH (R)
- 33 INHIBITOR SWITCH (N)
- 34 INHIBITOR SWITCH (D)
- 35 INHIBITOR SWITCH (2)
- 36 INHIBITOR SWITCH (L)
- 37 CRUISE CONTROL
- 38 BLANK
- 39 *COMPUTER 12V POWER SOURCE (FUSE #14)*
- 40 VEHICLE SPEED SENSOR
- 41 PULSE GENERATOR B
- 42 PULSE GENERATOR B
- 43 PULSE GENERATOR A
- 44 PULSE GENERATOR A
- 45 COMPUTER GROUND
- 46 *COMPUTER 12V POWER SOURCE (FUSE #14)*



## 1989 HYUNDAI SONATA

### TRANSAXLE COMPUTER PIN ID

20 PIN  
CONNECTOR

A10	A1
11	2
12	3
13	4
14	5
15	X
16	X
17	6
18	7
19	8
20	9

- A1 ENGINE COOLANT TEMPERATURE SENSOR
- 2 OVERDRIVE SWITCH
- 3 INHIBITOR SWITCH (R)
- 4 INHIBITOR SWITCH (D)
- 5 INHIBITOR SWITCH (L)
- 6 DAMPER CLUTCH CONTROL SOLENOID (DCCSV)
- 7 SHIFT CONTROL SOLENOID B (SCSV)
- 8 ACCELERATOR PEDAL SWITCH
- 9 BLANK
- 10 COMPUTER GROUND
- 11 *COMPUTER & INHIBITOR SWITCH 12V POWER SUPPLY*
- 12 INHIBITOR SWITCH (P )
- 13 INHIBITOR SWITCH ( N)
- 14 INHIBITOR SWITCH (2)
- 15 OIL PRESSURE CONTROL SOLENOID (PCSV)
- 16 SHIFT CONTROL SOLENOID A (SCSV)
- 17 BLANK
- 18 ENGINE RPM SIGNAL
- 19 DIAGNOSTIC CONNECTOR
- 20 A/C LOAD SIGNAL

13 PIN  
CONNECTOR

B7	B1
8	2
9	3
10	X
11	4
12	5
13	6

- B1 PULSE GENERATOR A
- 2 PULSE GENERATOR B
- 3 BLANK
- 4 BLANK
- 5 BLANK
- 6 BLANK
- 7 PULSE GENERATOR A
- 8 PULSE GENERATOR B
- 9 KICKDOWN SERVO SWITCH
- 10 THROTTLE POSITION SENSOR
- 11 VEHICLE SPEED SENSOR
- 12 BLANK
- 13 COMPUTER GROUND



**1990-93 MITSUBISHI PRECIS**  
**1990-93 HYUNDAI EXCEL**  
**1990-93 HYUNDAI SONATA**  
**1991-93 HYUNDAI SCOUPE**  
**1992-93 HYUNDAI ELANTRA**

**TRANSAXLE COMPUTER PIN ID**

**20 PIN  
CONNECTOR**

A10	A1
11	2
12	3
13	4
14	5
15	X
16	X
17	6
18	7
19	8
20	9

- 1 ECT SWITCH
- 2 ACCELERATOR PEDAL SWITCH
- 3 SHIFT CONTROL SOLENOID B (SCSV)
- 4 DAMPER CLUTCH SOLENOID (DCSV)
- 5 INHIBITOR SWITCH (L)
- 6 INHIBITOR SWITCH (D)
- 7 INHIBITOR SWITCH (R)
- 8 OVERDRIVE SWITCH
- 9 DIAGNOSTIC CONNECTOR
- 10 A/C SIGNAL
- 11 DIAGNOSTIC CONNECTOR (OUTPUT)
- 12 ENGINE RPM SIGNAL
- 13 BLANK
- 14 SHIFT CONTROL SOLENOID A (SCSV)
- 15 OIL PRESSURE CONTROL SOLENOID (PCSV)
- 16 INHIBITOR SWITCH (2)
- 17 INHIBITOR SWITCH (N)
- 18 INHIBITOR SWITCH (P)
- 19 INHIBITOR SWITCH 12V POWER SUPPLY (FUSE #10)
- 20 COMPUTER GROUND

**13 PIN  
CONNECTOR**

B7	B1
8	2
9	3
10	X
11	4
12	5
13	6

- 1 COMPUTER 12V POWER SUPPLY (FUSE #5)
- 2 BLANK
- 3 BLANK
- 4 A/T FLUID TEMPERATURE SENSOR (GROUND)
- 5 PULSE GENERATOR B
- 6 PULSE GENERATOR A
- 7 COMPUTER GROUND
- 8 A/T FLUID TEMPERATURE SENSOR
- 9 VEHICLE SPEED SENSOR
- 10 THROTTLE POSITION SENSOR
- 11 KICKDOWN SERVO SWITCH
- 12 PULSE GENERATOR B
- 13 PULSE GENERATOR A



# 1995 SEMINAR INFORMATION

## VIDEO

31

### HONDA TRANSAXLE MODEL APPLICATION CHART

#### CIVIC

1986-87	CIVIC	4 SPEED	CA
1988-90	CIVIC	4 SPEED	L4
1989-90	CIVIC WAGON	4 SPEED...4WD...3 SHAFT	S5
1991	CIVIC	4 SPEED	ML4A
1991	CIVIC WAGON	4 SPEED...4WD...3 SHAFT	MPSA
1992-94	CIVIC	4 SPEED...3 SHAFT	M24A

#### ACCORD

1983	ACCORD	4 SPEED...W/LOCK-UP	AK
1984-85	ACCORD	4 SPEED ...CARBURETED	AS
1986-89	ACCORD	4 SPEED...FUEL INJECTED	F4
1990	ACCORD	4 SPEED...3 SHAFT	PX4B
1991-93	ACCORD...U.S. BUILT	4 SPEED...3 SHAFT	APX4
1991-93	ACCORD...JAPAN BUILT	4 SPEED...3 SHAFT	*MPWA
1994	ACCORD	4 SPEED...3 SHAFT	MPOA

**NOTE:** The ACCORD MPWA is totally different than the VIGOR MPWA. The ACCORD unit is transversely mounted, while the VIGOR unit is longitudinally mounted.

#### PRELUDE

1983	PRELUDE	4 SPEED	AK
1984	PRELUDE	4 SPEED...CARBURETED	AS
1985-87	PRELUDE	4 SPEED...FUEL INJECTED	F4
1988-89	PRELUDE	4 SPEED	K4
1990	PRELUDE	4 SPEED	PY8A
1991	PRELUDE	4 SPEED	MY8A
1992-93	PRELUDE	4 SPEED...3 SHAFT	MP1A

#### PASSPORT

1994	PASSPORT	4 SPEED...RWD...4WD	4L30E
------	----------	---------------------	-------



## ACURA TRANSAXLE MODEL APPLICATION CHART

### INTEGRA

1986-87	INTEGRA	4 SPEED	CA
1988-89	INTEGRA	4 SPEED	P1
1990	INTEGRA	4 SPEED...3 SHAFT...W/MODULATOR	RO
1991-93	INTEGRA	4 SPEED...3 SHAFT...W/MODULATOR	MPRA

### LEGEND

1986-87	LEGEND...SEDAN	4 SPEED	G4
1987	LEGEND...COUPE	4 SPEED	L5
1988-89	LEGEND	4 SPEED	L5
1990	LEGEND	4 SPEED	PPL5X
1991-1993	LEGEND	4 SPEED...IN-LINE...W/PAN	MPYA

### VIGOR

1992-93	VIGOR	4 SPEED...IN-LINE...W/PAN	*MPWA
---------	-------	---------------------------	-------

**\*NOTE:** The VIGOR MPWA unit is totally different than the ACCORD MPWA unit. The VIGOR unit is longitudinally mounted, while the ACCORD unit is mounted transversely.

### NSX

1991-93	NSX	4 SPEED...3 SHAFT	M9RA
---------	-----	-------------------	------

### STERLING


1986-87	825-827 SI	4 SPEED	G4
1988-90	825-827SI	4 SPEED	L5




# TIME SAVING TOOLS DESIGNED FOR YOU, THE TRANSMISSION TECHNICIAN

ALL TOOLS IN STOCK  
READY FOR IMMEDIATE  
DELIVERY

**NEW**




**Universal Front Wheel Drive  
Hub & Bearing  
Remover & Installer Kit**  
95% of all Hubs



**RHINO  
Trio Dead-Blow Slide Hammer**



**"Longer"  
UNIVERSAL  
END CLEARANCE  
GAUGE**

**E-Z UNIVERSAL  
SPEEDOMETER GEAR  
INSTALLER**



**BIG 3  
FRONT PUMP  
PULLER**  
FORD, G.M., CHRYSLER U.S. PAT 5,243,749

**NEW**



**NISSAN RL4F02A**

**CONVERTOR SEAL DRIVER**

**RIGHT & LEFT AXLE SEAL INSTALLER**

**NEW**


**Universal Quick Lock  
Clutch Spring Compressor  
Model No: 2987A**

Ideal for all clutches  
even GM 350 and Chrysler  
604 - in the case.

Ring Adapters for  
Compressing Diaphragm Springs




## TOOLS FROM A TO Z



**AXEL SEAL INSTALLER  
#1250**




**CLUTCH SPRING  
COMPRESSOR KIT  
#2987 U.S. PATENT**



**UNIVERSAL BUSHING  
DRIVER SET  
#1001**



**P.R. VALVE SNAP  
RING INSTALLER  
#2993  
U.S. PATENT**



**#280  
SEAL PULLER**



**PUMP ALIGNMENT  
TOOLS**



**#125  
BUSHING DRIVERS BY  
TRANSMISSION TYPE**



**#350**



**U.S. PATENT  
TUFFY  
#2994**



**LO/REV. CLUTCH TOOLS  
#125-200  
U.S. PATENT**



**EXT. HOUSING BUSHING  
TOOL #2200  
U.S. PATENT**



**BUSHING EXTRACTORS  
#280B #280A**



**#280C  
BUSHING & SEAL CUTTER  
U.S. PATENT**




**#2995**



**CHRYSLER  
BEARING CUP & CONE  
SERVICE TOOLS**  
U.S. PATENT NO. 4339865



**NISSAN**



**U.S. PATENT  
#2997**

**RACE DRIVER**

**GEAR & PUMP PULLER**

CALL FOR  
CATALOG



ALL TOOLS AND PARTS MADE IN USA

CALL US TODAY AND SAVE!  
To take advantage of our  
A.T.S.G. Seminar promotional pricing.



COD Welcome

GUARANTEED **A to Z TOOL, INC.** • 446 W. ST. CHARLES ROAD • VILLA PARK, ILLINOIS 60181 • (708) 279-4118  
AGAINST DEFECTS IN QUALITY AND WORKMANSHIP. FAX: (708) 279-4134

**CALL US TODAY!**

## HONDA/ACURA

### **BINDS IN REVERSE; MOVES FORWARD IN NEUTRAL; WANTS TO MOVE IN PARK**

**COMPLAINT:** Binds in reverse; moves forward in neutral; wants to move in park.

**CAUSE:** Improper indexing of the first gear hub to the low friction plates causing the last friction plate to be caught between the first gear hub and the piston.

**CORRECTION:** Make certain all three clutches have splined to the first gear hub. After tightening the mainshaft nut, make certain you can turn the clutch drum while holding the first gear hub. (Refer to Figure 24)




Figure 24

## HONDA TRANSAXLES

### DIFFERENTIAL CROSS SHAFT FAILURE


**COMPLAINT:** Failure of the differential cross shaft in the area of the cross shaft where the pinion gears rotate.

**CAUSE:** The cause may be the material from which the cross shaft was made.

**CORRECTION:** There is available from Honda, two new design differential cross shafts made of Titanium, that will eliminate the above complaint and should be installed during routine overhaul. (See figure 23) These Titanium cross shafts can easily be identified by their gold color.

The rolled pin that retains the cross shaft in the differential carrier should also be replaced with a different design. The original rolled pin, with the split that resembles a "ZIPPER" (See figure 23), should NEVER be used. ALWAYS replace it with a regular split type rolled pin of the proper dimension.

Refer to the chart in figure 23 for the dimensions and part numbers for the design differential cross shaft.



#### CROSS SHAFT DIMENSIONS

APPLICATION	SHAFT DIAMETER	SHAFT LENGTH	ROLL PIN HOLE DIAMETER	PART NUMBER
4 CYL.	.708"	4.069"	.161"	41321-PL3-TOO
6 CYL.	.708"	4.522"	.238"	41321-PL5-ZOO


Figure 23

## HONDA PX4B

### 1990 ACCORD

4 EXTERNAL SOLENOIDS  
2 EXTERNAL SPEED SENSORS  
STEERING PUMP DRIVEN VEHICLE SPEED SENSOR  
ELBOW VENT ON TOP REAR OF CASE  
PUSH-IN DIP STICK

**PX4B-0000000**



SHIFT SOLENOIDS-12 TO 24 OHMS...TCC SOLENOIDS-12 TO 24 OHMS  
VEHICLE SPEED SENSOR-0 TO 5V PER 1 REVOLUTION...NM & NC SPEED SENSORS-400 TO 600 OHMS

## HONDA PX4B

### GRINDING WHEN SHIFTING FROM DRIVE TO REVERSE

**Complaint:** Grinding noise when shifting from drive to reverse

**Cause:** Misassembly of the reverse selector assembly

**Correction:** In most Honda 4 speed transaxles, the reverse selector is installed with the **FLAT SIDE UP**, and the selector hub is installed with the groove facing up. (See Figure 25)  
The PX4B found in 1990 Accords, is just the **OPPOSITE!**  
The reverse selector is installed with the **STEPPED SIDE UP**, and the selector hub is installed with the notches facing up. (See Figure 26 on the following page).




Figure 25

## HONDA PX4B




Figure 26

**NOTE:** The HONDA/ACURA transaxles listed below also use the stepped side up/notched side up reverse selector assembly design.

1. MP1A
2. APX4
3. MPWA-JAPAN BUILT ACCORD
4. MPOA
5. MPWA-VIGOR

## HONDA PX4B SOFT OR FLARED 3-4 SHIFT

**COMPLAINT:** Soft or flared 3-4 shift; good reverse.

**CAUSE:** The PX4B uses a double action 4th/reverse accumulator. If the small accumulator "o" ring seal is leaking, (See figure 27) only the 3-4 shift will be affected as 4th gear oil leaks into the reverse circuit and could cause a soft or flared 3-4 shift. The 4th/reverse accumulator is the center accumulator piston located in the servo body section of the valve body assembly.

**CORRECTION:** Replace accumulator seals.




Figure 27

## HONDA PX4B TRANSAXLE END PLAY

**Complaint:** Setting endplay adjustments and measurements

**Cause:** Other than the final drive, the PX4B uses NO SELECTIVES to adjust endplay

**Correction:** The countershaft distance collar must measure 46mm (1.811") in length. (See figure 28)  
The secondary shaft distance collar must measure 5mm (.1969") in thickness. (See figure 29)  
All clutch collars and hardparts should not be undercut.  
The counter shaft nut should be torqued to no more than 145 ft. lbs.  
The main shaft and secondary shaft nuts should be torqued to no more than 116 ft. lbs.




Figure 28





Figure 29



## ACURA MPYA

### 1991-93 ACURA LEGEND

2 EXTERNAL SOLENOIDS  
2 EXTERNAL SPEED SENSORS  
REMOVABLE OIL PAN  
FILLER TUBE WITH PUSH-IN DIP STICK  
VENT ON TOP, CENTER OF BELL HOUSING



SHIFT SOLENOID/ LINEAR SOLENOID CONNECTOR  
LOCATED ON DRIVER SIDE OF TRANSAXLE



SHIFT SOLENOID TERMINAL A...GREEN WIRE...12-24 OHMS  
SHIFT SOLENOID TERMINAL B...BLUE WIRE...12-24 OHMS  
LINEAR SOLENOID TERMINAL C...RED WIRE (+)...5.0-5.6 OHMS  
LINEAR SOLENOID TERMINAL D...WHITE WIRE (-)...5.0-5.6 OHMS

## ACURA MPYA

### OIL PRESSURE CHECKS

#### PRESSURE TAP LOCATIONS




Figure 30

#### PRESSURE SPECIFICATIONS

LINE PRESSURE.....	@ 2000 rpm.....	in NEUTRAL or PARK.....	114-122 psi (800-860 kPa)
1st CLUTCH PRESSURE.....	@ 2000 rpm.....	in D4 or D3.....	113-123 psi (800-860 kPa)
2nd, 3rd & 4th CLUTCH PRESSURE.....	@ CLOSED THROTTLE.....	in D4.....	65 psi (460 kPa)
2nd, 3rd & 4th CLUTCH PRESSURE.....	@ HALF THROTTLE.....	in D4.....	123 psi (860 kPa)
1st & 2nd CLUTCH PRESSURE.....	@ 2000 rpm.....	in 2 or 1.....	113-123 psi (800-860 kPa)
1st HOLD CLUTCH PRESSURE.....	@ 2000 rpm.....	in 1.....	113-123 psi (800-860 kPa)
REVERSE CLUTCH PRESSURE.....	@ 2000 rpm.....	in REVERSE.....	169-181 psi (1190-1270 kPa)
THROTTLE "B" PRESSURE.....	@ 1000rpm.....	in D4... *12 VOLTS TO LINEAR SOLENOID.....	0-2 psi (0-15 kPa)
THROTTLE "B" PRESSURE.....	@ 1000rpm.....	in D4... LINEAR SOLENOID DISCONNECTED.....	84-91 psi (590-640 kPa)

\*This should be done quickly to avoid Linear Solenoid damage.

## ACURA MPYA HARSH SHIFT CONCERNS

**Complaint:** Harsh upshifts and harsh coast downshifts

**Cause:** Failure of the Linear Solenoid

**Correction:** The 1991 & up Acura Legend with the MPYA transaxle uses a pressure control solenoid called a Linear Solenoid, which is normally closed, to adjust shift feel. This now eliminates the need of a throttle cable to control throttle pressure "B".

The throttle "B" valve still regulates pressure to the accumulators and the clutch pressure control valve as it did in past designs, but now the computer is controlling throttle "B" pressure through the Linear Solenoid.

Therefore, failure of the Linear Solenoid or the signal to it or a sticking throttle valve could cause harsh upshifts, harsh coast downshifts or harsh kickdown.

The Linear Solenoid and the Shift Solenoids share a common connector, the Linear Solenoid specifications are listed below in figure 31.




Figure 31

## ACURA MPYA

### REVERSE SELECTOR ELIMINATED

In all Honda/Acura transaxles, a mechanical sliding clutch is used as a reaction member to assist in backward movement. This design has also resulted in noisy garage shifts and bind-ups in reverse. In the 1991 and up Acura Legend the sliding clutch has been eliminated and been replaced with a reverse clutch. Hydraulic pressure applies the reverse clutch. Power is transmitted from the mainshaft reverse gear through the reverse idler gear to the countershaft reverse gear. Rotation direction of the countershaft reverse gear is changed through the reverse idler gear in the rear cover. Power is then transmitted to the secondary drive gear and drives the secondary gear. The power flow in reverse is illustrated below in figure 32.






Figure 32

**ACURA MPYA**  
**ONE-WAY CLUTCH ROTATION**



2ND GEAR ONE-WAY CLUTCH

FIGURE 33



1ST GEAR ONE-WAY CLUTCH

FIGURE 34

## MAZDA G4A-HL

### SLIPPING IN DRIVE POSITION ALL SHIFTS SOFT AND/OR SLIPPING LOW LINE PRESSURE

**COMPLAINT:** Some MAZDA 323 models equipped with the G4A-HL transaxle may exhibit a slipping condition with selector lever in the Drive (D) position, all shifts will be soft and/or slipping, and if line pressure has been checked, line pressure will be low.

**CAUSE:** The cause is low line pressure, and may be created by misassembly of the Throttle Modulator Line-up in the valve body.

**CORRECTION:** Install the Throttle Modulator Valve Line-up into the valve body as shown in Figure 35. Install throttle modulator sleeve "C", throttle modulator rear spring, throttle modulator plug, throttle modulator valve and throttle modulator sleeve "B", throttle modulator front spring, throttle modulator sleeve "A", and the retaining pin, as shown in Figure 35.

**SPECIAL NOTE:**  
THROTTLE MODULATOR SLEEVE "A", HAS  
A VALVE INSIDE RETAINED BY A SNAP  
RING. THIS VALVE MUST BE FREE TO  
ACHIEVE PROPER LINE PRESSURE.




Figure 35

**FORD PROBE 4EAT/MAZDA 626 G4A-EL  
DISPLAYS 4-2-3-1 SHIFT PATTERN  
(AFTER REBUILD)**

**COMPLAINT:** After you have finished the rebuild and installed the transaxle back into the vehicle, it starts off in 4th gear, followed by a shift into 2nd gear, followed by a shift into 3rd gear, and then shifts into 1st gear. The last shift is sometimes described as a shift into neutral, because of vehicle speed at the time of the shift. The vehicle could also display a 1-2 Neutral shift when manual shifting through the shift pattern, and a slipping condition on heavy acceleration.

**CAUSE:** The cause may be the 1-2 shift solenoid and the 2-3 shift solenoid reversed in their locations in the valve body (See Figure 36).

**CORRECTION:** Install the shift solenoids in their proper locations, as shown in Figures 36 and 37. Use Figure 36 for the 1-2 and 2-3 shift solenoids, and Figure 37 on the following page, for the 3-4 and lockup.

**1-2 AND 2-3 SHIFT VALVE LOCATION**




Figure 36

**3-4 SHIFT AND LOCKUP SOLENOID LOCATIONS**




Figure 37



**FORD PROBE 4EAT/MAZDA 626 G4A-EL  
BIND UP IN REVERSE AND MANUAL LOW**

**COMPLAINT:** Bind-up when the selector lever is placed in Reverse or the Manual Low positions.  
Also may display premature 3-4 clutch failure.

**CAUSE:** The cause may be the scarf-cut Teflon sealing ring on the input shaft, leaking, which would allow converter release oil into the 3-4 clutch passage and apply the 3-4 clutch pack (See Figure 38).

**CORRECTION:** Install a new Teflon scarf-cut sealing ring in the input shaft groove, as shown in Figure 38.


**CAUTION: THERE ARE TWO DIFFERENT DIAMETERS OF THE G4A-EL INPUT SHAFT AND THEY REQUIRE DIFFERENT SIZE SEALING RINGS.**

One shaft has 21 turbine splines, and the journal diameter behind the splines is .902" in diameter.

One shaft has 25 turbine splines, and the journal diameter behind the is 1.092" in diameter.

Be very careful to select the proper size scarf cut sealing ring for the input shaft.

**G4A-EL INPUT SHAFT**



**CAUTION: THERE ARE TWO DIFFERENT DIAMETERS OF THE G4A-EL INPUT SHAFT, AND THEY REQUIRE DIFFERENT SIZE SCARF-CUT SEALING RINGS.**

Figure 38

## FORD 4EAT/MAZDA G4A-EL

### FRONT SEAL BLOWOUT OR CHRONIC LEAK

**COMPLAINT:** Continuous front seal leak or front seal forced out on to the Torque Converter "Hub" repeatedly.

**CAUSE:** **A:** Insufficient drainback passages in the Stator Support.

**B:** Worn or misplaced bushing in Torque Converter.

**CORRECTION:** **A:** Remove Stator Support and bearing race. With Drill or Die Grinder enlarge and deepen the factory drainback passage in the "Rear" of the Stator Support as shown in Figure 39. Notice the drainback hole and the passage to "Dotted Line" enlarged.

**B:** Measure dimension "A" in figure 40, then measure dimension "C" in Figure 41. Subtract C from A and ensure the difference is .003"-.006". Also check the clearance between the bushing and the top of the converter hub. The bushing should be "Recessed" approximately .078" to .125" as shown in Figure 40, dimension "B".




Figure 39




Figure 40




Figure 41



**FORD F4EAT**  
**SLIPS IN 2ND AND 4TH**  
**AND/OR NO 2ND AND 4TH**

**COMPLAINT:** Vehicle exhibits a slipping condition going into 2nd gear, at times slipping through 2nd and on into 3rd gear, and a slipping condition going into 4th gear. Obviously this will also burn the 2-4 band. In severe conditions there will be NO 2nd gear, and NO 4th gear. The vehicle will shift 1-3 only.

**CAUSE:** The cause may be a clogged or partially clogged 2-4 servo feed orifice. The 2-4 servo feed orifice is only .038" in diameter, and will not tolerate much debris before the slipping condition will exist. If the 2-4 servo orifice becomes totally closed, there will be NO 2nd gear, and NO 4th gear. Another cause for NO 2nd and NO 4th gears could be a checkball that has been installed in the wrong location in the Premain valve body, as shown in Figure 43.

**CORRECTION:** Remove the 2-4 servo feed orifice assembly using a 10mm Hex socket. Refer to Figure 42 for the location in the case. Thoroughly clean the 2-4 servo orifice and all case passages with clean solvent. The spring in this assembly is larger on one end, and the larger end goes into the Hex bolt (See Figure 42). Also ensure that you have only TWO .243" diameter checkballs installed into the Premain valve body, in the locations shown in Figure 43.





Figure 42  
*Automatic Transmission Service Group*

**F4EAT PREMAIN VALVE BODY**



IF A CHECKBALL IS INSTALLED IN THIS LOCATION,  
THE RESULT MAY BE NO 2ND AND 4TH GEARS.

Figure 43



**FORD F4EAT**  
**BIND UPS AND WRONG GEAR STARTS**

**COMPLAINT:** A: After "overhaul" vehicle "Binds up" on the 1-2 shift.

B: After "overhaul" vehicle binds up in reverse and manual low and makes a third gear start.

**CAUSE:**

A: The cause may be, the 2-3 accumulator piston was installed into the 1-2 accumulator bore. Because of the difference in overall length, when the 2-3 accumulator piston is installed into the 1-2 accumulator bore, the sealing ring of the 2-3 accumulator piston provides an "Orifice" for 1-2 accumulator pressure (band apply) to enter the 3-4 clutch apply "circuit" on the 1-2 upshift.

B: The cause may be the 2-3, N-D or N-R accumulator was installed into the 1-2 accumulator bore, or the sealing ring at the small diameter of the 1-2 accumulator was damaged on installation into it's bore.

Because of the difference in overall length, when the 2-3 or N-D accumulator is installed into the 1-2 accumulator bore, "LINE PRESSURE" can be forced past the accumulator piston into the 3-4 clutch circuit. (Refer to figure 44)

When the N-R accumulator is installed into the 1-2 accumulator bore, "LINE PRESSURE" can also enter the 3-4 clutch circuit through the "factory" hole bored through the center of the small diameter of the piston or the "factory gap" in the small diameter sealing ring.

**CORRECTION:** A: See figure 45 for the correct accumulator identification and assembly.

B: See figure 45 for the correct accumulator identification and assembly or replace the damaged sealing ring.





Figure 44



# Another First ...



## Transmission Manuals Now On CD Rom

### **DOMESTIC TRANSMISSIONS**

General Motors, Ford, Chrysler,  
Pass Books, Updates and Transfer Cases


### **IMPORT TRANSMISSIONS**

Toyota, Honda, Nissan, Mercedes,  
BMW, Mitsubishi, Mazda and more

### **ATSG TECH BULLETINS**

1986 - 1993 on CD Rom

Call Our Toll Free Number for Prices and Information



**1-800-245-7722**

**9200 S. DADELAND BLVD.  
SUITE 720 • MIAMI, FL 33156**

ACCUMULATOR I.D.		
ACCUM.	PISTON COLOR	LENGTH
"A" 2 - 3	GREEN	2.108"
"B" 1 - 2	RED	2.313"
"C" N - D	BEIGE / WHITE	2.152"
"D" N - R	TURQUOISE / BLUE	2.152"

ACCUMULATOR SPRING I.D. (1.9)		
ACCUM.	SPRING COLOR INNER / OUTER	SPRING LENGTH INNER / OUTER
"A" 2 - 3	GREY / GREY	2.345" / 2.813"
"B" 1 - 2	NA 1.9 / WHITE	NA 1.9 / 3.080"
"C" N - D	YELLOW / PLAIN	2.100" / 2.080"
"D" N - R	ORANGE/ORANGE	3.670" / 4.115"




Figure 45

## MAZDA 929

### STACKED SHIFTS

**COMPLAINT:** After overhaul, it may be noted that the N4AEL Transmission found in 1987-1991 Mazda 929s shift early or "stack shift" at light throttle openings. It will seem that 2nd gear is missing and 3rd gear will occur on top of 1st gear at about 12-14 mph. 4th gear may occur as low as 19 mph. These shift characteristics may feel wrong, as the vehicle feels sluggish after the first shift at low speeds. This feeling usually goes away and the shifts spread out if the vehicle is driven more aggressively.

**CAUSE:** The EC-AT Computer strategy allows 1-2 upshifts as early as 7 mph at light throttle when the "normal" mode is selected. The shifts at 1/8 throttle or less occur at 7 mph, 13 mph, and 19 mph. (See Figure 46) It is not until 1/4 throttle or more that the shifts are perceptibly spread out.

**CORRECTION:** As long as other shift quality concerns have been addressed, no other action is necessary or possible.

THIS IS NORMAL OPERATION!




Figure 46

**MAZDA MPV****ENGINE DOES NOT START WHEN  
VEHICLE IS PARKED ON AN INCLINE.**

- COMPLAINT:** Some 1990 - 1992 Mazda MPV vehicles with the RE4R01A transmission may not start when the vehicle is parked on a steep incline. The automatic transmission lever may also not move from the "P" position.
- CAUSE:** Because of some play in the transmission linkage, a steep incline (20° or more) can pull the linkage so that the park/neutral circuit in the inhibitor switch does not close. Also because of the configuration of the manual plate (rooster cone), the shift lock mechanism may not disengage and allow movement of the gearshift lever.
- CORRECTION:** Beginning on May 1, 1991, the inhibitor switch was modified to correct the no start condition. If the vehicle has a Vin. number lower than M0348547, replace the inhibitor switch.  
Beginning on October 1, 1991, the round configuration of the manual plate between the "P" and "R" ranges was changed to facilitate lever movement. If the vehicle has a VIN number lower than N0414408, replace the manual plate (rooster comb) and manual shaft as well as the inhibitor switch. Parts information is found below in Figure 47.

PART NUMBER	DESCRIPTION	QTY
BU36 19 444A	Inhibitor Switch	1
BU36 19 440	Manual Plate	1
BU67 19 431	Manual Shaft	1
0338 19 432	"O" Ring	1
0338 19 446	"O" Ring	1
BU67 21 465	Spring Pin	1

Figure 47

## NISSAN RE4F02A

### ENGINE KILL WHEN TRANSAXLE IS PUT INTO DRIVE OR REVERSE

**COMPLAINT:** When the transaxle is put into drive or reverse, the engine is instantly killed.

**CAUSE:** The torque converter clutch is immediately applied due to a broken lock up shuttle valve retainer (See figure 48), which has jammed the valve in the apply position.

**CORRECTION:** Free the lock up shuttle valve and replace the retainer




Figure 48

## NISSAN RE4F02A PREMATURE HIGH CLUTCH FAILURE

**COMPLAINT:** Premature failure of the high gear clutch.

**CAUSE:** Premature failure of the high gear clutch may be caused by a leaking high clutch check valve, which is located in the pump cover /support. (See figure 49)

**CORRECTION:** With a GOOD FITTING set of sealing rings in place, install the high gear drum onto the pump cover/support. Then pour some solvent into the high gear check valve and air check the high gear drum through the high gear clutch feed passage in the pump side of the pump cover/support while checking the high gear check valve for leakage. (See figure 50)




Figure 49




Figure 50

## NISSAN RL4F03A AND RL4F03V

### FLARED 2-3 SHIFT OR NO 2-3 SHIFT ONLY WHEN HOT

**COMPLAINT:** Some low mileage vehicles equipped with the RL4F03A/V Transaxle may exhibit a flared or slipping 2-3 upshift, or have no 2-3 upshift at all, after the transaxle is warm. UPON DISASSEMBLY AND INSPECTION THERE IS NO VISUAL ROOT CAUSE FOUND FOR THE CONDITION LISTED ABOVE.

**CAUSE:** #1-It has been determined that the inner "D" ring on the direct clutch piston wears badly and/or shrinks, creating a leak of direct clutch oil at the inner seal. (See figure 51)

#2-It has also been found that the direct drum is prone to cracking in the area around the inside diameter of the drum where the input shaft is attached to the drum, and is sometimes difficult to see visually. (See figure 52)

**CORRECTIO** #1-Remove the outer lip seal from the direct clutch piston and install the piston back into the direct drum with only the "D" ring in the piston. Rotate the piston and check the "D" ring for "DRAG", as shown in figure 53. "D" ring wear and/or shrinkage is what normally creates this complaint, and simply replacing the "D" ring solves the problem.

#2-If when checking the "D" ring for "DRAG" as explained above, you determine the "D" ring DOES have sufficient "DRAG", than a close inspection of the direct drum for cracks, in the area shown in figure 52, is MANDATORY. Replace the direct drum as necessary.

**NOTE:** ATSG has found that the Chrysler 413/470 scarf-cut Teflon sealing rings provide much better sealing of direct clutch oil, when they are used on the input shaft in this unit. (See figure 52)




Figure 51

**NISSAN RL4F03A AND RL4F03V**




Figure 52




Figure 53



## NISSAN RL4R01A HARSH MANUAL SHIFT FROM D1 TO D2

**COMPLAINT:** Some 1990-1991 Nissan trucks equipped with the RL4R01A transmission may exhibit a harsh manual upshift from D1 to D2.

**CAUSE:** This complaint may be caused by a worn and broken Orifice Check Valve, which is located in the lower valve body (to figure 54). When wear occurs in the Orifice Check Valve, it may break, causing pieces of the check valve to become lodged in the Accumulator Control Valve, (Refer to figure 55) which is located in the upper valve body section.

**CORRECTION:** Remove the Orifice Check Valve and spring and check to see if it is broken. If it is broken, clean the broken pieces out of the Accumulator Check Valve and reassemble the valve body **WITHOUT** the Orifice Check Valve.

The removal of the Orifice Check Valve will not affect the operation of the transmission.

All transmissions built after June 13, 1991 will have the Orifice Check Valve eliminated.

**NOTE:** When reassembling the valve body be sure to reinstall the check ball shown in figure 55A. This check ball is not shown in repair manuals.




Figure 54

SLIDE

NISSAN RL4R01A

UPPER VALVE BODY





Figure 55A  
Automatic Transmission Service Group

## NISSAN RL4RO1A FALLS OUT OF FOURTH GEAR

**COMPLAINT:** Vehicles equipped with the RL4RO1A may exhibit a complaint of falling out of 4th gear at "Highway" speeds, although the vehicle will hold 4th gear at lower speeds.

**CAUSE:** The cause may be a "Broken" or "Cracked" bore plug at the end of the "Lock-up Control Valve Train". The reason is, when vehicle speed and governor pressure is high enough, (approx. 44 - 49 mph), governor pressure moves the 4th speed cut valve against spring pressure allowing 4th apply pressure to enter the "lock-up control valve", at the bore plug side, which in turn moves the lock-up control valve and applies the "torque converter clutch". When this action takes place the broken bore plug can act as an exhaust for 4th apply oil pressure causing the loss of 4th gear.

**CORRECTION:** Replace the bore plug ensuring the new bore plug fits "snug" in the valve body bore, See Figure 56.




Figure 56

## NISSAN RL4R01A WRONG GEAR STARTS

**COMPLAINT:** Vehicle starts off in a gear other than low

**CAUSE:** Installing the primary valve into the governor body incorrectly as shown in figure 57 will cause the vehicle to make a wrong gear start. The reason for the incorrect installation may be caused by the fact that the incorrect primary valve line-up shown in figure 57 is also shown incorrectly in various repair manuals.

**CORRECTION:** Install the primary valve line-up as it is seen in figure 58. This is the correct line-up.




Figure 57





Figure 58

## NISSAN RE4R01A



## NISSAN INFINITI RE4R03A

### SECOND GEAR STARTS

#### Information only:

1991-1992 Nissan Infiniti Q45 models with the RE4R03A transmissions are calibrated through the A/T Control Unit to start from a stop in second gear at less than 5/8 throttle opening. THIS IS NORMAL! The transmission will start in first gear if the throttle is opened to 5/8 or higher. The shift schedule for 1991-1992 Q45 models is shown in figure 59.




Figure 59

#### Information Only:

1993 Nissan Infiniti Q45 models with the RE4R03A transmissions are calibrated to start in first gear from a stop under all conditions. The change was made to the program in the A/T Control Unit. The shift schedule for the 1993 Q45 model is shown in figure 60.




Figure 60

## RE4R01A/JR403E

### SECOND GEAR STARTS WITH NO FIRST OR FOURTH

**COMPLAINT:** Vehicles may exhibit second gear starts with no first or fourth gears. The vehicle does shift to third automatically. No external electrical problem is evident and there is still no first gear even when the solenoids are energized using test equipment.

**CAUSE:**

1. Shift solenoid A is stuck open or has electrically failed.
2. Shift valve A is stuck.
3. The bore plug between shift valve A and the 4-2 relay valve has broken at the roll pin and is preventing shift solenoid A pressure from stroking the shift valve.

**CORRECTION:**

1. Check shift solenoid A resistance. It should be 20 - 40 ohms to ground. Check shift solenoid A with battery voltage to make sure that it closes when it is energized. See Figure 61.
2. Disassemble the valve body and clean thoroughly.
3. Replace the broken bore plug, making sure that no pieces are lodged in the worm tracks. Clean the bore so that the plug fits smoothly and the the roll pin holds it securely in place. See Figure 62.




Figure 61

**RE4RO1A/JR4O3E**  
**SECOND GEAR STARTS CONTINUED**




Figure 62

\* Due to differences in certain line ups between the RE4RO1A valve bodies and the JR4O3-E valve bodies, only the shift valve A line up is addressed in Figure 62. For other line up identification, refer to the proper Techtran Manual.



## SAAB 9000/EAGLE PREMIER (ZF-4HP-18)

### SAAB TURBO 9000

Saab 9000 vehicles that are turbo equipped, will have a tube that connects the turbo charger to the valve body. Its function is to provide pressure to the spring side of the 4-3 downshift valve during turbo boost periods. When a turbo 4-3 downshift takes place, the forward clutch will fully apply before the 2-4 band is fully released. This added shift overlap is needed during a turbo 4-3 downshift due to the increased torque demand. If the "O" ring that seals the pipe to the valve body end plate is missing or damaged, transmission fluid will be drawn up through the turbo during non-boost periods. This will allow the oil to be burned by the engine resulting in excessive white smoke exiting the tail pipe. (See Figure 13 below)




Figure 63

**SAAB 9000/EAGLE PREMIER (ZF-4HP-18)**  
**NO FORWARD GOOD REVERSE**

**COMPLAINT:** ZF-4HP-18 transmissions may exhibit a no move condition in any forward range and works fine in reverse.

**CAUSE:** One cause may be that either the 3-4 or 4-3 traction valve in the valve body has stuck in a stroked position preventing forward clutch apply (See Figure 64).

**CORRECTION:** Remove the valve body from the transaxle. Inspect and free the valve that is stuck.




Figure 64

**SAAB 9000/EAGLE PREMIER (ZF-4HP-18)  
DELAYED FORWARD ENGAGEMENT OR  
PREMATURE FAILURE OF THE FORWARD CLUTCH**

- COMPLAINT:** ZF-4HP-18 transmissions may exhibit a delayed forward engagement or premature forward clutch failure after overhaul.
- CAUSE:** One cause may be that the top sealing ring on the stator may have machined its groove wider causing a leak in the forward clutch circuit. The widening of the groove by the sealing ring is done so well that it may be overlooked during overhaul. Another cause may be the bushing in the stator having a ring groove cut into it by the turbine shaft sealing ring. This will also cause a forward clutch leak (See Figure 65).
- CORRECTION:** If a .040" or greater feeler gauge can fit into the groove along side the sealing ring, the stator will need to be replaced (See Figure 65). If the sealing ring groove is good and the bushing is bad, the bushing is serviced separately by aftermarket companies. Refer to your local supplier.





Figure 65

# TEST YOURSELF

## with Intercont's new Super Combination Transmission Test Machine



Intercont's new transmission test machine, the "Super Combo" will allow you to test virtually every transmission known. With an exclusive 1:1 gear ratio from a gas powered engine, the "Super Combo" is designed to test right hand rotations, rear wheel drive, and even the left hand rotation Honda transmission.

Hand-built by skilled professionals, the "Super Combo", as well as all of Intercont's quality products, is built to withstand day-to-day use for years. At Intercont, we know the problems associated with testing transmission effectively, so we build the solutions.

**Call your Intercont sales representative at 1-800-749-3939 for more details about the "Super Combo" or other quality testing and washing equipment.**

**SAAB 9000/EAGLE PREMIER (ZF-4HP-18)**  
**NO 3-4 OR STACKED 3-4 SHIFT**

Both Saab and Eagle Premiers may exhibit a no 3-4 shift or a stacked 3-4 shift. One cause may be that the plastic spacer in the 3-4 shift valve line up had melted. The spacer could melt and block the 3-4 shift valve preventing the 3-4 shift, or it could melt and cause a loss of spring tension causing a stacked 3-4 shift. (see figure 66 below). This spacer can be purchased through a local authorized ZF distributor under the part # 1036 326 223. Dimensions of the spacer is provided below in figure 14 in the event one needs to be fabricated.




Figure 66

## SAAB 9000/EAGLE PREMIER (ZF-4HP-18)

### HARSH ENGAGEMENT INTO DRIVE AND A HARSH 4-3 DOWNSHIFT

Both the Saab and Eagle Premiers may exhibit a harsh engagement into drive and a harsh 4-3 downshift. One cause may be a faulty forward clutch (A clutch) accumulator spring (See Figure 67). This allows the forward clutch to come on abruptly when doing a 4-3 downshift or placing the selector lever into any forward ranges. If upon inspection of this spring you find that it is not broken, collapse the spring and see if there is uneven coil binding. A new spring can be ordered through a local authorized ZF distributor. To order the properly calibrated spring for the transmission you are working on, obtain the 3 digit number that is pressed into the identification plate (See Chart Below). Saab has this plate mounted on top of the bellhousing and Premiers mount the plate on the side of the case next to the servo. Once the number has been located, cross reference the number in the chart below to obtain the appropriate part number.

SAAB		PREMIER	
CODE #	PART #	CODE #	PART #
023 024	0732 042 051	010 015	0732 042 170
031 032		006	0732 042 211
048 049	0732 042 219	021	0732 042 185
058 059			
065			

OBTAIN NUMBER  
HERE





Figure 67



**ZF4HP22**

**NO OR SLIPPING 2ND GEAR**

**COMPLAINT:** A: Vehicle slips in second gear and may, after one shift cycle, loose second gear entirely.

B: Unable to install snap ring into groove in case due to center support assembly not seated all the way into the case.

**CAUSE:** A: Incorrectly assembling the intermediate and intermediate overrun friction and steel plates into the front half of the center support assembly will create a space between the intermediate overrun clutches and the intermediate/intermediate overrun pressure plate, depending on where the assembly error was made, causing either of the clutch pistons to over extend its travel, thereby cutting the piston seal on the return travel of the piston. Refer to figure 68 for the correct order of assembly.

B: When installing the center support assembly into the case, an incorrect stack-up of the components will cause the intermediate overrun piston assembly to be located above the snap ring groove in the case, making it impossible to install the snap ring. (Refer to figure 70)

**CORRECTION:** A: Refer to the illustration in figure 68 and assemble the intermediate section as follows:

1. Install the intermediate one-way clutch onto the sun gear shaft. Make certain that the word "OBEN" stamped into the one-way clutch surface is facing UP. Align the upper and lower halves of the intermediate one-way clutch.
2. Install the intermediate clutch pack, beginning with a steel plate and ending with a friction plate. The outside lugs of the intermediate steel plates index into the "Y" shaped slot "A" as shown in figure 69.
3. Index the outer lugs of the intermediate/intermediate overrun clutch pressure plate into the "Y" shaped slot "A" as shown in figure 69.
4. Install the intermediate overrun clutch pack, beginning with a friction plate and ending with a steel plate making certain that the outside lugs of the intermediate overrun steel plates index into the "SQUARE" shaped slot "B" as shown in figure 69.
5. Install the intermediate overrun piston housing onto the clutch drum, making certain to index the "V" shaped tab of the intermediate overrun piston housing into the "Y" shaped slot marked "A", checking to see that all 4 oil feed holes in the clutch drum and the intermediate overrun piston housing are aligned as shown in figure 69.

B: Follow the above procedure, making certain that the snap ring groove in the case is exposed after the center support assembly is installed into the case. (Refer to figure 70)

ZF4HP22

INTERMEDIATE/INTERMEDIATE OVERRUN CLUTCH ASSEMBLY




Figure 68



ZF4HP22

CENTER SUPPORT ASSEMBLY




Figure 69

**ZF4HP22**




Figure 70

## PASSAT - 096 PRELIMINARY INFORMATION

There are 7 solenoids mounted on the valve body of the Passat 096 transaxle. These solenoids connect to a detachable plastic harness retainer. The harness itself travels through the case with the main round connector attached to a plate that is bolted to the top of the case beside the linkage. The main voltage supply is fed through pin # 1 as shown in figure 73 on the next page. This terminal feeds battery voltage through a brown wire which travels all the way to the end of the detachable plastic retainer. There, it is soldered, to a temperature sensor and 6 other brown wires which goes on to feed battery voltage to 6 out of the 7 solenoids (See Figure 71 below).




Figure 71

### TEMPERATURE SENSOR

The Temperature Sensor shown above measures approximately 200K ohms at room temperature and drops in resistance as the transmission fluid heats up. The Temperature Sensor signal wire is red in color and goes to pin # 12 in the connector as shown in figure ? on the next page. This sensor monitors the transmission's fluid temperature continuously.

When transmission fluid temperatures exceed a predetermined limit, the ECU is programmed to cause later shifts resulting in higher engine revs. This produces greater coolant flow in an attempt to bring the fluid temperature down. Also, this transaxle has a hydraulic and a mechanical third gear. The ECU will command a mechanical third gear sooner in an attempt to reduce converter slip which produces heat. As soon as the transmission fluid cools down, the normal driving program is resumed.

### SOLENOIDS

The resistance of six out of the seven solenoids (Solenoid #'s 1, 2, 3, 4, 5, and 7) measure approximately 60 ohms each. The remaining #6 solenoid measures approximately 5 ohms in resistance (See Figure 73 on the following page for the solenoid locations on the valve body). All six solenoids that measure 60 ohms in resistance are **normally open** solenoids and close to hold pressure when they are energized. The # 6 solenoid is a pulsed width modulated pressure control solenoid and it is a **normally closed** solenoid. This solenoid has its own voltage supply through pin # 2 as shown in figure 73 on the next page. A 200 ohm resistor is soldered in a parallel circuit with the pressure control solenoid (See Figure 72 Below).




Figure 72

The ECU controls shift timing and shift feel by providing ground signals for each of the seven solenoids. Solenoid #'s 1, 2, 3 and 4 are used to control shift timing. The gearshift transitions are controlled by solenoids # 5 and # 7. Solenoid # 6 controls main line pressure as previously stated.

If all power was lost so that the solenoids could not be energized, the transaxle would have third gear starts. Manual low and reverse could also be achieved if power to the solenoids were lost. The ECU will also cause third gear starts as a failsafe in the event it had monitored a problem within the system.

PASSAT - 096  
SOLENOIDS




Figure 73

**JOIN THE**

**HEAVYWEIGHTS**



**leave the guesswork to the other guys**

Can you chance picking up today's mushrooming tech-information 'job to job' by the seat of your pants ? ATSG is the tech service that spends all day every day making sure it has up to the minute information on *foreign and domestic* computers and hydraulic controlled transmissions.

All of this is available to you in bulletins, manuals, videos, hot line service and tech training courses.

It helps to belong to a tech service... but belong to a tech service that helps. Call 1 (800) 245-7722 today and let us tell you why your choice should be ATSG ... or better still, ask about our seminar special.

**That number again for subscriber information is:**

**1 (800) 245-7722**

**AUTOMATIC TRANSMISSION SERVICE GROUP**

9200 S. Dadeland Blvd. • Suite 720 • Miami, FL 33156 • (305) 670-4161



PASSAT - 096  
SOLENOIDS

**SOLENOIDS Continued**

To check each solenoid for resistance, place the positive lead of a multimeter to pin # 1 in the connector. With the ground lead of the meter, check each solenoid by touching the appropriate ground pin (Use Figure 73 for pin location). Below is a chart that can be used as a quick reference guide.

DEVICE TO BE CHECKED	NEGATIVE METER LEAD TO PIN #	OHMS VALUE *
Solenoid #1	Pin # 3	60
Solenoid #2	Pin # 4	60
Solenoid #3	Pin # 5	60
Solenoid #4	Pin # 6	5
Solenoid #5	Pin # 7	60
Solenoid #6	Pin # 8	60
Solenoid #7	Pin # 10	60
ATF Sensor	Pin # 12	200K

\* All values are approximate at room temperature.

The electrical management system that operates or controls this transaxle is called DIGIMAT. No it is not misspelled, it is just a strange name. Unfortunately, this Digimat ECU has a permanent fault memory and self diagnosis capability with stored codes that can only be retrieved with the use of a VAG 1551 scanner by, guess who? Fahrvergnugen! Short for V.W.. This means that when this unit comes into your shop in failsafe, you'll have to run it down to your FRIENDLY and COOPERATIVE Volkswagen Dealership and ask them to hook up their scanner to retrieve the codes.

If you want to shift the transmission separate from the computer, it can be done if you have patience. First supply 12 volts through a 20 amp fuse to pin # 1 in the connector and keep it there. Now you can begin to ground the appropriate pins:

Ground pin 6 to get 1st gear.

Ground pins 4 and 6 to get 2nd gear.

No grounds is a hydraulic 3rd gear.

Ground pin 5 for a mechanical 3rd gear.

Here is the Grand Finale':

Ground pins 3, 4, 5 and 6 to get 4th gear.

This test can be helpful in a pinch, but the best way to diagnose this guy is with a scanner.

As you can see the solenoid shift pattern is quite different when it is compared to any other solenoid shifted transmission. This shouldn't have come at much of a surprise, after all, it is a Digimat electrical system.

When the selector lever is placed into Drive, line pressure is fed to the K1 and K2 clutch. The K1 clutch can be thought of as a 1st to 3rd clutch and the K2 as a 3rd and reverse clutch. When solenoid #4 is energized by grounding pin # 6, the K2 clutch feed is exhausted allowing just the K1 clutch to be applied. A spring and roller one way clutch now becomes effective and the transaxle has first gear.


To make a shift into 2nd, solenoid # 4 remains energized to keep the K2 clutch from applying. Solenoid # 2 is energized by grounding pin # 4 which allows the B2 clutch (2/4 clutch) to come on.

A shift into a hydraulic 3rd gear takes place when all the grounds are removed. The K1 clutch is still applied, the B2 clutch comes off and now the K2 clutch finally comes on because the # 4 solenoid was turned off. With both the K1 and K2 clutch on at the same time, the planetary gear set is locked spinning 1:1.

A mechanical 3rd gear can be achieved by grounding the # 5 pin which energizes the # 3 solenoid. This allows the K3 clutch (3/4 clutch) to be applied. The K3 clutch drum is splined into a damper plate in the torque converter which provides a direct mechanical link to the crank shaft eliminating the need for a converter clutch. This also produces the mechanical 3rd gear. Remember, the K1 and K2 clutch is still applied, by energizing the # 3 solenoid, we add the K3 clutch connecting the gear train to the crank shaft which eliminates all converter slip.

The shift into 4th gear occurs when a ground is made to the # 3 pin to energize the # 1 solenoid. This exhaust oil from the K1 clutch turning this clutch off. Solenoid # 2 is turned back on to apply the B2 clutch (2/4 clutch), the K3 clutch (3/4 clutch) is already on from the mechanical 3rd shift. Solenoid # 4 is turned back on to exhaust the oil from the K2 clutch (3rd and reverse). All this happens at once leaving the B2 and K3 clutches as the only two clutch packs on to achieve 4th gear. A powerflow chart has been provided for you in figure 74 Also, Mario Aristides from Independent Transmissions has provided us with valve body illustrations (See Figures 75 - 78), Thanks Mario!

**PASSAT - 096**  
**CLUTCH APPLY CHART**



RANGE	GEAR	B1 CLUTCH	LOW ONEWAY CLUTCH	K3 CLUTCH	K2 CLUTCH	K1 CLUTCH	B2 CLUTCH
D4	1ST		ON			ON	
	2ND					ON	ON
	3RD (H)				ON	ON	
	3RD (M)			ON	ON	ON	
	4TH			ON			ON
L	1ST	ON			ON		
R	REV	ON			ON		

D3 - IS THE SAME AS D4 BUT NO 4TH GEAR

D2 - IS THE SAME AS D4 BUT NO 3RD OR 4TH GEAR

Figure 74





Figure 75  
Automatic Transmission Service Group



# ROSTRA


## THE TRADITION CONTINUES

*From Modulators To Diagnostic Test Equipment And More . . .*



Rostra Modulators are recognized as the highest quality in our industry. Complete and universal, problem solving designs, function perfectly first time. . . every time! When quality counts, no one matches Rostra!

The Rostra Analytical Tool: The RAT system is the most universal, expandable, and easy to use diagnostic tool for the transmission repair industry. This diagnostic system allows you to monitor outputs from the ECU or bypass the ECU and manually control the transmission. You can pinpoint hydraulic and electronic problems without even dropping the pan. State of the art RAT PAK modules expand coverage to the latest models. Free technical service is available to assist you in your diagnosis. Let a RAT loose in your shop and save time, improve diagnoses, and get rid of come-backs.



Rostra proudly introduces the LU-1 lockup delay module. The LU-1 is an electronic device that delays lockup until a preset speed is reached. The unit may be installed on any lockup system including all GM, Ford A4LD, AXOD, and Chrysler lockup systems. Plus with Rostra's Adapter Harness 250-4233 coverage is expanded to the Ford E40D. The LU-1 eliminates common problems such as early lockup, lockup hunting and lockup on top of shifting. Installation is easy. Just connect the appropriate color coded wires as shown in the illustrated instruction manual and set your desired lockup speed! All the necessary hardware is included too! Our free technical support is available to assist in your installation.



*As always, Rostra is committed to engineering the highest quality product, with performance unmatched by anyone. Our manufacturing represents the best in American expertise and craftsmanship. Rely on Rostra for the quality products you and your customer deserve.*

**ROSTRA  
PRECISION  
CONTROLS INC.**

2519 Dana Drive, Laurinburg, NC 28351 • 910-276-4853 • Technical support: 910-276-8211




Figure 76  
*Automatic Transmission Service Group*




Figure 77





Figure 78



GEAR	TEST CONDITION	PRESSURE (psi)	BARS
Drive	Idling with solenoid connector plugged in	49 - 55	3.4 - 3.8
Reverse	Idling with solenoid connector plugged in	94 - 109	6.5 - 7.5
Drive	2000 Rpm's with solenoid connector unplugged	146 - 164	10.1 - 11.3
Reverse	2000 Rpm's with solenoid connector unplugged	333 - 349	23 - 24

Figure 79



## 1995 SEMINAR INFORMATION VIDEO

94

### THM 3T40 (125C)

#### RE-DESIGNED FORWARD CLUTCH PACK

**CHANGE:** Beginning June 24, 1993 (Julian Date 154) ALL 3T40 (125C) transaxles were built with a re-designed Forward Clutch Pack, as shown in Figure 2.

**REASON:** Improved garage shift from "Reverse to Drive" after removal of the thermo element from the manual valve. The thermo element was eliminated from the manual valve in production models effective April 1, 1993, on all models except "A" Car and "T" Car applications (See Figure 1).

#### PARTS AFFECTED:

- (1) **WAVE PLATES** - The two previous "Wave" plates have been eliminated, as shown in Figure 2.
- (2) **BELLVILLE PLATE** - Added to the forward clutch pack to replace the two wave plates, and provides more resistance to improve the forward clutch apply feel (See Figure 2).
- (3) **STEEL PLATE** - There is one "Flat" Steel plate added next to bellville plate, as shown in Figure 2.
- (4) **BACKING PLATE** - The backing plate used in the re-designed forward clutch pack happens to be the thinnest of the current design selective backing plates, and was used to make the forward clutch clearance correct. Because of the elimination of the "Wave" plates there is no longer any need for selective backing plates and this backing plate will be used in all models. The backing plate being used is .125"-.131" thick and is stamped "D" for identification.
- (5) **BACKING PLATE SNAP RING** - The backing plate snap ring used in the new design forward clutch pack is also a previous design level snap ring that is slightly larger in diameter (Stronger) than the current snap ring, to accomodate the added bellville plate. The stronger snap ring is identified with "Square" cut ends instead of "Stepped" cut ends as shown in Figure 3. The "Stepped" cut snap ring is now used ONLY in the direct clutch pack.

#### INTERCHANGEABILITY:

The new design parts listed above will service ALL 3T40 (125C) transaxles back to 1987 when used as a package, AND THE THERMO ELEMENT IS REMOVED FROM THE MANUAL VALVE.

**NOTE:** We recommend that the thermo element be removed from the manual valve on ALL models so equipped, and install the conversion package part number listed below.

Removing the thermo element will eliminate premature Lo/Reverse clutch failure (ATSG Bulletin 92-40), and installing the conversion package will restore the proper shift feel from "Reverse to Drive" with the thermo element removed.

Continued on next Page.

### SERVICE INFORMATION:

Forward Clutch Bellville Plate (New Design) .....	8685867
Forward Clutch Backing Plate (Stamped "D") .....	8664163
Forward Clutch Backing Plate Snap Ring (Stronger) .....	8631028
Conversion Kit Service Package (Includes 3 Parts Listed Above) .....	24200477
Forward Clutch Steel Plate (Current Design) .....	8683084





Figure 1

PREVIOUS DESIGN FORWARD CLUTCH



RE-DESIGNED FORWARD CLUTCH




Figure 2



FORWARD CLUTCH BACKING PLATE SNAP RING





Figure 3

## SATURN

## NO CONVERTER CLUTCH APPLY

- COMPLAINT: After rebuilding a Saturn transaxle, you have no converter clutch apply at any speed and the computer is sending the proper signals at the proper time to the transaxle.
- CAUSE: The cause may be, the "O" ring on the turbine shaft missing. The "O" ring MUST be installed in the turbine shaft groove BEHIND the spiral ring, as shown in Figure 4, and NOT next to the turbine shaft splines.  
If the "O" ring is installed next to the splines, the "O" ring will roll off and remain in the torque converter as the converter is removed from the transaxle.
- CORRECTION: Install a new, proper size, "O" ring into the turbine shaft groove. Make sure the "O" ring is placed BEHIND the spiral ring, as shown in Figure 4, and NOT next to the turbine shaft splines. It is not necessary to remove the spiral ring to install the "O" ring into the groove in the proper position.
- NOTE: We have recieved several reports of this complaint on transaxles that have been disassembled for the first time, which can only mean that the "O" ring was installed in the wrong position when it was originally assembled.


# SATURN TURBINE SHAFT



THE "O" RING MUST BE INSTALLED IN THE TURBINE SHAFT GROOVE BEHIND THE SPIRAL RING, AS SHOWN ABOVE.

Figure 4


# DEMAND THE BEST



**T-0025-A**  
**RINGLOC SNAP RING**  
**PLIERS**



**T-1703**  
**FRONT PUMP SPRING LOADER**  
**TOOL FOR GM 700R4, 2004R**  
**AND 440-T4**



**T-0158-SP**  
**SNAPRESS CLUTCH**  
**SPRING COMPRESSOR**



**T-0157**  
**QUICK LOCK**  
**SPRING COMPRESSOR**



**T-1571**  
**GM 700-R4**  
**DAMAGED SUN GEAR PULLER**



**T-1453**  
**CHRYSLER BEARING CUP AND CONE**  
**REMOVER AND INSTALLER KIT**

**YOUR COMPLETE TRANSMISSION TOOL SOURCE**



**HAYDEN Trans-Tool**

**110 Connelly, San Antonio, TX 78203**

**1-800-531-5978/FAX (210) 225-2114**




**SATURN**  
**MANUAL VALVE ORIENTATION**  
**GRINDING NOISE IN REVERSE**

- COMPLAINT: After overhaul, you have a bad grinding noise when the selector lever is placed in reverse, and the vehicle feels as if it wants to move forward.
- CAUSE: The cause may be, the manual valve installed improperly, with the "Flat" oriented so that it is facing down towards the case.
- CORRECTION: Remove the valve body and rotate the manual valve so that the "Flat" is facing UP TOWARDS THE TOP PAN, as shown in Figure 5. Re-install the valve body and torque to proper specifications.

# SATURN MANUAL VALVE ORIENTATION

UPPER VALVE BODY



WHITE

PINK

LOWER VALVE BODY

MANUAL VALVE SHOULD BE INSTALLED WITH  
THE "FLAT" FACING UP TOWARDS THE TOP  
PAN AS SHOWN IN THIS ILLUSTRATION.




Figure 5



**SATURN**  
**MOVES FORWARD ALL GEAR SELECTIONS**  
**REVERSE AND/OR FORWARD WITH THE**  
**SELECTOR IN PARK OR NEUTRAL**

There are currently 3 different design levels of the Manual Valve, and 2 different design levels of the Manual Valve Link, that can create the complaints listed above if they are installed wrong, and/or parts mis-matched.

**COMPLAINT NO. ONE:**

The vehicle moves forward in all selector lever positions, including Neutral, and tries to move forward in Park, on all late 1992 and all 1993 model Saturn transaxles that use the 2nd design Manual Valve.

**COMPLAINT NO. TWO:**

The vehicle tries to move Forward and/or Reverse with the selector lever in Park, and can move unexpectedly Forward and/or Reverse with selector lever in eutral, on 1993/1994 Saturn transaxles.

**CAUSE NO. ONE:**

2nd design Manual Valve installed improperly with the "Notch" facing down towards the case. The "Notch" MUST face up towards the top pan (See Figure 6).

**CAUSE NO. TWO:**

1994 (3rd Design) Manual Valve used with a 91-93 "Stamped Form" Manual Valve Link, that allows extra play in the shift linkage because of mis-matched parts. Refer to Figure 7 for dimension differences.

**CORRECTION NO. ONE:**

On ALL 1991 to 1993 models, remove the valve body and orient the Manual Valve with the "Flat" (1st Design) or "Notch" (2nd Design) on the Manual Valve facing UP TOWARDS THE TOP PAN, as shown in Figure 6. Reinstall the valve body and torque to proper specifications.

**CORRECTION NO. TWO:**

Install the proper design level Manual Valve Link with the matching Manual Valve. Functionally, the 1994 (3rd Design) Manual Valve is the same as the late 1992 and 1993 (2nd Design) Manual Valve. There are two different stem diameters on the Manual Valve Links, where it goes into the manual valve.

1st design "Stamped Form" Manual Valve Link is used on all 91-93 models, and the stem diameter is .153" (See Figure 6).

2nd design "One Piece Wire" Manual Valve Link is used on all 1994 models, and the stem diameter is .194" (See Figure 7).

As a result of the change to the Manual Link, the hole in the Manual Valve also had to increase in diameter from .161" to .202", to accommodate the 2nd design manual link (See Figure 7). There was also a plastic cap added to the 1994 (3rd Design) Manual Valve as an assembly aid to prevent the manual valve from being installed to the manual link backwards (See Figure 7).




Figure 6






Figure 7



**Southeast**

A Division of Consulier Engineering

#1 In Transmission Industry  
Specialty Products

**When You Need a Part, Call a  
Southeast Distributor!**

**When You Need  
To Find Out "Which  
Part...?"**

**Look In A Southeast  
Product Catalog?**

ATSG Members  
Call For the Southeast catalog you need:

**1-800-888-5489**


(305) 885-8689

## **TRANSMISSION, ENGINE & STUT MOUNTS**




New early 1995  
A Mount Usage  
Catalog that list  
"By Car"

ask for Catalog  
#MC95



**FREE  
1995  
Giant Mount  
Wall-Chart**  
If your Distributor  
doesn't have any  
Give Us A Call


## **TOOLS**



The Standard Case  
Repair Tools For The  
Transmission  
Professional  
.....and much more

ask for Catalog  
#T101

## **CABLES**



US & Foreign  
Cables etc.....  
Listed By O.E.  
Part I.d.

ask for Cable Listing  
#CL12

## **FLYWHEELS**



The Largest Supplier  
of OEM Manufactured  
Flywheels to the  
Transmission  
Industry

ask for Catalog  
#FF95

## **PLASTICS & Speciality Parts**




ask For Plastic List  
#PL222


For Various Shafts  
#SS444

For Hard Parts  
#HP232

# HYDRA-MATIC 4T40-E

PRELIMINARY INFORMATION





### 4T40-E GEAR RATIOS

FIRST	2.96
SECOND	1.62
THIRD	1.00
FOURTH	0.68
REVERSE	2.14

RANGE	GEAR	SHIFT "A" SOL	SHIFT "B" SOL	2ND CLUTCH	2ND ROLLER CLUTCH	2-4 BAND	REVERSE CLUTCH	COAST CLUTCH	COAST CLUTCH SPRAG	DIRECT CLUTCH	FORWARD CLUTCH	LO/REV. BAND	LO ROLLER CLUTCH
PARK	N	ON	OFF									APPLIED	
REV	R	ON	OFF				APPLIED					APPLIED	
NEU	N	ON	OFF									APPLIED	
D4	1st	ON	OFF						HOLDING		APPLIED		HOLDING
	2nd	OFF	OFF	APPLIED	HOLDING				HOLDING		APPLIED		OVER-RUNNING
	3rd	OFF	ON	APPLIED*	OVER-RUNNING				HOLDING	APPLIED	APPLIED		OVER-RUNNING
	4th	ON	ON	APPLIED	OVER-RUNNING	APPLIED				APPLIED	APPLIED*		OVER-RUNNING
D3	1st	ON	OFF					APPLIED	HOLDING		APPLIED	APPLIED	HOLDING
	2nd	OFF	OFF	APPLIED	HOLDING	APPLIED		APPLIED	HOLDING		APPLIED		OVER-RUNNING
	3rd	OFF	ON	APPLIED*	OVER-RUNNING			APPLIED	HOLDING	APPLIED	APPLIED		OVER-RUNNING
D2	1st	ON	OFF					APPLIED	HOLDING		APPLIED	APPLIED	HOLDING
	2nd	OFF	OFF	APPLIED	HOLDING	APPLIED		APPLIED	HOLDING		APPLIED		OVER-RUNNING
D1	1st	ON	OFF					APPLIED	HOLDING		APPLIED	APPLIED	HOLDING
	2nd	OFF	OFF	APPLIED	HOLDING	APPLIED		APPLIED	HOLDING		APPLIED		OVER-RUNNING

ON = SOLENOID ENERGIIZED

OFF = SOLENOID DE-ENERGIIZED

\* = APPLIED WITH NO LOAD.

\*\* = MANUAL FIRST - SECOND GEAR IS ONLY AVAILABLE ABOVE APPROXIMATELY 30 TO 35 MPH.

Figure 8





Figure 9

### THM 4T40-E CASE CONNECTOR



### PRESSURE SWITCH ASSEMBLY (PSA) CONNECTOR




Figure 10




Figure 11

*Automatic Transmission Service Group*

1	COVER, SIDE (STRUCTURAL)	61	STUD, OUTPUT SPEED SENSOR
2	SEAL, AXLE OIL	62	SENSOR, OUTPUT SPEED
3	BOLT, SIDE COVER	63	SEAL, O-RING (OUTPUT SPEED SENSOR)
4	STUD, SIDE COVER	64	PIN, BAND ANCHOR - LO/REVERSE
5	GASKET, SIDE COVER	65	PLUG, OIL LEVEL CONTROL
6	GASKET, SIDE COVER OIL LEVEL CONTROL	66	SPRING, SERVO RETURN (LO/REVERSE)
7	WASHER, THRUST (SIDE COVER TO DRIVEN SPROCKET)	67	PIN, SERVO APPLY (LO/REVERSE)
8	BOLT, OIL PUMP	68	SPRING, SERVO CUSHION
9	BOLT, OIL PUMP	69	PISTON, SERVO (LO/REVERSE)
10	PUMP ASSEMBLY, TRANSAXLE OIL	70	RING, SERVO SNAP
11	WIRING ASSEMBLY, TRANSAXLE	71	SEAL, SERVO PISTON (LO/REVERSE)
12	BOLT, PRESSURE SWITCH ASSEMBLY	72	SEAL, SERVO COVER (LO/REVERSE)
13	PRESSURE SWITCH ASSEMBLY (PSA)	73	COVER, SERVO (LO/REVERSE)
15	BOLT, WIRING HARNESS BRACKET	75	SPRING, SERVO RETURN (INTERMEDIATE/4TH)
	BOLT, INPUT SPEED SENSOR	76	PIN, SERVO APPLY (INTERMEDIATE/4TH)
16	BOLT, VALVE BODY	77	PISTON, SERVO (INTERMEDIATE/4TH)
18	BODY ASSEMBLY, CONTROL VALVE	78	SEAL, SERVO PISTON (INTERMEDIATE/4TH)
19	SHAFT, OIL PUMP DRIVE	79	SEAL, SERVO COVER (INTERMEDIATE/4TH)
20	BOLT, SPACER PLATE SUPPORT	80	COVER, SERVO (INTERMEDIATE/4TH)
21	SUPPORT, SPACER PLATE	81	BOLT, TUBE ASSEMBLY
22	GASKET, VALVE BODY TO SPACER PLATE		BOLT, BOTTOM PAN
23	PLATE, VALVE BODY SPACER	82	SEAL, OIL FEED TUBE ASSEMBLY
24	GASKET, SPACER PLATE TO CHANNEL PLATE	83	TUBE ASSEMBLY, OIL FEED
25	BOLT, CHANNEL PLATE	84	SEAL, TRANSAXLE OIL FILTER
	BOLT, SERVO COVER	85	FILTER ASSEMBLY, TRANSAXLE OIL
26	CHECKBALLS (7)	86	VALVE, OIL LEVEL CONTROL
27	PLATE, CHANNEL	87	GASKET, TRANSAXLE BOTTOM PAN
28	GASKET, CASE TO CHANNEL PLATE	88	PAN, TRANSAXLE OIL
29	PISTON, ACCUMULATOR (1-2, 2-3 AND 3-4)	89	MAGNET, CHIP COLLECTOR
30	SEAL, ACCUMULATOR PISTON (1-2, 2-3 AND 3-4)	91	SPROCKET, DRIVEN
31	SPRING, 1-2 ACCUMULATOR PISTON	92	WASHER, THRUST (DRIVEN SPROCKET TO SUPPORT)
32	SPRING, 2-3 AND 3-4 ACCUMULATOR PISTON	94	SHAFT, OUTPUT
33	SEAL, O-RING (TURBINE SHAFT TO SPROCKET)	95	SUPPORT ASSEMBLY, DRIVEN SPROCKET
34	WASHER, THRUST (CHANNEL PLATE TO DRIVE SPROCKET)	96	PLATE, 2ND CLUTCH WAVED
35	RING, SNAP (TURBINE SHAFT TO DRIVE SPROCKET)	97	PLATE, 2ND CLUTCH STEEL
36	LINK ASSEMBLY, DRIVE	98	PLATE, 2ND CLUTCH FIBER
37	SPROCKET, DRIVE	99	PLATE, 2ND CLUTCH BACKING
38	WASHER, THRUST (DRIVE SPROCKET TO SUPPORT)	100	BAND, INTERMEDIATE/4TH
39	SHAFT, TURBINE	101	WASHER, THRUST (SUPPORT TO REVERSE INPUT CLUTCH)
40	SEAL, O-RING (TURBINE SHAFT TO SUPPORT)	102	CLUTCH ASSEMBLY, REVERSE INPUT
41	SEAL, O-RING (TORQUE CONVERTER)	103	BEARING, THRUST
42	BEARING, DRIVE SPROCKET SUPPORT	104	WASHER, THRUST (SELECTIVE)
43	SUPPORT, DRIVE SPROCKET	105	CLUTCH ASSEMBLY, DIRECT & COAST
44	BUSHING, DRIVE SPROCKET SUPPORT	106	CARRIER ASSEMBLY, INPUT
45	PIN, DOWEL (CHANNEL PLATE TO CASE)	107	BEARING, THRUST
46	SENSOR, INPUT SPEED	108	INPUT FLANGE & FORWARD CLUTCH HUB ASSEMBLY
48	PLUG, LINE PRESSURE TAP	109	WASHER, THRUST
49	SEAL, COOLER PIPE	110	CLUTCH ASSEMBLY, FORWARD
51	CASE, TRANSAXLE	111	BAND, LO/REVERSE
52	CAP, VENT	112	RING, SNAP (FORWARD CLUTCH SUPPORT TO CASE)
53	SCREW, DRIVE SPROCKET SUPPORT	113	BEARING, THRUST
54	SEAL, CONVERTER	114	SUPPORT ASSEMBLY, FORWARD CLUTCH
55	TORQUE CONVERTER ASSEMBLY	115	GEAR, SUN (FINAL DRIVE)
56	SLEEVE, OUTPUT/STUB SHAFT	116	DIFFERENTIAL AND FINAL DRIVE ASSEMBLY
57	RING, OUTPUT/STUB SHAFT SNAP	117	BEARING, THRUST
58	SHAFT, OUTPUT STUB	118	GEAR, FINAL DRIVE INTERNAL
60	BUSHING, CASE TO FINAL DRIVE	119	RING, FRETTING (INTERNAL GEAR TO CASE)

Figure 12







Figure 13



- 300 BODY, CONTROL VALVE ASSEMBLY
- 301 SPRING, 1-2 SHIFT VALVE
- 302 VALVE, 1-2 SHIFT
- 303 O-RING, SHIFT SOLENOID A AND B
- 304 RETAINER CLIP
- 305 SOLENOID, SHIFT (A AND B)
- 306 SPRING, 2-3 SHIFT VALVE
- 307 VALVE, 2-3 SHIFT
- 308 SPRING, TORQUE SIGNAL REGULATOR VALVE
- 309 VALVE, TORQUE SIGNAL REGULATOR
- 310 O-RING, PRESSURE CONTROL SOLENOID
- 311 O-RING, PRESSURE CONTROL SOLENOID
- 312 SOLENOID, PRESSURE CONTROL
- 313 O-RING, ACTUATOR OIL FILTER
- 314 FILTER, ACTUATOR OIL
- 315 VALVE, ACTUATOR FEED LIMIT
- 316 SPRING, ACTUATOR FEED LIMIT VALVE
- 317 PLUG, BORE
- 318 SPRING, 3-4 SHIFT VALVE
- 319 VALVE, 3-4 SHIFT

- 320 O-RING, 3-4 SHIFT VALVE PLUG
- 321 PLUG, BORE
- 322 SPRING, 1-2/3-4 ACCUMULATOR VALVE
- 323 VALVE, 1-2/3-4 ACCUMULATOR
- 324 BUSHING, PRESSURE REGULATOR BOOST
- 325 VALVE, PRESSURE REGULATOR BOOST
- 326 SPRING, ISOLATOR
- 327 SPRING, PRESSURE REGULATOR VALVE
- 328 VALVE, PRESSURE REGULATOR
- 329 SPRING, 2-3 ACCUMULATOR VALVE
- 330 VALVE, 2-3 ACCUMULATOR
- 331 SPRING, TCC FEED LIMIT VALVE
- 332 VALVE, TCC FEED LIMIT
- 333 SPRING, TCC CONTROL VALVE
- 334 VALVE, TCC CONTROL
- 335 SOLENOID, TCC CONTROL
- 337 O-RING, TCC CONTROL SOLENOID
- 338 O-RING, TCC CONTROL SOLENOID
- 339 VALVE, TCC REGULATED APPLY
- 340 SPRING, TCC REGULATED APPLY VALVE

Figure 14




Figure 15





Figure 16



- |  |  |
|--|--|
| 500 RING, OIL SEAL - INPUT SHAFT                   | 517 RING, SNAP (DIRECT/COAST CLUTCH RETAINING)     |
| 501 BUSHING, INPUT SHAFT                           | 518 PISTON ASSEMBLY, DIRECT CLUTCH                 |
| 502 HOUSING, DIRECT & COAST CLUTCH AND INPUT SHAFT | 519 SPRING AND RETAINER ASSEMBLY, DIRECT CLUTCH    |
| 503 BUSHING, DIRECT CLUTCH HOUSING TO OUTPUT SHAFT | 520 RING, DIRECT CLUTCH SPRING RETAINER            |
| 504 PISTON ASSEMBLY, COAST CLUTCH                  | 521 PLATE, DIRECT CLUTCH (STEEL)                   |
| 505 SPRING, COAST CLUTCH RELEASE                   | 522 PLATE, DIRECT CLUTCH (FIBER)                   |
| 506 RETAINER, COAST CLUTCH SPRING                  | 523 PLATE, DIRECT CLUTCH (BACKING)                 |
| 507 RING, SNAP (COAST CLUTCH SPRING RETAINER)      | 524 BEARING, THRUST                                |
| 508 PLATE, COAST CLUTCH (STEEL)                    | 525 BUSHING, REACTION CARRIER SHAFT                |
| 509 PLATE, COAST CLUTCH (FIBER)                    | 526 SHELL, REACTION CARRIER SHAFT                  |
| 510 BEARING, THRUST                                | 527 BEARING, THRUST (CARRIER SHAFT TO SHELL)       |
| 511 SHAFT AND INNER RACE ASSEMBLY, INPUT SUN GEAR  | 528 BUSHING, REACTION SUN GEAR                     |
| 512 RACE, OUTER (INPUT SPRAG)                      | 529 SHELL, REACTION SUN                            |
| 514 END BEARINGS, SPRAG CLUTCH (2)                 | 531 CARRIER ASSEMBLY, REACTION                     |
| 515 SPRAG ASSEMBLY, INPUT                          | 532 BEARING, THRUST (REACTION CARRIER TO SUN GEAR) |
| 516 RING, SNAP (OUTER RACE TO SPRAG ASSEMBLY)      | 533 GEAR, REACTION SUN                             |
|  | 534 RING, SNAP                                     |

Figure 17




Figure 18






Figure 19



- 575 BUSHING, INPUT FLANGE  
560 GEAR, INTERNAL INPUT  
577 INPUT FLANGE AND FORWARD CLUTCH HUB  
578 SNAP RING (INPUT RING GEAR TO INPUT FLANGE)

Figure 20



- |   |  |
|---|--|
| 600 RING, SNAP (FORWARD CLUTCH)                 | 607 PISTON ASSEMBLY, FORWARD CLUTCH                |
| 601 PLATE, FORWARD CLUTCH (BACKING)             | 608 SEAL AND SLEEVE ASSEMBLY, FORWARD CLUTCH INNER |
| 602 PLATE, FORWARD CLUTCH (FIBER)               | 609 HOUSING, FORWARD CLUTCH                        |
| 603 PLATE, FORWARD CLUTCH (STEEL)               | 610 BUSHING, FORWARD CLUTCH SUPPORT                |
| 604 PLATE, FORWARD CLUTCH (WAVED)               | 611 BUSHING, FORWARD CLUTCH SUPPORT                |
| 605 RING, SNAP (FORWARD CLUTCH SPRING ASSEMBLY) |  |
| 606 SPRING ASSEMBLY, FORWARD CLUTCH RETURN      |  |

Figure 21

- 650 BUSHING, FINAL DRIVE SUN SHAFT
- 651 SHAFT, FINAL DRIVE SUN
- 652 CLUTCH ASSEMBLY, LO ROLLER
- 653 BEARING, THRUST
- 654 RING, OIL SEAL (FORWARD CLUTCH SUPPORT)
- 655 BUSHING, FORWARD CLUTCH SUPPORT
- 656 SUPPORT, FORWARD CLUTCH
- 657 BUSHING, FORWARD CLUTCH SUPPORT
- 658 BEARING, THRUST (FORWARD SUPPORT TO PARK GEAR)
- 659 GEAR, PARK LOCK
- 660 RING, SNAP (FINAL DRIVE SUN SHAFT)
- 661 SHAFT, PARKING LOCK PAWL
- 662 SPRING, PARKING LOCK PAWL RETURN
- 663 PAWL, PARKING LOCK




Figure 22

- 700 BEARING, THRUST
- 701 RING, SPIRAL PIN RETAINING
- 702 CARRIER, DIFFERENTIAL & FINAL DRIVE
- 703 SHAFT, DIFFERENTIAL PINION
- 704 PIN, DIFFERENTIAL PINION SHAFT RETAINING
- 705 ROTOR, SPEED SENSOR
- 706 WASHER, THRUST (DIFFERENTIAL PINION)
- 707 GEAR, DIFFERENTIAL PINION
- 708 WASHER, THRUST (DIFFERENTIAL SIDE GEAR)
- 709 GEAR, DIFFERENTIAL SIDE
- 710 WASHER, PINION THRUST
- 711 GEAR, PINION (FINAL DRIVE PLANET)
- 712 ROLLER NEEDLE BEARING
- 713 SPACER, PINION NEEDLE BEARING
- 714 PIN, PLANET PINION




Figure 23




Figure 24