



Technical Service Information

THM 200-4R SECOND GEAR STARTS

COMPLAINT: No 2-1 coastdown shift in cold weather conditions, and then may exhibit normal operating conditions after warm.

CAUSE: The cause may be an incorrect 1-2 throttle valve spring (See Figure 1). This affects ONLY 1987-1988 models CCF, CHF, CRF, CTF, CYF, and CZF.

CORRECTION: Replace the 1-2 throttle valve spring, available under OEM part number 8643619. Refer to Figure 1 for proper assembly of valves and sleeves.




Figure 1