



Technical Service Information


THM 440-T4 NO TCC APPLY OR TCC SHUDDER

COMPLAINT: No TCC apply or TCC shudder

CAUSE: Some 1984 and some early 1985 THM 440-T4 transaxles may experience a no Torque Converter Clutch (TCC) apply or TCC shudder condition, which may be due to a cut or rolled TCC accumulator piston seal (See Figure 1).

CORRECTION: Install updated service package 8646926. Updated service package 8646926 contains the followings

- 1.1-TCC ACCUMULATOR PISTON
- 2.1-TCC ACCUMULATOR PISTON PIN
- 3.1-TCC ACCUMULATOR PISTON SEAL



Copyright © 2001 ATSG

Figure 1