



# Technical Service Information

## CHRYSLER A604 DELAYED FORWARD ENGAGEMENT

**COMPLAINT:** After overhaul vehicle exhibits delayed and/or a shuddering condition, when shift lever is engaged into any forward range, followed by an immediate abort to "Limp Mode."

**CAUSE:** The cause may be, that during the valve body cleaning process, retainer No.3 and/or one of the small "Buttons" in the solenoid switch valve train was not installed during reassembly. These parts can usually be found in the bottom of the solvent tank.

**CORRECTION:** Install the solenoid switch valve train and retainer No.3 as shown in Figure 1.

**NOTE:** Retainer location No. 4 and Torque Converter Clutch Switch Valve Train shown in Figure 1 are for '92 " and later only!




Figure 1