





# Technical Service Information

## NISSAN RL3F01A STANZA 3-2 DOWN SHIFT CLUNK

**COMPLAINT:** Stanza models exhibit a 3-2 down shift clunk.

**CORRECTION:** Install new Secondary Governor Spring, part # 31873-01X01



Governor valve spring chart

SPRING P/N	FREE LENGTH MM (IN)	WIRE DIA. MM (IN)	OUTER COIL DIA. MM (IN)
Former-31873-01X00	38.2 (1.504)	0.8 (0.031)	10.8 (0.425)
New -31873-01X01	41.0 (1.614)	0.8 (0.031)	10.8 (0.425)

Figure 1