



Technical Service Information

THM 3T40 (125C) RATTLE OR CLICKING NOISE

COMPLAINT: An intermittent rattle and/or clicking noise that is most evident in 3rd gear.

CAUSE: The noise may be caused by 'Grooved' lo-reverse lined clutch plates (See Figure 1).

CORRECTION: Install 'Smooth' lo-reverse lined clutch plates, available under OEM Part No. 8666667 the new clutch plates went into production May 5, 1989 (Julian Date 125).




Figure 1