



# Technical Service Information

## TOYOTA A240 HARSH 1-2 SHIFT (CLUTCH MATERIAL)

To reduce the shift shock levels on MR2's and Corolla's equipped with A240 automatic transaxles the following changes have been made,

1. Friction material of B2 disc has been changed.
2. The number and order of B2 disc and plates has been changed. (See illustration)
3. B2 Accumulator Piston Spring has been changed




Figure 1



## Technical Service Information

### PRODUCTION EFFECTIVE:

<u>FROM FRAME #</u>	<u>FROM TRANS. NO.</u>	<u>FROM PRODUCTION DATE</u>
JT2AW1##G0065249	6AZ-00972	JANUARY, 1986
JT2AE8#E#G3333682	6AZ-00972	JANUARY, 1986

### PART NUMBER INFORMATION:

<u>PREVIOUS PART #</u>	<u>Q'TY</u>	<u>NEW PART #</u>	<u>Q'TY</u>	<u>PART NAME</u>
35677-12010	3	*35677-20020	2	DISC, CLUTCH. (For 2nd Brake)
35648-32010	3	*SAME	4	PLATE, CLUTCH (For 2nd Brake)
90501-25011	1	*90501-26014	1	SPRING (B2 ACCUMULATOR PISTON)

\* PARTS ARE INTERCHANGEABLE AS A SET ONLY